72185 COUNTY ROAD 3 NAPPANEE, IN 46550


## NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007


TECHNICAL SERVICE BULLETIN							
DATE ISSUED MODE		ODEL YEAR(S) AFFECTED		Model(s) Affected		TSB#	
10/26/98	1997-1999			ALL		164	
Brand				Түре			
All   Americ	can Star 🛚	Kountry Star	Dut	ch Star 🛚	All 🗖 T	T 🗆 F W 🗖	
NewAire □ Mountain Aire ■ Kountry Aire ■			Lon	don Aire■	C A 🗖 D	P■ DB□	
☐ Air Conditioning &			☐ Electrical Components				
☐ Appliances & Accessories			☐ Exterior Components				
☐ Cabinets & Furniture				☐ Interior Components			
■ Chassis Components				☐ Plumbing & Bath Components			
☐ Construction Components				☐ Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Possible air intake tubes rubbing together.							
RECOMMENDED SOLUTION							
See the attached photos portion of engine comp clamp or a strong plum	oartment just b	behind the hinge for	the b	ed access. At	tach the hanger	to the elbow with a	

800.858.4924 Fax 219.773.2007

## NEWMAR CORPORATION WARRANTY DEPARTMENT



## NEWMAR CORPORATION WARRANTY DEPARTMENT



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.