TECHNICAL SERVICE BULLETIN					
DATE ISSUED	MODEL YEAR(S) AFFECTED			TSB #	
11/3/98	1998-1999	ALL		166	
BRAND			Түре		
All 🗖 American Star 🗖 Kountry Star 🗖		Dutch Star □ All □ TT□ FW ■			
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖		London Aire	C A 🗖 D	PD DBD	
□ Air Conditioning & Heating □ Electrical Components					
□ Appliances & Acc	Exterior Components				
Cabinets & Furniture		Interior Components			
□ Chassis Components		Plumbing & Bath Components			
Construction Con	□ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM					
RECOMMENDED SOLUTION					
During transit, set both into the cabinets.	recliners against each other, back-	to-back. This will	prevent the recl	iners from rocking	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.