

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
8/16/99	1999 & 2000	DIESEL PUSHERS	178				
BRAND		TYPE					
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input checked="" type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Headlights must be on low beam when the motorhome is shut off.							
RECOMMENDED SOLUTION							
See attached.							

NEWMAR CORPORATION

WARRANTY DEPARTMENT

Freightliner Diesel Pusher Motorhomes

Freightliner has discovered that if a unit is shut off with the headlights off and the high/low beam switch in the high beam position that it draws the batteries down. Over a period of 48 hours or so this will completely drain the chassis batteries. Currently there is no permanent solution to this problem, except to be sure that the headlights are on low beam when the unit is shut off.

Freightliner is working to try to figure out what is causing this problem. When Freightliner solves this issue you will be contacted and they will repair all the units in the field. Until then, it is important to double check the headlight switches to make sure they are always in the low beam position before the headlights are turned off.

If you have any questions, please contact a Newmar Warranty representative.

□