TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED		_	MODEL(S) AFFECTED		TSB #	
2/14/01	2/14/01 2001			DS DP		211	
BRAND					Түре		
All 🗖 Americ	an Star 🛛	Kountry Star 🛛	Dut	ch Star 🗖	All 🗖 T	$T \square F W \square$	
NewAire Mounta	ain Aire 🛛	Kountry Aire	Lon	don Aire□		DP■ DB□	
□ Air Conditioning & Heating □				Electrical Components			
Appliances & Accessories				Exterior Components			
□ Cabinets & Furniture				☐ Interior Components			
Chassis Components				Plumbing & Bath Components			
Construction Components				Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM Possible exterior lighting blackout on the Spartan chassis. (Headlights, marker lights, etc.)							
RECOMMENDED SOLUTION							
Check and secure the co	onnection as	shown in the attached	phc	to.			

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

