

72185 COUNTY ROAD 3  
NAPPANEE IN 46550

# NEWMAR CORPORATION

## WARRANTY DEPARTMENT

800.858.4924  
FAX. 219.773.2007

### TECHNICAL SERVICE BULLETIN

Date Issued  
08/31/01

Model Year(s) Affected  
2001-2002

Model(s) Affected  
NewAire

TSB #  
227

B r a n d				T y p e		
ALL <input type="radio"/>	American Star <input type="radio"/>	Kountry Star <input type="radio"/>	Dutch Star <input type="radio"/>	All <input type="radio"/>	TT <input type="radio"/>	FW <input type="radio"/>
	Mountain Aire <input type="radio"/>	Kountry Aire <input type="radio"/>	London Aire <input type="radio"/>	CA <input type="radio"/>	DP <input checked="" type="radio"/>	DB <input type="radio"/>

- ☐ Air Conditioning & Heating
- ☒ Appliances & Accessories
- ☐ Cabinets & Furniture
- ☐ Chassis Components
- ☐ Construction Components

- ☐ Electrical Components
- ☐ Exterior Components
- ☐ Interior Components
- ☐ Plumbing & Bath Components
- ☐ Windows, Awnings, Vents & Doors

#### Description of Problem

The power cord for the refrigerator may be routed incorrectly. This will pertain to units 40004-40025.

#### Recommended Solution

Remove the access cover on the top left corner of the refrigerator. Next, move the location of the power cord to the side of the refrigerator. By moving the cord this will prevent it from hanging over the coils at the rear of the opening.

Install a plastic wire cover over the cord, approximately 2' of plastic conduit. Cover the slide over the cord to assist with protection.

Please use the attached picture as a reference.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

