

72185 COUNTY ROAD 3
NAPPANEE IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX. 219.773.2007

TECHNICAL SERVICE BULLETIN

Date Issued
08/31/01

Model Year(s) Affected
2001-2002

Model(s) Affected
NewAire

TSB #
228

Brand				Type		
ALL <input type="radio"/>	American Star <input type="radio"/>	Kountry Star <input type="radio"/>	Dutch Star <input type="radio"/>	All <input type="radio"/>	TT <input type="radio"/>	FW <input type="radio"/>
	Mountain Aire <input type="radio"/>	Kountry Aire <input type="radio"/>	London Aire <input type="radio"/>	CA <input type="radio"/>	DP <input checked="" type="radio"/>	DB <input type="radio"/>

- | | |
|--------------------------------------------------|-------------------------------------------------------|
| <input type="radio"/> Air Conditioning & Heating | <input type="radio"/> Electrical Components |
| <input type="radio"/> Appliances & Accessories | <input type="radio"/> Exterior Components |
| <input type="radio"/> Cabinets & Furniture | <input checked="" type="radio"/> Interior Components |
| <input type="radio"/> Chassis Components | <input type="radio"/> Plumbing & Bath Components |
| <input type="radio"/> Construction Components | <input type="radio"/> Windows, Awnings, Vents & Doors |

Description of Problem

The interior fuel fill cover located on the passenger side under the sofa may not be properly sealed to the floor. This will pertain to units 40011-40025.

Recommended Solution

First, close off front end of opening area. Then fill the cavity from the rear with spray foam. Removal of the sofa kick panel or base may be required to gain access to this area. Please refer to the attached picture.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

TSB.09019

Newmar Corporation

TSB #228

Page 1

Front of Vehicle

Fill this cavity
with foam spray.

