72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED		Model(s) Affected			TSB#	
11/12/01	2001-2002	Class A Workhorse			S	233	
Brand				Түре			
All □ American Star □ Kountry Star ■		Dute	ch Star	All 🗖	ТТ	□ FW□	
NewAire □ Mountain Aire ■ Kountry Aire □			don Aire□	C A ■	D P	□ DB□	
☐ Air Conditioning of		☐ Electrical Components					
☐ Appliances & Accessories			☐ Exterior Components				
☐ Cabinets & Furniture			Interior Components				
☐ Chassis Components			☐ Plumbing & Bath Components				
☐ Construction Components			☐ Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM							
RECOMMENDED SOLUTION							
To correct this, relocate the instrument cluster. First, remove the wood grain cluster cover and remove the							
cluster. Next, drill hole the new holes as the mo	es on all four mounting tabs 1/4" abounting point. This will shift the cose use flat rate code #15420603, w	ove tl luster	ne current ho down appro	les. Re-asse ximately 1/4'	emble th ' allowin	ne cluster using	