

# NEWMAR CORPORATION

## WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #			
12/26/01	2001-2002	NewAire's Prior to #40034	235			
BRAND		TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>
NewAire <input checked="" type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input checked="" type="checkbox"/> Electrical Components		
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components		
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components		
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components		
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM						
Short flashes of the third brake light.						
RECOMMENDED SOLUTION						
Locate and install a relay, part number 44482, in the tail light harness third brake light circuit to prevent unpredictable short flashes. This relay can be found on the passenger side of the engine compartment below the chassis disconnect switch. (See the attached diagram). It has not been confirmed that all units experience this condition.						
When making this repair, please use flat rate code number 20914601 and allow .8 hour to complete.						

# NEWMAR CORPORATION WARRANTY DEPARTMENT

NewAire Third Brake Light modification per ECO 2002 #448

Locate relay on passenger side of engine compartment below chassis disconnect switch.

