

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
10/01/02	Current	All	243
BRAND		TYPE	
All <input checked="" type="checkbox"/> American Star <input type="checkbox"/> Kountry Star <input type="checkbox"/> Dutch Star <input type="checkbox"/>		All <input checked="" type="checkbox"/> T T <input type="checkbox"/> F W <input type="checkbox"/>	
Scottsdale <input type="checkbox"/> Mountain Aire <input type="checkbox"/> Kountry Aire <input type="checkbox"/> London Aire <input type="checkbox"/>		C A <input type="checkbox"/> D P <input type="checkbox"/> D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating			
<input type="checkbox"/> Appliances & Accessories			
<input type="checkbox"/> Cabinets & Furniture			
<input checked="" type="checkbox"/> Chassis Components			
<input type="checkbox"/> Construction Components			
<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM			
Road salt.			
RECOMMENDED SOLUTION			
With winter approaching, please power wash the chassis and undercarriage of each unit to remove road salt promptly upon receipt of new units.			

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.