

# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #			
8/29/89	ALL	ALL	25			
BRAND		TYPE				
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input checked="" type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components		
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components		
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components		
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components		
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM						
Difficulty reconnecting the chassis battery disconnect relay due to low chassis battery voltage.						
RECOMMENDED SOLUTION						
Have someone press the battery boost switch while you press the battery disconnect switch to the reconnect position. This will allow the chassis battery to be reconnected if the house battery has an ample charge. If the unit is not equipped with a battery boost switch it will be necessary to jump the chassis battery with cables from the house battery or another vehicle.						

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.