Technical Service Bulletin							
Date Issued		Model Year(s) Affected		Model(s) Affected		TSB #	
10/20/2006		11/2/03 - 5/13/06		Spartan K2 Chassis		283	
Brand						Туре	
All		American Star		Mountain Aire		All 🗖	ТТ 🗖
		Dutch Star		Kountry Aire		FW□	САП
		Kountry Star		Essex		D P 🗖	DB□
Sco	ttsdale 🛛	Northern Star		London Aire		D1 –	
□ Air Conditioning & Heating □ Electrical Components							
	Appliances & Accessories			Exterior Components			
	Cabinets & Furniture			Interior Components			
	Chassis Components				n Compo	onents	
	Construction Components				-		3
Description of Problem							
Spartan K2 Chassis with the Cummins ISM engine and a mechanical fan drive that have been manufactured within specified dates have a potential for engine overheating when operating under full power.							
Recommended Solution							
Replace crankshaft pulley and fan clutch assembly. See Manufacturers attached repair directions. Contact manufacturer directly for additional information or instructions.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.