

Newmar Corporation

Warranty Department

Technical Service Bulletin							
Date Issued		Model Year(s) Affected		Model(s) Affected		TSB #	
10/20/2006		2005		Spartan MM Chassis		289	
Brand						Type	
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	All	<input type="checkbox"/>
		Dutch Star	<input checked="" type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	F W	<input type="checkbox"/>
		Kountry Star	<input checked="" type="checkbox"/>	Essex	<input type="checkbox"/>	D P	<input checked="" type="checkbox"/>
Scottsdale	<input type="checkbox"/>	Northern Star	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	D B	<input type="checkbox"/>
<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> Air Conditioning & Heating <input type="checkbox"/> Appliances & Accessories <input type="checkbox"/> Cabinets & Furniture <input checked="" type="checkbox"/> Chassis Components <input type="checkbox"/> Construction Components </div> <div> <input type="checkbox"/> Electrical Components <input type="checkbox"/> Exterior Components <input type="checkbox"/> Interior Components <input type="checkbox"/> Plumbing & Bath Components <input type="checkbox"/> Windows, Awnings, Vents, & Doors </div> </div>							
Description of Problem							
<p>Subject: Instructions for replacing the fan motor for hydraulic fan drive system</p> <p>Applies To: Mountain Master with Spartan hydraulic fan drive</p>							
Recommended Solution							
<p>See Manufacturers attached repair directions. Contact manufacturer directly for additional information or instructions.</p>							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.