Technical Service Bulletin							
	Date Issued	Model Year(s) Affected		Model(s) Affected		TSB #	
10/20/2006		7/25/03 - 3/19/04		Spartan K2 Chassis		293	
Brand				Туре			ре
All	C	American Star	r 🗆	Mountain Aire	] A	.ll 🗖	ТТ 🗖
		Dutch Star		Kountry Aire	1 F	wΠ	САП
		Kountry Star		Essex	I   <sub>T</sub>	) P ■	DB
Sco	ttsdale C	Northern Star		London Aire	]	/1 —	00-
<ul> <li>Air Conditioning &amp; Heating</li> <li>Electrical Components</li> </ul>							
	Appliances & Accessories			Exterior Components			
	Cabinets & Furniture			□ Interior Components			
	Chassis Components			Plumbing & Bath Components			
	Construction Components			Windows, Awnings, Vents, & Doors			
Description of Problem							
occur. There is not enough clearance between components.							
Recommended Solution							
Reposition CAC hose. If component damage is found, contact Spartan Chassis, Inc. for further direction.							
See Manufacturers attached repair directions. Contact manufacturers directly for additional information or instruction.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.