TECHNICAL SERVICE BULLETIN								
DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED		<u> </u>	TSB #	
7/31/90	1989-1991			ALL			35	
Brand					Түре			
All Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All 🗖	Т Т 🗖	FW 🗖	
NewAire 🗖 Mount	ain Aire 🛛	Kountry Aire	Lon	don Aire 🗖	САП	D₽□	DB 🗖	
□ Air Conditioning & Heating □				Electrical C	omponents			
 Appliances & Accessories 				Exterior Components				
Cabinets & Furniture				☐ Interior Components				
□ Chassis Components				Plumbing & Bath Components				
Construction Components				Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Convection microwave ovens have exterior vents that may be latched in closed position when not in use. If								
RECOMMENDED SOLUTION								
Make sure customers ar extended periods of nor			vents	should be in	the lock positi	on only	during	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.