
TECHNICAL SERVICE BULLETIN					
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED		TSB #	
6/20/91	1991	ALL		41	
Brand			Түре		
All 🗖 Americ	can Star 🛛 Kountry Star 🗖	Dutch Star 🛛	All 🗖 T	T ■ FW ■	
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖		London Aire	C A 🗖 🛛 D	PD DBD	
■ Air Conditioning &	Electrical Components				
□ Appliances & Acce	Exterior Components				
Cabinets & Furnit	□ Interior Con	☐ Interior Components			
Chassis Componen	Plumbing & Bath Components				
□ Construction Components □ Wind			s, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM					
RECOMMENDED SOLUTION					
Add ¼ or 3/16 foam co	ore or plywood to bottom of duct.	Refer to the attac	ehed print.		

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT

72185 COUNTY ROAD 3

NAPPANEE, IN 46550



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.