TECHNICAL SERVICE BULLETIN											
DATE ISSUED		MODEL YEAR(S) AFFECTED			Model(s)	AFFECTE	D	TSB #			
5/11/92			1991-1992			A	LL	L		50	
Brand						Түре					
All	American Star Kountry Star					Dutch Star 🛛 All 🗖 TT 🗖 FW 🗖			FW 🗖		
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖						London Aire \blacksquare C A \blacksquare D P \square D B \square			DB 🗖		
	Air Condition	ning 8	& Heating		Electrical Components						
□ Appliances & Accessories						Exterior Components					
	Cabinets & Fr	ure	Interior Components								
	Chassis Components					Plumbing & Bath Components					
	Construction	Com	ponents		□ Windows, Awnings, Vents, & Doors						
	DESCRIPTION OF PROBLEM Slide out rooms being ran with the driver seat in the back position.										
RECOMMENDED SOLUTION											
Installing a label, warning the driver to put the seat in the forward position before running the slide out. Contact the warranty rep in your area for these tags: WARNING BE SURE THAT DRIVER'S SEAT IS IN THE FORWARD POSITION BEFORE ACTIVATING THE SLIDE OUT ROOM.											

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.