

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
5/19/92	1991-1992	ALL	54
BRAND		TYPE	
All <input checked="" type="checkbox"/> American Star <input type="checkbox"/> Kountry Star <input type="checkbox"/> Dutch Star <input type="checkbox"/>		All <input checked="" type="checkbox"/> T T <input type="checkbox"/> F W <input type="checkbox"/>	
NewAire <input type="checkbox"/> Mountain Aire <input type="checkbox"/> Kountry Aire <input type="checkbox"/> London Aire <input type="checkbox"/>		C A <input type="checkbox"/> D P <input type="checkbox"/> D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating			
<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories			
<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture			
<input checked="" type="checkbox"/> Interior Components			
<input type="checkbox"/> Chassis Components			
<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components			
<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM			
Free standing chairs coming apart at joints.			
RECOMMENDED SOLUTION			
Contact the Newmar Parts Department and replace the frames only. Back and seat cushions must be removed and bad frame sent back. Back and seat cushion will then have to be installed on new frames.			

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.