
TECHNICAL SERVICE BULLETIN								
DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
9/3/92	1993			ALL			63	
BRAND					Түре			
All 🗖 Americ	can Star 🛛	Kountry Star 🛛	Dut	ch Star 🛛	All 🗖 🕺	ГТ 🗖	FW 🗖	
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖			Lon	don Aire	$CA \blacksquare DP \blacksquare DB \square$			
□ Air Conditioning & Heating				Electrical Components				
□ Appliances & Accessories				Exterior Components				
□ Cabinets & Furniture				Interior Components				
Chassis Components				Plumbing & Bath Components				
Construction Components				Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM Daylight running lights and/or windshield wipers activate headlights. Whenever ignition or wipers are turned								
RECOMMENDED SOLUTION								
Enclosed is a wiring dia park high or low beam l		and windshield wip	oer set	up. Fog ligh	ts cannot be tu	rned on	unless the	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.