

# NEWMAR CORPORATION

## WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
10/8/92		1992-1993			ALL			64	
BRAND					TYPE				
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	All	<input type="checkbox"/>
NewAire	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	London Aire	<input type="checkbox"/>	C A	<input checked="" type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating					<input type="checkbox"/> Electrical Components				
<input type="checkbox"/> Appliances & Accessories					<input type="checkbox"/> Exterior Components				
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components				
<input type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components				
<input type="checkbox"/> Construction Components					<input checked="" type="checkbox"/> Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM									
Storage doors leaking into storage area. Door seal material used on the frame is made out of a sponge material that will let water go through into the storage area.									
RECOMMENDED SOLUTION									
Door seal sponge material must be changed to a rubber type material. This needs to be changed on the frame only, not the door. Contact the Newmar Parts Department for this seal.									

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.