


# NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #			
3/26/93	1992-1993	ALL	74			
BRAND		TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components		
<input type="checkbox"/> Appliances & Accessories				<input checked="" type="checkbox"/> Exterior Components		
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components		
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components		
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM						
Rubber steering shaft cover binding up on steering shaft.						
RECOMMENDED SOLUTION						
Check to see if the rubber cover has a clamp installed on it, per the attached picture. This will be under the vinyl cover. If this clamp is not on the cover, it must be installed. Newmar will pay .5 to add clamp. If you have any questions on this, contact your service representative.						

72185 COUNTY ROAD 3  
NAPPANEE, IN 46550

# NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924  
FAX 219.773.2007



□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.