
TECHNICAL SERVICE BULLETIN									
DATE ISSUED	MODEL YEAR(S) AFFECTED			Model(s)	AFFECTED		TSB #		
6/22/93	1	992-1993		ALL			78		
BRAND					Түре				
All 🛛 American Star 🗖 Kountry Star 🗖			Dut	Dutch Star ■ All □ TT□ FW□			FW 🗖		
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖			Lon	$CA \square DP \square DB \square$			DB 🗖		
□ Air Conditioning & Heating □ E					omponents				
□ Appliances & Accessories				Exterior Components					
□ Cabinets & Furniture				Interior Components					
Chassis Components				Plumbing & Bath Components					
Construction Components				□ Windows, Awnings, Vents, & Doors					
DESCRIPTION OF PROBLEM Water leaks on windshields.									
RECOMMENDED SOLUTION									
Seal windshield accordin Department. Please cos								's Parts	

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.