
TECHNICAL SERVICE BULLETIN						
DATE ISSUED	MODEL YEAR(S) AFFECTE	2	MODEL(S) AFFECTED		TSB #	
9/22/93	1992-1994		AI	L	85	
BRAND				Түре		
All 🛛 American Star 🗖 Kountry Star		Dut	tch Star ■ All □ TT■ FW■			
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖		Lon	don Aire□	C A D	D P D B D	
□ Air Conditioning & Heating			Electrical Components			
Appliances & Accessories			Exterior Components			
□ Cabinets & Furniture			Interior Components			
Chassis Components			Plumbing & Bath Components			
Construction Components			Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM						
	Recommend	- 5				
Add vent per attached print. This can cause cold air to come in unit by adding vent. This is not covered under						
	s a solution if your customer war					

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.