PRODUCT INFORMATION BULLETIN		
DATE ISSUED		PIB #
01/13/2011	ADDITIONAL WINTERIZATION STEPS FOR A RESIDENTIAL REFRIGERATOR	008
YEAR / BRAND / TYPE / MODEL#		
These additional steps must be performed when winterizing a unit with a residential refrigerator.		
PRODUCT INFORMATION		
 Please perform these <u>additional steps</u> after winterizing a coach that has a residential size refrigerator. Close off the valve on the water supply line to the refrigerator. Clean all excess antifreeze out of the icemaker area. Re-install the icemaker tray. Put a CLEAN absorbent towel in the chute on the inside of the refrigerator door (See Figure A). Put a CLEAN absorbent towel in the water dispensing area outside of the refrigerator door (See Figure B). 		

Figure A

Figure B

If you have any questions regarding this P.I.B., please contact a Warranty Service Representative at Newmar Corporation.