

72185 COUNTY RD 3  
NAPPANEE, IN 46550

**NEWMAR CORPORATION**

866.290.5371  
FAX 574.773.2007

## PRODUCT INFORMATION BULLETIN

DATE ISSUED

12/24/2012

PIB #

34

MAGNUM ENERGY  
ME-MR Remote staying in  
battery saver mode

YEAR / BRAND / TYPE / MODEL #

The intent of this Product Information Bulletin is to inform that Magnum Energy has issued a bulletin noting some ME-MR remotes have been identified to staying in the battery saver mode with the voltage below 12.6 VDC.

### PRODUCT INFORMATION

Please review the attached Product Bulletin from Magnum Energy. Identify revisions on inverter and remote. If the Inverter is v5.4 and remote is v0.8, contact Magnum Energy @ 425-353-8833.

**This bulletin affects these model 2010 Newmar Motor Homes;**

- Dutch Star DP
- Ventana DP
- Mountain Aire DP



## TECH BULLETIN

TECH BULLETIN NUMBER	120713
PCR	ME-MR Remote staying in Battery Save Mode
DATE	7/13/2012
SUBJECT	Inverter staying in Battery Saver Mode with battery voltage below 12.6 VDC
MODELS AFFECTED	ME-MR Remote
REPAIR PROCEDURE	Identify revisions on inverter and remote. If the inverter is v5.4 and remote is v0.8 contact Magnum Energy.
WARRANTY	Regular warranties apply

To identify if action need to be taken:

1. Press the Menu button until the screen reads "TECH Press ON".
  2. Press the ON Button till you see "Inverter Rev \*.\*" and make note of the inverter revision.
  3. Press ON once more you will see "Remote Rev \*.\*" make a note of the Remote revision.
- If you note less than "Inverter Rev 5.0" no action needed.
  - If you note "Inverter Rev 5.4" and "Remote Rev 1.0" no action need.
  - If it reads "Inverter Rev 5.4" and "Remote Rev 0.8" remote needs to be upgraded to Rev 1.0.

Magnum Energy Inc., 2211 West Casino Road, Everett, WA 98204  
P425-353-8833 F425-353-8390