72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 FAX 574.773.2007

Date Issued Model Year(s) Affected Ventana, Dutch Star, Recall 12V-552 TSB 401		-	TECHNICAL S	ER	VI	CE BULLE	TIN		
BRAND	DATE ISSUED		MODEL YEAR(S) AFFE	CTED		Model(s) Affe	CTED		TSB#
BRAND All American Star Mountain Aire, Essex Type All American Star Mountain Aire Bay Cypress Dutch Star Bay Mountain Aire Datch Cypress Dutch Star Bay Mountain Aire Datch Cypress Dutch Star Bay Mountain Aire Datch Construction Star Bay Star Datch All Star ME Ventana Bay Star Datch All Star ME Ventana Bay Star Datch Appliances & Accessories Exterior Components Cabinets & Furniture Interior Components Cabinets & Furniture Interior Components Construction Components Plumbing & Bath Components Construction Components Windows, Awnings, Vents, & Doors DESCRIPTION OF PROBLEM Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www. Daimler-TrucksNorthAmerica.com	02 /07 /2013		2010_2013			Ventana, Dutch	ı Star,	Re	
All American Star Mountain Aire All TT Cypress Dutch Star Kountry Aire Resex All TT CA Northern Star Kountry Star Essex All TT CA Northern Star Kountry Star Essex All Star ME Ventana Bay Star DP DP DB	02/07/2013					Mountain Aire,	Essex		TSB 401
Cypress			BRAND						TYPE
Northern Star	All		American Star			Mountain Aire	X	All 🗆	тт口
Northern Star	Cypress		Dutch Star	X		Kountry Aire		EW□	САП
All Star ME	Northern Star		Kountry Star			Essex			
□ Air Conditioning & Heating □ Electrical Components □ Appliances & Accessories □ Exterior Components □ Cabinets & Furniture □ Interior Components □ Chassis Components □ Plumbing & Bath Components □ Construction Components □ Windows, Awnings, Vents, & Doors □ DESCRIPTION OF PROBLEM Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com			_					D P 🗵	DRD
□ Appliances & Accessories □ Exterior Components □ Cabinets & Furniture □ Interior Components □ Chassis Components □ Plumbing & Bath Components □ Construction Components □ Windows, Awnings, Vents, & Doors □ DESCRIPTION OF PROBLEM Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	All Star ME		Ventana	X	В	ay Star			
□ Construction Components □ Windows, Awnings, Vents, & Doors □ DESCRIPTION OF PROBLEM Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com		_			_	-			
DESCRIPTION OF PROBLEM Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	☐ Cabinets & Fu	rnit	are			Interior Compone	ents		
Description of Problem Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	☑ Chassis Comp	one	nts			Plumbing & Bath	Compo	nents	
Daimler Truck North America LLC, on behalf of Freightliner Custom Chassis Corporation, is initiating Recall Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	☐ Construction (Com	ponents			Windows, Awning	gs, Vent	s, & Do	ors
Campaign FL634 for specific XB and XC chassis manufactured January 1 2010 through September 20, 2012. On these specific vehicles, the brake and cruise control diode jumpers may come loose over time resulting in an intermittent or continuous open circuit. Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com			DESCRIP	TION O	FP	ROBLEM			
Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is pressed, may result into an accident. RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	Campaign FL634	for	specific XB and XC chassi les, the brake and cruise co	s manuf ntrol die	facti ode	ired January 1 2010 jumpers may come l	through	Septem	ber 20, 2012.
RECOMMENDED SOLUTION (FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	Failum of the omi					•	n tha b	ralza mad	al is pressed
(FCCC NHTSA #12V-552) (NEWMAR NHTSA #12V-578) (CANADA NHTSA #2012425) NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	ranure of the cruis	se co	00 -		_		ше в	take ped	ar is pressed,
NEEDED CORRECTION: Potentially affected vehicles will be inspected to ensure the locking tabs of the diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com									
diode jumpers are fully engaged and locked in place. Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	(FCCC NHTSA #12V	-552) (NEWMA	R NHTS	SA #	12V-578)	(CAN.	ADA NH	TSA #2012425)
Please Note: Repairs will be performed at an authorized Daimler Trucks North America repair facility. To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com					s wi	ll be inspected to en	sure the	locking	tabs of the
To locate an authorized dealer, you can search online at www.Daimler-TrucksNorthAmerica.com	diode jumpers are fo	ılly	engaged and locked in place	e.					
Dealer and Customer notification will be completed by January 28, 2013.	1		-					-	icility.
		D	ealer and Customer notifica	ation wi	ll be	completed by Janua	ary 28, 2	2013.	

Daimler Trucks North America LLC

Daimler Trucks North America LLC P.O. Box 4090 Portland, OR 97208-4090 800.547.0712 Phone 503.745.9009 Fax

December 2012 FL634 NHTSA #12V-552 TC – No Number Assigned

Notice of Submission of Defect Information Report/Defect Information Notice Subject: FCCC X-Line Chassis Brake Signal Diode Jumpers

Daimler Trucks North America has determined that a safety related defect exists in certain chassis manufactured by Freightliner Custom Chassis Corporation and delivered to your company. As the incomplete vehicle manufacturer of these products, Daimler Trucks North America is unable to provide the National Highway Traffic Safety Administration and/or Transport Canada with the information necessary to fully describe the vehicles potentially containing this defect as required by Title 49 Code of Federal Regulations Part 573.6(c)(2) and/or Motor Vehicle Safety Regulations Section 15(1)(b). Your company may have an obligation to report this information.

The attached Defect Information Report and Defect Information Notice were filed with the appropriate government agencies. Please refer to these notices for details regarding the nature of the defect, the remedy, and the expected date when the remedy without charge will be available to owners. Daimler Trucks North America will be conducting this recall and filing the quarterly reports required by Title 49 CFR §573.7 and/or MVSR §15(3). Repairs will be performed by authorized Daimler Trucks North America repair facilities.

A preliminary list of potentially affected vehicles delivered to you is included.

This is the first letter in regard to this recall that you will receive. You will receive another notice when Daimler Trucks North America notifies its dealers and owners that a remedy without charge for this issue is available.

If you have questions regarding this notice, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com.

WARRANTY CAMPAIGNS DEPARTMENT Enclosure

DAIMLER

November 28, 2012

Daimler Trucks North America Nasser Zamani Senior Manager Compliance and Regulatory Affairs

Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue S.E.
Washington D.C. 20590

Re: Defect Information Report FL-634, Diode Jumpers

Ms. Lewis,

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith reports a safety campaign to recall approximately 7,596 Freightliner Custom Chassis XB and XC chassis manufactured January 1, 2010, through September 20, 2012, with brake and cruise control signal diode jumpers which may come loose over time resulting in an intermittent or continuous open circuit.

Attached is Daimler Trucks North America's Defect Information Report.

Please contact me if you have any questions.

Nossel Jamain

Sincerely yours,

Nasser Zamani

Cc: Amy Martin, Chief Counsel, CAL-OSHA

Enclosure

Certified Mail# 7003 2260 0001 3404 2396

Daimler Trucks North America LLC 4747 N. Channel Avenue Portland OR 97217-7699 503-745-6910 Phone 503-745-5544 Fax Nasser,Zamanl@Daimler.com

DAIMLER

Defect Information Report

(Section 573.6)

November 28, 2012

(c)(1) Manufacturer:

Daimler Trucks North America LLC

P.O. BOX 3849

Portland, Oregon 97208

(503) 745-5219

Brands:

Freightliner Custom Chassis

(c)(2) Vehicles identification:

Model(s) affected: XB and XC chassis **Model Years affected:** 2010 through 2013

Manufacture Dates: January 1, 2010, through September 20, 2012

Basis for determining population: XB and XC chassis build with 680 540 04 24 diode jumpers manufactured by Nexans Autoelectric of America, Inc. from the January 1, 2010,

changeover to Nexans through the September 20, 2012, containment action.

Component manufacturer if other than the vehicle manufacturer:

Nexans Autoelectric of America, Inc. 1000 Central Parkway North, Suite 225

San Antonio, Texas 78232 USA

Attn: Edeltraud Fabianke, President & CEO, 210.881.2607

(c)(3) Total number of vehicles potentially affected:

XR Chassis

Body Builder	US
CABLE CAR CLASSICS	1
CABLE CAR CONCEPTS	2
CAIO INDUSCAR	16
CHAMPION MOTOR COACH	49
CLASSIC TROLLEY	15
COACHMEN RV OF INDIANA	20
DOUBLE K, INC.	10
ELDORADO NATIONAL CO	1
GLAVAL BUS	18
MOLLY CORPORATION	5
STALLION BUS	10
SUPREME CORP.	33
Grand Total	180

XC Chassis

Body Builder	CANADA	US
COACHMEN RV OF INDIANA		294
ENTEGRA COACH	1 1	4
FARBER SPECIALTY VEHICLES, INC.	1 1	3
FLEETWOOD		1156
FOREST RIVER DIESEL DIVISION		451
FOUR WINDS	1	33
JAYCO INC.		144
NEWMAR	1	691
REXHALL	1	1
THOR MOTOR COACH	1	834
TIFFIN	1	2282
WINNEBAGO		1521
Grand Total	2	7414

(c)(4) Percentage of vehicles estimated to contain the defect: Unknown

DAIMLER

- (c)(5) Description of the defect: Excess heat shrink used to protect the diode on brake and cruise control signal diode jumpers may prevent the connector(s) from fully locking in place, potentially allowing the connector(s) to come loose over time resulting in an intermittent or continuous open circuit. Two separate circuits are potentially affected: one circuit disengages the cruise control with brake pedal activation, and the other circuit illuminates the brake lights with brake pedal application.
 - **49CFR Section 577.5(f) Evaluation of the risk to motor vehicle safety:** Failure of the cruise control to disengage, or of the brake lights to illuminate when the brake pedal is depressed may lead to a crash.
- (c)(6) Chronology of principal events: September 2012 loose brake diode connections were identified during the manufacturing process. DTNA conducted an analysis to identify the root cause and determine if this was an isolated or systemic issue. November 21, 2012 DTNA decided to conduct a voluntary safety campaign.
- (c)(7) Noncompliance-test or other data:
- (c)(8)
 (i) Remedial program: Potentially affected vehicles will be inspected to ensure the locking tabs on the diode jumpers are fully engaged and locked in place. Repairs will be performed by Daimler Trucks North America authorized service facilities.

 Reimbursement Plan: Copies will be submitted as a supplemental report when available.
 - (ii) Estimated Owner and Dealer Notification Date: Customer notification will be by first class mail using Daimler Trucks North America records to determine the customers affected. This will be completed approximately January 28, 2013

 Dealer and distributor notification will be completed approximately January 28, 2013
- (c)(9) Information for tire recalls: Not Applicable
- (c)(10) Communications sent to manufacturers, dealers and owners: Copies will be submitted as a supplemental report when available.
- (c)(11) Manufacturer's campaign number: FL-634

TYPE OP	DP	90 5	90 90 90 90	DP	90	DP	OD .	90 90	D do	DP	9 9	5 B	9 6	h 6	DP	DP	d d	DP	ОР	d 8	5 B	DP	9 g	5 6	DP	d 6	8	PP 6	d d	PP PP	DP CC	h 6	DP	8 6	5 B	DP	9 G	h 2	5 B	DP	д :	DP	90 90	5 음	DP
YEAR BRAND 2008 VT	2011	2011	2011 DS 2011 DS	2011	2011 DS	2011	2011	2011 DS	2011	2011	2011 DS	2011	2011	2011 05	2011	2011	2011 DS 2011 DS	2011	2011	2011 DS	2011	2011	2011 DS	2011	2011	2011 DS	2011	2011	2011 DS	2011	2011 DS	2011	2011	2011 DS	2011	2011	2011	2011 DS	2011	3 2011 DS	2011	2011	7 2011 DS		-
PRODNO 1 410552		604283	604337	604370	604409	604371	604377	604382	604340	604391	604275	604363	604379	604302	604407	604333	604401	604318	604301	604354			604366			604404			604308		604399	604372	_		604369			604411		604393			604387		
VINNUM 4UZAB2DT8BCAW7251	4UZFCHCY6BCA95973	4UZFCHCY3BCAV0120	4UZACHCY2BCAV0183 4UZFCHCY4BCAY1263	4UZACHCY8BCBA7627	4UZFCHCY8BCAY8796	4UZFCHCY4BCAY0615	4UZFCHCY8BCAY1279	4UZFCHCY6BCAY1281	4UZFCHCY2BCAY0614	4UZFCHCY9BCAY1288	4UZFCHCY3BCAV0294	4UZFCHCY5BCAY1272	4UZFCHCY9BCAY1257	4UZFCHCYXBCAV0129	4UZFCHCY8BCAY6787	4UZFCHCY4BCAV0143	4UZACHCY2BCBB1592 4UZFCHCY1BCAY1284	4UZFCHCY0BCAV0141	4UZFCHCY1BCAV0133	4UZFCHCY2BCAY1259	4UZACHCY0BCAV0179	4UZACHCY9BCAV0181	4UZACHCY4BCBA9200	4UZFCHCY2BCAV0139	4UZFCHCY6BCAY1264	4UZFCHCY6BCAY6786	4UZFCHCY4BCAW7248	4UZACHCY4BCAY1239	4UZFCHCY1BCAY1Z70 4UZFCHCY5BCAV013S	4UZFCHCY4BCAX9626	4UZFCHCY7BCAY1287	4UZFCHCYXBCAY8797	4UZACHCYXBCAV0299	4UZACHCY3BCAV0144	4UZFCHCY9BCAY1260	4UZACHCY4BCAV0184	4UZFCHCY1BCAY1253	4UZFCHCY1BCAY6/89	4UZACHCY2BCBA5582	4UZFCHCY0BCAY6783	4UZFCHCYXBCAY6788	4UZFCHCY0BCAV0138	4UZFCHCY3BCAY1285	4UZACHCY3BCAV0175	4UZFCHCY8BCAY1265

BRAND TYPE	DP	do 1	d 6	h 6	DP	DP	do 8	h 6	DP	DP	DP	do s	4 6	o do	DP	DP	d d	ď	DP	9 2	h h	DP	dG 1	d do	5 G	OP	g 6	2 6	5 B	OP	do s	2 6	6	90	a a	. d		8 8	_			4 6					4 6		_	
	_		201102			-	2011 DS	2011 DS	_	2011 DS	=	11 DS	201102		=	н .	2011 DS	_		2011 DS	2011 DS			2011 DS		_	2011 DS		-			2011 DS	_		2011 DS 2011 DS	_	-	11 MA		-		2011 MA		ā	2011 MA		ZUII MA			
IO YEAR																-																						965 201											ı m	
PRODNO	604349	604306	604408	604297	604388	604325	604364	604374	604312	604386	604384	604400	60435/	604304	604315	604383	604358	604394	604346	604398	604365	604331	604385	604368	604326	604338	604339	604322	604356	604324	604313	604380	604357	604274	604381	604373	903956	903965	903970	903973	904019	903978	903974	904018	904010	903997	904009	90401	86606	
VINNUM	4UZFCHCY1BCAY1267	4UZACHCY2BCAY1238	4UZFCHCYXBCAY1265	4UZFCHCY8BCAV0128	4UZFCHCYXBCAY1283	4UZFCHCY1BCAV0147	4UZFCHCY0BCAY1275	4UZFCHCY2BCAY1276	4UZFCHCYXBCAV0132	4UZFCHCY0BCAY1261	4UZFCHCY6BCAY1278	4UZACHCYXBCBA7628	4UZACHCY4BCBA5583	4UZACHCY6BCAV0185	4UZACHCY0BCAY1237	4UZFCHCY4BCAY1280	4UZACHCY0BCAY1268	4UZACHCY4BCBB1593	4UZFCHCY3BCAY1254	4UZFCHCY9BCBA5584	4UZFCHCY3BCAY1271	4UZACHCY5BCAV0145	4UZFCHCY0BCAY1258	4UZFCHCY8BCAX96Z8 4UZFCHCY9BCAY1274	4UZFCHCY7BCAV0136	4UZFCHCY3BCAV0148	4UZFCHCY5BCAV0149	4UZECHCY9BCAV0137	4UZACHCY0BCAY6776	4UZFCHCYXBCAV0146	4UZACHCY7BCAV0180	4UZFCHCY8BCAY1282	4UZACHCY2BCAY1241	4UZACHCY8BCAV0298	4UZACHCY6BCBA9Z01 4UZFCHCY7BCAY1273	4UZFCHCY7BCAY1256	4UZFCHCY5BCAV0300	4UZFCHCY1BCAV0231	4UZFCHCY3BCAW7256	4UZFCHCY6BCAV0242	4UZFCHCY7BCAY6795	4UZFCHCY8BCAV0257	4UZFCHCY8BCAV0243	4UZFCHCY0BCAY6797	4UZFCHCYXBCAY6791	4UZFCHCY0BCAY1079	4UZFCHCY1BCAY5/9Z	4UZFCHCY6BCBA5591	4UZFCHCY3BCAV0263	

w		
2011 MA 2011 M	2011 MA	
903976 903977 903977 903961 903988 90398 90398 90398	903999 904006 903988 903988 903988 903989 903968 903968 903968 903989 903980 903980 903980	903971 903973 904003 904017 903976 903976 903979 904002 410888 410893 410960 410960 410960 410960 410960 410960 410987 410987 410987 410987 410987 410987 410987 410987 410987 410987
VINNUM 4UZFCHCYBCAV0234 4UZFCHCYBCAV0256 4UZFCHCYBCAV0227 4UZFCHCYBCAV0237 4UZFCHCYBCAV0237 4UZFCHCYBCAV0237 4UZFCHCYBCAV0237 4UZFCHCYBCAV0237 4UZFCHCYBCAV0237	4UZFCHCYBCAY1083 4UZFCHCYBCAY1083 4UZFCHCYBCAY0258 4UZFCHCYBCAY1084 4UZFCHCYBCAY1080 4UZFCHCYBCAY1080 4UZFCHCYBCAY1080 4UZFCHCYBCAY1080 4UZFCHCYBCAY1080 4UZFCHCYBCAY1080 4UZFCHCYBCAY1089 4UZFCHCYBCAY1089 4UZFCHCYBCAY1089 4UZFCHCYBCAY1089 4UZFCHCYBCAY1085 4UZFCHCYBCAY1085 4UZFCHCYBCAY0223 4UZFCHCYBCAY0223 4UZFCHCYBCAY0234 4UZFCHCYBCAY0224 4UZFCHCYBCAY0225 4UZFCHCYBCAY0225 4UZFCHCYBCAY0223 4UZFCHCYBCAY0223 4UZFCHCYBCAY0223 4UZFCHCYBCAY0223 4UZFCHCYBCAY0223 4UZFCHCYBCAY0223	4UZECHCYBECANOLSS 4UZECHCYBECANOLSS 4UZECHCYBECANOLSS 4UZECHCYBECANOLSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHCYBECANOSS 4UZECHSSBECANOSS 4UZECHBSBECANOSS

ñ																																																				
Ē 2	9 8	5 2	5 2	6	g	DP	6	2	9 8	g 2	2 2	5 2	2 5	9	В	В	Db	6	6	9 6	7 9	Ы	占	Ы	g :	2 5	2 9	8	P	Б	9 8	5 8	2 4	Ы	2 2	5 6	В	Ы	8	2	8	8	ద	ద	9 6	5 6	2 2	8	Ы	6	2 2	6 6
>	2011 VI	2011		2011	2011	2011	2011 VT	2011 VT	2011			2011 VT		2011 VT	2011	2011 VT	2011	2011	2011	2011 VI	2011	2011	2011	2011	2011	2011 VT	2011	2011	2011	2011 VT	2011	2011 VI	2011	2011		2011	2011	2011	2011	2011 VI	2011	2011	2011	2011	2011 VT	2011	2011	2011	2011	2011	2011	2011 VT 2011 VT
PRODNO	410951	410039	410972	410882	410993	410873	410968	410994	410959	4108/1	41095/	410910	410885	410877	410939	410883	410929	410921	410851	410880	410904	410847	410891	410970	410865	410973	410954	410866	410950	410900	410872	410983	410938	410949	410868	410901	410957	410898	410824	410850	410905	410986	410892	410979	410894	410960	410981	410869	410988	410853	410992	410940
VINNUM	4UZABZDTSBCAV0410	4UZFCHBS4BCAV03Z0	4UZACHDI 9BCAVUS6Z	4UZAB2DT1BCAV0386	4UZACHDTXBCAV0399	4UZAB2DT1BCAV0369	4UZFCHBS8BCAV0336	4UZACHDT2BCAV0400	4UZAB2DT7BCAV0408	4UZFCHBS8BCAV0319	4UZFCHBS7BCAV0327	ALIZABZDI IBCAV0403	4UZECHRS2BCAV0433	4UZFCHBS7BCAV0313	4UZFCHBS5BCAV0326	4UZFCHBS0BCAV0329	4UZFCHB51BCAV0324	4UZACHDTXBCAV0354	4UZACHDT7BCAV0389	4UZFCHBS0BCAV033Z	4UZFCHBS8BCAV0322	4UZACHDT3BCAV0387	4UZACHDT0BCAV0394	4UZACHDT7BCAV0361	4UZFCHBS2BCAV0316	4UZACHDT0BCAV0363	4UZACHDT7BCAV0351	4UZACHDT8BCAV0370	4UZACHDT5BCAV0360	4UZFCHBS6BCAV0321	4UZFCHBSXBCAV0323	4UZACHDIXBCAV03/1	4UZFCHBS3BCAV0325	4UZAB2DT5BCAV0407	4UZACHDT48CAV0396	4UZACHDT3BCAV0355	4UZACHDT9BCAV0359	4UZABZDTXBCAV0368	4UZFCHBS1BCAV0307	4UZACHDISBCAV0388	4UZACHDT1BCAV0355	4UZAB2DTXBCBF5424	4UZFCHBS9BCAV0314	4UZFCHBS3BCAV0339	4UZFCHBS0BCAV0315	ALIZECHBSGBCAV0235	4UZECHBS1BCAV0333	4UZFCHBS5BCAV0312	4UZFCHBSXBCAV0340	4UZACHDT3BCAV0390	4UZACHDTZBCAV0395	4UZACHDT5BCAV0357 4UZFCHBS5BCAW7255

YEAR BRAND TYPE		DS	2012 DS DP	SO	DS	DS	2012 US DP	DS	SO	2012 DS DP	2012 DS DP	DS	DS	2012 DS DP	Sa	S DS	DS .	2012 DS DP	DS	DS	DS	SO	2012 DS DP	2 05	DS	DS	DS	2012 US UP	2 02	2012 DS DP	2012 DS DP	2012 DS DP	2 02	DS	DS	2012 DS DP	DS	DS	2012 DS DP	2 DS	2012 DS DP	DS	2 DS	SOZ	2012 US UP	2 DS	2012 DS DP	2012 DS DP	2 DS	2012 DS DP
PRODNO YEA	410990	604446	604463	604503	604447	604425	604449	604488	604431	604426	604461	604486	604465	604419	604499	604436	604457	604489	604458	604478	604444	604442	604502	604470	604471	604437	604428	604497	604421	604466	604420	604476	604481	604494	604451	604474	604454	604484	604480	604456	604460	604468	604414	604475	604491	604438	7 604412	604469	5 604487	604462
VINNUM	4UZFCHBS9BCBE7072	4UZFCHCYSCCBP7646	4UZFCHCYXCCBR8590	4UZFCHCYOCCBX3178	4UZACHCY4CCBL5334	4UZFCHCYSCCBMSS40	4UZFCHCY6CCBT6393	4UZFCHCYXCCBV6162	4UZFCHCY4CCBM7022	4UZFCHCYSCCBI9682	4UZFCHCY8CCBT6394	4UZFCHCY4CCBU3634	4UZFCHCYXCCBT6395	4UZFCHCYBCCBL5339	4UZFCHCY3CCBW9772	4UZFCHCY7CCBP3937	4UZFCHCY8CCBU7623	4UZFCHCY8CCBV8329	4UZFCHCY0CCBR4290	4UZFCHCYZCCBU1428	4UZFCHCY6CCBS6494	4UZFCHCY2CCBR4288	4UZFCHCYODCBY2822	4UZACHCY8CCBT8835	4UZFCHCYXCCBU7624	4UZFCHCY4CCBR4289	4UZFCHCY9CCBM5539	4UZFCHCYACCBW 1264	4UZFCHCY2CCBL5340	4UZACHCY1CCBT6392	4UZFCHCY8CCBL9683	4UZFCHCY3CCBU7626	4UZFCHCY4CCBU1429	4UZFCHCY4CCBV8330	4UZFCHCY2CCBR2136	4UZFCHCY1CCBU3465	4UZFCHCY4CCBR2137	4UZFCHCY8CCBV1512	4UZFCHCYSCCBV1516	4UZFCHCY3CCBR8589	4UZFCHCY8CCBS0308	4UZFCHCY3CCBV1515	4UZFCHCYZCCBL5337	4UZFCHCYZCCBU1431	4UZFCHCY8CCBV6161	4UZFCHCYXCCBP1907	4UZACHCY1CCBH3387	4UZACHCY6CCBT8834	4UZFCHCY6CCBU363	40ZFCHCYSCCB1346/

TYPE		0	0. (0	0	0. (n. (0	۵.	۵.	٥	٥.	n. c	. 0	. 0			٥	C	n 6		. 0	. 0	۵	•	۵	۵.	۵. ۵			٥.	۵	۰.	2. 0		۵	۵	۵.	2. 0	. 0.	. 0	۵	۵	۵.	۵. ۱				۵.
	_	D	g !	2 2	5 B	ద	9	9	2 2	5 2	5 2	5 B	ď	ద	å	6	9 5	5 8	6	D	ď	ద	占	9 2	2	5 8	6	В	В	ď	9 9	2 2	2 9	6	Ы	Б	PP 6	2 5	5 8	9	В	9	2 5	5 6	6	8	Ы	9 8	9 5	2 5	5 6	g	Б
BRAND		DS		2 2	-	_	DS		2 2		2 2		DS	DS	_		So	2 2	_	DS					2 2		_	_	_	_		Ψ ×		_	_	_		MA V	_	MA	_	_	MA MA		-	_	MA	_		M M		MA	MA
YEAR	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012	2012
PRODNO	ın	604434	604440	604498	604424	604496	604450	604453	604501	604430	604441	604432	604418	604473	604493	604482	604477	604397	604423	604413	604427	604429	604439	604459	604445	904016	904029	904044	904056	904068	904028	904082	904047	904048	904058	904053	904050	904042	904075	904074	904051	904060	904054	904025	904072	904062	904070	904037	904015	904078	904046	904057	904063
VINNUM	4UZFCHCY1CCBV6163	4UZFCHCY8CCBP1906	4UZFCHCY8CCBR2125	4UZFCHCYSCCBV1511	4UZFCHCY8CCBH3389	4UZFCHCY4CCBV1510	4UZFCHCY7CCBP7647	4UZFCHCY3CCB13466	4UZFCHCYOCCBU1430	ALIZECHCYTCCB01908	4UZACHCY9CCBN3859	4UZFCHCY6CCAY6790	4UZACHCY3CCBH3388	4UZACHCY3CCBV1508	4UZFCHCY6CCBU7622	4UZACHCYSCCBV1509	4UZFCHCYICCBV1514	4UZFCHCY8CCRA5593	4UZFCHCYXCCBL9684	4UZFCHCY9CCBL5335	4UZACHCY2CCBL5333	4UZFCHCY4CCBH3390	4UZFCHCYXCCBP6430	4UZFCHCYZCCBR4Z91	4UZFCHCY2CCBN9475	4UZFCHCY1CCAY1092	4UZFCHCY3CCBK8378	4UZFCHCY1CCBP1911	4UZFCHCY1CCBT6396	4UZFCHCY6CCBV8331	4UZFCHCY5CCBJ4644	ALIZECHOVICOBDEA31	4UZFCHCYQCCBP3942	4UZFCHCY6CCBR4293	4UZFCHCY3CCBT6397	4UZFCHCYXCCBT1794	4UZFCHCY6CCBR2138	ALIZECHCYSCCBP3941	4UZFCHCY9CCBU7629	4UZFCHCY5CCBV6165	4UZFCHCY8CCBT1793	4UZFCHCY1CCBU3638	ALIZECHCYACCB18398	4UZFCHCY6CCBA5589	4UZFCHCY7CCBV6166	4UZFCHCY6CCBT8838	4UZFCHCY7CCBV1517	4UZFCHCYXCCBN9479	4UZFCHCY1CCBA5595	4UZFCHCYSCCBU/630	4UZFCHCYSCCBP1913	4UZFCHCY7CCBT3468	4UZFCHCY4CCBU1432

TYPE	2 9	<u>В</u>	DP	do l	6 6	à à	ద	DP	DP	g 6	2 2	5 6	d d	PP	9 5	h 2	<u>6</u>	DP	90	2 5	5 6	<u>Б</u>	DP	DP	DP E	90	h h	Ы	PP	<u>a</u> 8	급 급	DP	90	5 6	Ы	<u>6</u>	5 6	DP	ద	9 5	2 2	5 6	5 B	PP	DP	DP	PP (9 9	à 2	5 6
YEAR BRAND		_	_	_		2012 MA 2012 MA	_	2012 MA	_		2012 MA 2017 MA		_	_		2012 MA	-	_		2012 MA	2012 IMA 2012 MA			-		2012 VL	2012 VL 2012 VL		-	2012 VL		_	2012 VL	-	-	2012 VL	-	-			2012 VL			2012 VL	2012 VL	-	2	2012 VL		
PRODNO Y			904079	904083	904055	904055	904095	904022	904024	904039	904040	904080	904030	904043	904035	904084	904077	904021	904027	904033	904097	904049	904038	410963	410944	411027	411062	411006	410931	410934	410946	410935	410956	411034	411068	410888	411002	410933	410978	410906	411038	410911	410966	411014	411005	411087	410955	410925	410913	410920
VINNUM	4UZFCHCY6CCBAS592	4UZFCHCY7CCBU7628	4UZFCHCY8CCBV8332	4UZFCHCY5CCBX5752	4UZFCHCY4CCBT8837	4UZFCHCY3CCBV6164	4UZFCHCY6DCBZ8670	4UZFCHCY6CCAZ2010	4UZFCHCY2CCBA5587	4UZFCHCY8CCBN9478	4UZECHCYRCCBN6838	4UZFCHCY9CCBV1518	4UZFCHCY9CCBM9980	4UZFCHCY5CCBP6433	4UZFCHCY4CCBN9476	4UZFCHCY2CCBA5590	4UZFCHCY0CCBV1519	4UZFCHCY0CCBA5586	4UZFCHCY1CCBK8377	4UZFCHCYXCCBN3861	4UZFCHCY6CCBN6837	4UZFCHCY3CCBP6432	4UZFCHCY6CCBN9477	4UZAB2DT6BCBE3142	4UZAB2DT9BCBE7041	4UZAB2DT9CCBH3379	40ZAB2DT7BCBE3120	4UZAB2DT1CCBH3375	4UZAB2DT6BCBC0007	4UZABZDISBCBE3116	4UZABZDT4BCBE3124	4UZABZDT0BCBE3119	4UZAB2DT9BCBE3118	4UZAB2DT2CCBP7651	4UZAB2DT2CCBS6490	4UZAB2DTXBCBB0418	4UZAB2DT3CCBE3133	4UZAB2DT4BCBE3141	4UZAB2DT8CCBE3130	4UZAB2DT2BCBC0005	4UZABZDISCCBK8588	4UZAB2DT6BCBE3125	4UZAB2DT8BCBE3143	4UZAB2DT7CCBH3378	4UZAB2DT1CCBJ4640	4UZAB2DT8CCB50306	4UZAB2DT8BCBC0011	4UZAB2DT0BCBE3122	4UZABZD13BCBESISS	4UZAB2DT6BCBE3139

TYPE	DP	90	5 G	D do	DP	90 90	5 G	DP	90	40	P G	DP	DP	DP	4 6	Ы	DP	OP .	40	DP -	DP	ОР	90	h 6	DP	DP	Ь	DP	4 d	<u>а</u>	DP	4 60 60	5 d	DP	do do	о В	DP	DP oc	5 B	DP	DP	DP DP	2 2	5 G	OG	DP	90 8	4 6	d d
YEAR BRAND	2012	2012		2012	2012	2012 VL	2012	2012	2012	2012 VL	2012	2012		2012	2012 VL	2012	, 2012 VL	2012	2012 VL	2012	2012	2012	5 2012 VL	2012	2012		2012	2012	2012 VL 3 2012 VL	2012	2012	2012 VL	2012	2012	7 2012 VL	2012	2012	2 2012 VL	2012		2012	2012	5 2012 VI	2012	2012		2012	7 2012 VI	
PRODNO			3 411084			5 410995 4 410908				4 410909			8 410942		6 410914 2 410969	_	7 411017		7 411032	_				3 411000					410932 6 410928			32 411030			7 410977			9 410962					5 411076					38 41104/	
VINNUM	4UZAB2DTXCCBC0013	4UZAB2DT6CCBE3126	40ZABZD14CCBS6491 4UZABZDT8CCBS6493	4UZABZDT3BCBC0000	4UZAB2DTXCCBE3131	4UZAB2DT5CCBJ0946	4UZAB2DT5CCBH3377	4UZAB2DT3CCBJ0945	4UZABZDTXCCBE3128	4UZABZDTOBCBCO004	4UZAB2DT7BCBE7040	4UZAB2DTXBCBC0009	4UZAB2DT4BCBE3138	4UZABZDT7CCBH3381	4UZABZDT0BCBE3136 4UZABZDT9CCBE7042	4UZAB2DT5CCBH3380	4UZAB2DT1CCBJ8297	4UZAB2DT5BCAZ8926	4UZABZDT3CCBJ4641	4UZABZDTXCCBH3360	4UZAB2DT7BCBE3117	4UZAB2DT8BCBC0008	4UZABZDT5BCBC0001	4UZABZDTOCCBE7043	4UZAB2DT1CCBH3361	4UZAB2DT6CCBR6090	4UZAB2DT3CCBN7652	4UZAB2DT9BCBE3121	4UZABZDT/BCBC0002 4UZABZDT4BCBC0006	4UZAB2DTXBCBC0012	4UZABZDT6BCBC0010	4UZAB2DT9CCBH3382	4UZAB2DT6CCBM7021	4UZAB2DTXCCBH3374	4UZAB2DT8CCBE3127	4UZAB2DTXCCBJ5737	4UZAB2DT4BCBE7044	4UZAB2DT1CCBE3129	4UZAB2DT2BCBE3137	4UZAB2DT3CCBR8587	4UZAB2DT6CCBS0305	4UZABZDTZCCBU3631	4UZABZUIBCCBLS306	4UZFCHBS6CCBL9680	4UZAB2DT8CCBL5307	4UZAB2DT6CCBV6155	4UZAB2DT6CCBV8326	4UZFCHBS0CCBM5538	4UZFCHBS9CCBM5537

TYPE	DP	DP	9 9	h 6	6	DP	DP	DP 2	90 80	h 6	DP	DP	DP	DP	DP	d d	6	DP	DP	dd od	90	6 6	DP	DP	DP GC	90	00	DP	DP	h 6	5 d	DP	90	2 0	Ъ	DP	90 80	5 6	DP	DP	DP PP	à à	DP -	DP	DP	9 9	5 B	DP	DP.	d d	ī
) YEAR BRAND		2012	88 2012 VI	2012	2012	2012	2012	2012	59 2012 VT	2012	2012	2012		2012	2012	33 2012 VT	2012	2012	2012	23 2012 VT	2012	2012	2012	2012	31 2012 VT	2012	2012	51 2012 VT	2012	50 2012 VI	2012	2012	12 2012 VT	2012	2012	2012	54 2012 VT	2013	2013	2013	2013	51 2013 DS	2013	2013	2013	15 2013 DS	2013	2013	2013	40 2013 DS 13 2013 DS	
PRODNO	385 411010		7515 411058			424 411055		4 .	620 411069							581 411083 1240 411088				328 411023			386 411009		411091			7617 411061		091 411046			329 411042		_		071 410964					183 604555		_		569 604515				7050 604540 529 604513	
VINNUM	4UZFCHBS4CCBH3385	4UZAB2DT4CCBW1239	4UZABZDIZCCBU7615	4UZFCHBS2CCBU1426	4UZAB2DT8CCBU7618	4UZAB2DT9CCBU1424	4UZAB2DT0DCBY2817	4UZABZDT0CCBU1425	4UZFCHBS6CCBU7620	4UZFCHBS3CCBL5330	4UZABZDTXCCBF5425	4UZFCHBS8CCBL5324	4UZFCHBS3CCBE7070	4UZFCHBS4CCBU3632	4UZAB2DT4CCBL5305	4UZFCHBS8CCBL9681	4UZFCHBS6CCBM9979	4UZFCHBSXCCBU7619	4UZAB2DT1CCBF5426	4UZFCHBS5CCBL5328	4UZAB2DT4CCBU7616	4UZFCHBS1CCBL5326	4UZFCHBS6CCBH3386	4UZAB2DT2CCBV1499	4UZAB2DT3CCBX3172	4UZAB2DT5CCBV1500	4UZAB2DT7CCBV1501	4UZAB2DT6CCBU761	4UZAB2DT4CCBV6154	4UZFCHBSBCCBU3B33	4UZFCHBSXCCBL9679	4UZFCHBS3CCBL5327	4UZFCHBS7CCBL5329	4UZFCHBS7CCBL5332	4UZFCHBS2CCBH3384	4UZABZDTXCCBL5308	4UZFCHBS5CCBE7071	4UZFCHCY1DCFD2390	4UZFCHCY5DCFD2389	4UZFCHCY6DCFD7052	4UZFCHCY2DCFD0471	4UZECHCYZDCFE2183	4UZFCHCY2DCFB0530	4UZFCHCY6DCBV6158	4UZFCHCY7DCFE2549	4UZFCHCYXDCBZ8669	4UZFCHCY8DCBZ8668	4UZFCHCYXDCFA6077	4UZFCHCY6DCFE1750	4UZFCHCY2DCFD7050	

BRAND	a DS DP	2 2	3 DS	S DS	0 0	SOS	S DS	3 DS	3 DS DP	a DS DP	13 DS DP	DS	3 DS	3 DS	DS	S DS	200	13 DS DP	DS	DS	13 DS DP	DS	DS	SO	DS	13 DS DP	DS C	DS	DS	13 DS DP	DS	DS	13 DS DP	50	DS	m	DS	DS	13 EX DP	MA	MA	13 MA DP	MA	MA	MA :	13 MA DP	Z Z	MA	13 MA DP	13 MA DP	MA	MA S	A MA	13 MA DP
_	604542 2013				604500 201				604539 2013	604546 2013	604514 201		_					604569 2013			604566 201					604519 2013				604524 2013			604531 2013			604516 201			801001 2013			904106 2013				904096 2013	904108 2013		904112 2013	904098 2013		-	_ ,	904076 2013
VINNUM	4UZFCHCY4DCFD7051	4UZFCHCYICCBW1Z65	4UZFCHCY1DCBX5751	4UZFCHCY4DCFD8507	4125CHC400CB24005	4UZECHCY4DCFB0528	4UZFCHCYSDCBZ4903	4UZFCHCY8DCFE1751	4UZFCHCY8DCFD4959	4UZFCHCY9DCFD8504	4UZFCHCY0DCFA7934	4UZFCHCY3DCFE0054	4UZFCHCYXDCFE0052	4UZFCHCYXDCFE1749	4UZFCHCY8DCFE1748	4UZFCHCY8DCFE5864	4UZFCHCYXDCFE5865	4UZFCHCYSDCFEZSS1	4UZFCHCY4DCFES862	4UZFCHCYXDCBW9771	4UZFCHCY9DCFE2553	4UZFCHCY3DCFE2550	4UZACHCY3DCBW1263	4UZFCHCY0DCFD0470	4UZFCHCY0DCFB0526	4UZFCHCYZDCFB05Z/	4UZACHCY1DCBV8328	4UZFCHCY7DCBZ2487	4UZFCHCY8DCBV6159	4UZFCHCY2DCFA7935	4UZFCHCY8DCFD4962	4UZFCHCY6DCFD4961	4UZFCHCY1DCFA6078	4UZFCHCYODCFD8505	4UZFCHCY7DCFD8503	4UZFCHCY1DCBZ5126	4UZFCHCY3DCFD2388	4UZFCHCY7DCFD2281	4UZFCTDV8DCBR5924	4UZFCHCY6DCBY2825	4UZFCHCY8DCFB6428	4UZFCHCY6DCFD8508	4UZFCHCY5DCBZ5128	4UZFCHCY4DCBY2824	4UZFCHCY6DCFA7937	4UZFCHCY3DCFB9303	417FCHCY8DCFD8509	4UZFCHCYXDCFD4963	4UZFCHCY1DCFE5866	4UZFCHCY1DCFB9302	4UZFCHCY9DCFD2282	4UZFCHCY6DCFB3396	4UZFCHCYXDCFB9301	4UZFCHCY/DCBX3180 4UZFCHCY0DCFE2554

TYPE	DP	DP	DP	DP	DP	DP	90	h 2	9 9	DP	g 6	2 0	DP	DP	DP	DP	DP	d 60	90	D ₀	DP	DP	DP	DP	DP	2 0	DP	DP	DP	DP	90	7 2	DP	DP	DP	Db	2 6	DP	DP	DP	DP	DP	90	- C	2 2	o do	DP	DP						
YEAR BRAND	2013 MA				2013	2013 MA	2013 MA		2013 1	2013	2013	2013 VL	m	2013 VL	-	m	2013 VL	. ~	_	m	m	-	m	2013 VL 2013 VI	-	-	m	_	-		2013 VT	2013 VT		_	m	-	2013 VT		m	2013 VT	-	2013 VT	2013 VI	m		-	-	m	2013 VT		2013 VT	m	2013 VT	2013 VT
PRODNO	904116	904114	904101	904088	904115	904081	904099	904091	904100	904103	904086	411105	411111	411118	411095	411113	411175	411101	411187	411078	411131	411174	411109	411115	411151	411114	411124	411140	411106	411146	411123	411145	411097	411096	411101	411094	411110	411134	411135	411093	411122	411107	411132	411102	411136	411152	411154	411125	411182	4110//	411141	411119	411164	411104
VINNUM	4UZFCHCY3DCFF0132	4UZFCHCY6DCFE7421	4UZFCHCY5DCFB9304	4UZFCHCY4DCFB0531	4UZFCHCY6DCFF2151	4UZFCHCY9DCBZ2488	4UZFCHCY4DCFA7936	4UZFCHCY3DCFD4965	4UZFCHCY1DCFD4964	4UZFCHCY8DCFD7053	4UZFCHCY5DCBX5753	4UZAB2DT0DCFA2195	4UZAB2DT9DCFD2277	4UZAB2DT9DCFB0523	4UZAB2DT8DCBT1646	4UZAB2DT2DCB56488	4UZABZDTXDCFE0047	4UZAB2D13DCRZ6713	4UZABZDT8DCFE5859	4UZAB2DT0DCBY4017	4UZAB2DT2DCFB3392	4UZAB2DT8DCFD7048	4UZABZDTZDCFA6099	4UZABZDIBDCFU7047	4UZAB2DT4DCBS6489	4UZAB2DT6DCBT6389	4UZAB2DT2DCFB0525	4UZFCHBSXDCFE0050	4UZFCHBS3DCBX3173	4UZAB2DT1DCFF0126	4UZFCHBSZDCFD2279	4UZFCHBSBDCFD4957	4UZFCHBS8CCBV8327	4UZFCHBS2DCBM5543	4UZFCHBS0DCBM5542	4UZAB2DT2DCBY2818	4UZABZDI7DCBZ9761	4UZAB2D10DCFD4938	4UZFCHBS6DCFE1745	4UZABZDT7DCBX5749	4UZAB2DT8DCBZ8666	4UZFCHBSZDCBY2821	4UZFCHBS6DCFE0049	4UZAB2DT1DCBZ6712	4UZAB2DT2DCFE1743	4UZFCHBSXDCFE1747	4UZFCHBS8DCFE1746	4UZFCHBSBDCFE0984	4UZFCHBS5DCFF0128	40ZFCHBSIDCBW9//0	4UZAB2DT1DCFB1603	4UZFCHBS7DCBZ2485	4UZAB2DT6DCFB3394	4UZAB2DTXDCBZ8667

VINNUM	PRODNO YEAR BRAND	YEAR	BRAND	TYPE
4UZFCHBSXDCFD7049	411120	2013	7	Ob
4UZFCH8S8DCFF2150	411166	2013	M	Ob
4UZFCH859DCFD8502	411128	2013	7	å Q
4UZFCHBS0DCBY2820	411112	2013	7	90
4UZFCHB53DCBX5750	411108	2013	5	20
AUZFCHBSXDCFF2148	411157	2013	5	g
4UZFCHBSXDCFD4958	411133	2013	5	g
4UZACHCY9DC8X3174				
4UZFCHCY0DCFA2197				
4UZ482DT1DCFE0048				
4UZFCHCY6DC826711				
4UZAB2D74DCFE5860				
4UZACHCY1DC8W1252				
4UZFCHCY4DCFB3395				
4UZFCHCY9BCAY6796				
4UZACHCYXBCAW7247				
4UZAB2016CC816388				
4UZAB2DT4CCST6387				
4UZAB2DT6DC8T1645				
4UZA82DT1CC8T1647				