

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	TSB #
3/24/2016	2016	449 rev. A

BRAND

Bay Star Sport	☐	Ventana	☒	Essex	☐
Bay Star	☐	Dutch Star	☒	King Aire	☐
Canyon Star	☐	Mountain Aire	☐	Other	☐
Ventana LE	☐	London Aire	☐		

DESCRIPTION

Newmar Corporation has decided a defect relating to motor vehicle safety exists in specific motor homes. In response to notification from Freightliner Custom Chassis Corporation, an incorrect front tire inflation level is shown on their provided 'Incomplete Vehicle Label.'

NHTSA# 16V 041, TC # 2016-034

Issue: Inflation of the tire beyond the manufacturer's maximum pressure rating may increase the risk of a crash, resulting in injury and/or damage to property.

Motor homes included in this recall include: 2016 Ventana (40' and 43' floorplans) and 2016 Dutch Star (37' and 40' floorplans) motorhomes built between 3/19/2015 and 1/21/2016.

RECOMMENDED ACTION

Correction: Freightliner will send Newmar a new label with the correct 120 PSI rating for the tires. Newmar will mail the correct label to the customer. Check the tire pressure to verify that the pressure does not exceed the maximum pressure rating as printed on the new label.

Repair Procedure:

Newmar Corporation will mail out labels with the correct tire rating to be installed by the customer. If you have any questions, please contact the Newmar Service Department at: 1-866-290-5371, and a Newmar associate will provide you with any assistance you may need.

Flat rate code: 16v 041

Labor Time: .3 hr.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

How to Install a New Chassis Information Label

Work instructions related to TSB 449 and TSB 450

1. Locate the label on the outside wall behind the driver's chair.



Original Incorrect Label

2. Clean the existing label with rubbing alcohol. If the edges are peeling, it may be easier to remove the label. If you are installing a new label over the top of the existing label, take care to align the new label directly over the old label so that it is covered completely.



Method #1: Removing the Original Label


3. Install a clear protective film over the new label.
4. Repeat the process for the label in the kitchen cabinet.



Method #2: Installing New Label over the Original Label




Protective Film




Original Label Installed

5. Locate the label in the kitchen cabinet. To install the new label, clean the existing label with rubbing alcohol. If the edges are peeling, it may be easier to carefully remove label. If you are installing a new label over the top of the existing label, take care to align the new label directly over the old label so that it is covered completely.




Old Label Removed



New Label Installed

6. Install clear protective film over the new label.



New Label with Clear Protective Film

7. Check the tire pressure to verify that the pressure does not exceed the maximum pressure rating as printed on the new label.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: February 29, 2016

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 16V 041

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle which is subject to a recall campaign of this type must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motor homes.

In response to notification from Freightliner Custom Chassis Corporation, an incorrect front tire inflation level is shown on the 'Incomplete vehicle label' provided by Freightliner Custom Chassis. The incomplete vehicle label provided by Freightliner for these specific motorhomes shows front tire max pressure as 130 psi while the front tire is only rated for max pressure of 120 psi. The tire pressure is correct on Newmar's 'final stage manufacturer label' on these same motorhomes which correctly shows a max of 120 psi for these tires. Inflation of tire past the manufactures maximum pressure rating could increase the risk of a crash causing injury and/or damage to property. Correction: Freightliner will send Newmar a new label with the correct 120 psi rating for the tires. Newmar will mail the correct label to the customer.

Motorhomes included in this recall include:

2016 Ventana 40/43 foot and **2016 Dutch Star** 37/40 foot motorhomes built between 3/19/2015 and 1/21/2016.

These motor homes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will mail out labels with the correct tire rating to be installed by customer. If you should have any questions please contact the Newmar service department at: **1-866-290-5371** and a Newmar associate will provide you with any assistance you may need.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: February 29, 2016

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: # 2016-034

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the Canada Motor Vehicle Safety Act. Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific Newmar recreational vehicles.

Each vehicle which is subject to a recall campaign of this type must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect which relates to motor vehicle safety exists in specific motor homes.

Certain Motorhomes may fail to comply with the requirements of Canada Motor Vehicle Safety Standard 120 - Tire Selection and Rims. The certification label may not contain the correct front axle tire pressure information. Incorrect tire pressure could lead to tire failure, resulting in loss of vehicle control increasing the risk of a crash causing injury and/or damage to property. Correction: Manufacturer will mail out revised labels indicating 120 PSI (827 kPa) maximum front axle tire inflation pressure.

These motor homes require immediate service. Continued use poses a potential safety hazard.

This recall applies to certain Newmar motorhomes built between 6/16/2015 and 11/17/2015.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

Newmar will mail out labels with the correct tire rating to be installed by customer. If you should have any questions please contact the Newmar service department at: **1-866-290-5371** and a Newmar associate will provide you with any assistance you may need.

If you should have any questions please contact the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation

VIN Number	Production	Model			Floor	Chassis		
	Number	Year	Brand	Type	Plan	Brand	Date In Production	Date Off Production
4UZFCHCY3GCGS4013	412016	2016	VT	DP	4041	FL	3/19/2015	3/30/2015
4UZFCHCY2GCGS4066	412017	2016	VT	DP	4322	FL	3/23/2015	3/31/2015
4UZFCHCY4GCHH5471	412062	2016	VT	DP	4041	FL	6/9/2015	6/18/2015
4UZFCHCY8GCHH5473	412063	2016	VT	DP	4369	FL	6/10/2015	6/19/2015
4UZFCHCYXGCHE0546	412067	2016	VT	DP	4041	FL	6/9/2015	6/18/2015
4UZFCHCY4GCHA3413	412068	2016	VT	DP	4369	FL	4/30/2015	5/8/2015
4UZFCHCY0GCHJ1223	412092	2016	VT	DP	4037	FL	6/18/2015	7/6/2015
4UZFCHCY2GCHJ1224	412096	2016	VT	DP	4322	FL	6/22/2015	7/8/2015
4UZFCHCY4GCHJ1225	412097	2016	VT	DP	4369	FL	7/9/2015	7/17/2015
4UZFCHCY3GCHK7464	412100	2016	VT	DP	4041	FL	8/12/2015	8/20/2015
4UZFCHCYXGCHK9860	412101	2016	VT	DP	4002	FL	8/14/2015	8/24/2015
4UZFCHCY9GCHK7467	412102	2016	VT	DP	4369	FL	7/27/2015	8/4/2015
4UZFCHCY9GCHJ1222	412107	2016	VT	DP	4037	FL	6/17/2015	7/6/2015
4UZFCHCY5GCHJ1976	412120	2016	VT	DP	4037	FL	7/7/2015	7/15/2015
4UZFCHCY0GCHJ1979	412127	2016	VT	DP	4369	FL	7/29/2015	8/6/2015
4UZFCHCY4GCHP1943	412128	2016	VT	DP	4381	FL	10/12/2015	10/20/2015
4UZFCHCY9GCHJ8252	412129	2016	VT	DP	4369	FL	8/10/2015	8/18/2015
4UZFCHCY5GCHJ8247	412130	2016	VT	DP	4037	FL	6/24/2015	7/10/2015
4UZFCHCY1GCHJ1974	412136	2016	VT	DP	4041	FL	6/24/2015	7/13/2015
4UZFCHCY2GCHH5470	412138	2016	VT	DP	4041	FL	6/12/2015	6/22/2015
4UZFCHCY7GCHJ1977	412143	2016	VT	DP	4369	FL	7/15/2015	7/23/2015
4UZFCHCY6GCHJ1226	412144	2016	VT	DP	4369	FL	7/7/2015	7/16/2015
4UZFCHCYXGCHP3633	412145	2016	VT	DP	4316	FL	10/28/2015	11/5/2015
4UZFCHCY1GCHS7219	412146	2016	VT	DP	4316	FL	1/4/2016	1/13/2016
4UZFCHCYXGCHK9857	412150	2016	VT	DP	4002	FL	7/21/2015	7/29/2015
4UZFCHCY5GCHM2631	412156	2016	VT	DP	4037	FL	10/1/2015	10/8/2015
4UZFCHCY7GCHN1640	412157	2016	VT	DP	4037	FL	10/20/2015	10/28/2015
4UZFCHCY2GCHP1942	412158	2016	VT	DP	4041	FL	11/17/2015	11/24/2015
4UZFCHCY0GCHN1639	412159	2016	VT	DP	4041	FL	10/14/2015	10/22/2015
4UZFCHCY4GCHP7631	412160	2016	VT	DP	4311	FL	10/15/2015	10/23/2015
4UZFCHCY5GCHB0905	412163	2016	VT	DP	4041	FL	8/27/2015	9/3/2015
4UZFCHCY5GCHJ8250	412164	2016	VT	DP	4322	FL	7/29/2015	8/7/2015
4UZFCHCY2GCHL5409	412167	2016	VT	DP	4037	FL	9/4/2015	9/15/2015
4UZFCHCY0GCHK4893	412169	2016	VT	DP	4041	FL	7/30/2015	8/7/2015
4UZFCHCY3GCHK2071	412170	2016	VT	DP	4041	FL	7/30/2015	8/7/2015
4UZFCHCY7GCHK4891	412173	2016	VT	DP	4002	FL	7/30/2015	8/10/2015
4UZFCHCY3GCHL7461	412177	2016	VT	DP	4037	FL	8/25/2015	9/2/2015
4UZFCHCY4GCHK4895	412178	2016	VT	DP	4369	FL	8/13/2015	8/21/2015
4UZFCHCY4GCHN5127	412179	2016	VT	DP	4322	FL	9/23/2015	10/1/2015
4UZFCHCY6GCHK4896	412180	2016	VT	DP	4369	FL	8/17/2015	8/25/2015
4UZFCHCY1GCHS4806	412181	2016	VT	DP	4369	FL	1/12/2016	1/20/2016
4UZFCHCY4GCHN7069	412182	2016	VT	DP	4002	FL	9/24/2015	10/2/2015
4UZFCHCYXGCHP7620	412189	2016	VT	DP	4041	FL	12/1/2015	12/9/2015
4UZFCHCY3GCHM0246	412197	2016	VT	DP	4002	FL	9/21/2015	9/29/2015
4UZFCHCY6GCHS4803	412199	2016	VT	DP	4369	FL	12/11/2015	1/5/2016
4UZFCHCY0GCHP1941	412203	2016	VT	DP	4037	FL	11/10/2015	11/18/2015
4UZFCHCYXGCHP5706	412204	2016	VT	DP	4002	FL	12/1/2015	12/9/2015
4UZFCHCY6GCHN5131	412205	2016	VT	DP	4369	FL	10/15/2015	10/23/2015
4UZFCHCY8GCHN5129	412208	2016	VT	DP	4316	FL	10/2/2015	10/12/2015

4UZFCHCY7GCHK2073	412209	2016	VT	DP	4037	FL	7/17/2015	7/27/2015
4UZFCHCY3GCHK9859	412210	2016	VT	DP	4041	FL	8/13/2015	8/21/2015
4UZFCHCY1GCHM0245	412211	2016	VT	DP	4037	FL	8/13/2015	8/21/2015
4UZFCHCY4GCHN1644	412212	2016	VT	DP	4316	FL	9/22/2015	9/30/2015
4UZFCHCY1GCHP1947	412216	2016	VT	DP	4369	FL	10/22/2015	10/30/2015
4UZFCHCY5GCHP7623	412217	2016	VT	DP	4041	FL	10/22/2015	10/30/2015
4UZFCHCY5GCHM8347	412218	2016	VT	DP	4369	FL	9/8/2015	9/16/2015
4UZFCHCY7GCHM2632	412219	2016	VT	DP	4037	FL	10/1/2015	10/9/2015
4UZFCHCY9GCHT9554	412220	2016	VT	DP	4037	FL	1/5/2016	1/13/2016
4UZFCHCY6GCHR6388	412221	2016	VT	DP	4369	FL	12/9/2015	12/17/2015
4UZFCHCYXGCHS4805	412222	2016	VT	DP	4369	FL	12/11/2015	1/5/2016
4UZFCHCY3GCHP7622	412223	2016	VT	DP	4037	FL	12/14/2015	1/7/2016
4UZFCHCY2GCHK4894	412227	2016	VT	DP	4002	FL	8/12/2015	8/20/2015
4UZFCHCY0GCHK7468	412231	2016	VT	DP	4369	FL	8/17/2015	8/25/2015
4UZFCHCY7GCHJ8248	412232	2016	VT	DP	4037	FL	7/14/2015	7/22/2015
4UZFCHCY7GCHK7466	412233	2016	VT	DP	4037	FL	8/6/2015	8/14/2015
4UZFCHCY7GCHL7463	412234	2016	VT	DP	4041	FL	9/17/2015	9/25/2015
4UZFCHCY0GCHK2075	412238	2016	VT	DP	4369	FL	8/6/2015	8/14/2015
4UZFCHCY1GCHK9858	412240	2016	VT	DP	4037	FL	8/14/2015	8/24/2015
4UZFCHCY8GCHN1646	412241	2016	VT	DP	4316	FL	9/23/2015	10/1/2015
4UZFCHCY9GCHK2074	412242	2016	VT	DP	4322	FL	8/7/2015	8/17/2015
4UZFCHCY9GCHJ8249	412245	2016	VT	DP	4037	FL	7/23/2015	7/31/2015
4UZFCHCY3GCHK9862	412246	2016	VT	DP	4369	FL	8/27/2015	9/4/2015
4UZFCHCY1GCHK2070	412250	2016	VT	DP	4041	FL	7/24/2015	8/4/2015
4UZFCHCY0GCHL5408	412252	2016	VT	DP	4037	FL	8/19/2015	8/27/2015
4UZFCHCY1GCHK9861	412254	2016	VT	DP	4369	FL	9/1/2015	9/9/2015
4UZFCHCY9GCHL5410	412255	2016	VT	DP	4369	FL	8/26/2015	9/3/2015
4UZFCHCY9GCHN5124	412256	2016	VT	DP	4002	FL	9/8/2015	9/16/2015
4UZFCHCY8GCHS7217	412261	2016	VT	DP	4369	FL	11/17/2015	11/25/2015
4UZFCHCY9GCHL5407	412262	2016	VT	DP	4002	FL	8/24/2015	9/1/2015
4UZFCHCY5GCHL7462	412263	2016	VT	DP	4037	FL	8/25/2015	9/2/2015
4UZFCHCY4GCHN5130	412264	2016	VT	DP	4381	FL	10/6/2015	10/14/2015
4UZFCHCY9GCHK4892	412266	2016	VT	DP	4037	FL	7/24/2015	8/3/2015
4UZFCHCY1GCHM8345	412267	2016	VT	DP	4369	FL	8/21/2015	8/31/2015
4UZFCHCY2GCHK7469	412271	2016	VT	DP	4369	FL	8/28/2015	9/8/2015
4UZFCHCY0GCHL7465	412272	2016	VT	DP	4369	FL	8/28/2015	9/8/2015
4UZFCHCY7GCHJ8251	412273	2016	VT	DP	4369	FL	7/28/2015	8/5/2015
4UZFCHCY9GCHM0249	412274	2016	VT	DP	4322	FL	7/31/2015	8/11/2015
4UZFCHCY5GCHK7465	412275	2016	VT	DP	4041	FL	7/31/2015	8/10/2015
4UZFCHCY5GCHK2072	412280	2016	VT	DP	4002	FL	8/3/2015	8/12/2015
4UZFCHCY7GCHH5478	412281	2016	VT	DP	4311	FL	9/25/2015	10/5/2015
4UZFCHCY2GCHL7466	412282	2016	VT	DP	4369	FL	9/3/2015	9/14/2015
4UZFCHCY6GCHN5128	412289	2016	VT	DP	4369	FL	9/18/2015	9/28/2015
4UZFCHCY5GCHM0247	412290	2016	VT	DP	4002	FL	9/24/2015	10/2/2015
4UZFCHCY4GCHP9797	412291	2016	VT	DP	4311	FL	12/3/2015	12/11/2015
4UZFCHCY3GCHM8346	412292	2016	VT	DP	4369	FL	9/9/2015	9/17/2015
4UZFCHCY6GCHN1645	412294	2016	VT	DP	4322	FL	9/25/2015	10/5/2015
4UZFCHCY7GCHM0248	412296	2016	VT	DP	4041	FL	9/25/2015	10/5/2015
4UZFCHCY9GCHL7464	412302	2016	VT	DP	4037	FL	9/10/2015	9/18/2015
4UZFCHCY5GCHM0250	412303	2016	VT	DP	4369	FL	9/2/2015	9/11/2015
4UZFCHCY0GCHP7626	412310	2016	VT	DP	4316	FL	11/10/2015	11/18/2015

4UZFCHCY0GCHM2634	412311	2016	VT	DP	4369	FL	9/10/2015	9/18/2015
4UZFCHCY4GCHM6699	412312	2016	VT	DP	4369	FL	9/4/2015	9/15/2015
4UZFCHCY6GCHL5414	412318	2016	VT	DP	4311	FL	9/29/2015	10/7/2015
4UZFCHCY2GCHM2635	412319	2016	VT	DP	4369	FL	9/4/2015	9/15/2015
4UZFCHCY0GCHN1642	412320	2016	VT	DP	4369	FL	9/21/2015	9/29/2015
4UZFCHCY2GCHN1643	412322	2016	VT	DP	4369	FL	9/30/2015	10/8/2015
4UZFCHCY9GCHM2633	412329	2016	VT	DP	4037	FL	10/7/2015	10/15/2015
4UZFCHCY2GCHP7630	412333	2016	VT	DP	4369	FL	12/3/2015	12/11/2015
4UZFCHCY1GCHP5707	412334	2016	VT	DP	4002	FL	12/14/2015	1/7/2016
4UZFCHCY0GCHN5125	412336	2016	VT	DP	4002	FL	10/23/2015	11/2/2015
4UZFCHCY8GCHP1945	412338	2016	VT	DP	4369	FL	10/16/2015	10/26/2015
4UZFCHCY6GCHP1944	412339	2016	VT	DP	4369	FL	10/13/2015	10/20/2015
4UZFCHCYXGCHP1946	412340	2016	VT	DP	4316	FL	10/19/2015	10/27/2015
4UZFCHCY6GCHP3631	412341	2016	VT	DP	4369	FL	10/23/2015	11/2/2015
4UZFCHCY7GCHN5123	412344	2016	VT	DP	4037	FL	10/26/2015	11/3/2015
4UZFCHCY4GCHT5606	412345	2016	VT	DP	4037	FL	12/4/2015	12/11/2015
4UZFCHCY4GCHS7215	412346	2016	VT	DP	4037	FL	12/17/2015	1/12/2016
4UZFCHCY4GCHS4802	412347	2016	VT	DP	4369	FL	12/10/2015	1/4/2016
4UZFCHCY4GCHP7628	412350	2016	VT	DP	4369	FL	11/11/2015	11/19/2015
4UZFCHCY0GCHP9795	412352	2016	VT	DP	4322	FL	12/4/2015	12/14/2015
4UZFCHCY9GCHN1641	412353	2016	VT	DP	4037	FL	10/28/2015	11/5/2015
4UZFCHCY3GCHP1948	412355	2016	VT	DP	4369	FL	10/30/2015	11/6/2015
4UZFCHCY7GCHP7624	412356	2016	VT	DP	4369	FL	10/30/2015	11/9/2015
4UZFCHCY8GCHP5705	412357	2016	VT	DP	4037	FL	12/2/2015	12/9/2015
4UZFCHCYXGCHS7218	412382	2016	VT	DP	4369	FL	1/7/2016	1/15/2016
4UZFCHCY2GCHN5126	412385	2016	VT	DP	4037	FL	11/3/2015	11/11/2015
4UZFCHCY0GCHN7070	412386	2016	VT	DP	4041	FL	11/4/2015	11/12/2015
4UZFCHCY8GCHP3629	412387	2016	VT	DP	4002	FL	11/4/2015	11/12/2015
4UZFCHCY8GCHP3632	412388	2016	VT	DP	4316	FL	11/5/2015	11/13/2015
4UZFCHCY1GCHP3634	412392	2016	VT	DP	4369	FL	11/5/2015	11/13/2015
4UZFCHCY2GCHP7627	412393	2016	VT	DP	4369	FL	11/6/2015	11/13/2015
4UZFCHCY6GCHP7629	412421	2016	VT	DP	4369	FL	11/12/2015	11/19/2015
4UZFCHCY9GCHP7625	412422	2016	VT	DP	4369	FL	11/12/2015	11/20/2015
4UZFCHCY3GCHS4807	412431	2016	VT	DP	4369	FL	12/17/2015	1/12/2016
4UZFCHCY8GCHT5608	412433	2016	VT	DP	4369	FL	12/7/2015	12/15/2015
4UZFCHCY6GCHT5607	412436	2016	VT	DP	4037	FL	1/13/2016	1/21/2016
4UZFCHCY6GCHS7216	412438	2016	VT	DP	4037	FL	1/8/2016	1/15/2016
4UZFCHCY2GCHS4801	412443	2016	VT	DP	4037	FL	12/16/2015	1/11/2016
4UZFCHCY4GCHP3630	412444	2016	VT	DP	4037	FL	11/18/2015	11/30/2015
4UZFCHCY6GCHP5704	412445	2016	VT	DP	4037	FL	11/20/2015	12/1/2015
4UZFCHCY0GCHS7213	412448	2016	VT	DP	4037	FL	12/17/2015	1/11/2016
4UZFCHCY8GCHS4804	412451	2016	VT	DP	4369	FL	11/20/2015	12/2/2015
4UZFCHCY9GCHT2457	412454	2016	VT	DP	4037	FL	1/11/2016	1/18/2016
4UZFCHCY8GCHS7220	412460	2016	VT	DP	4369	FL	1/15/2016	1/22/2016
4UZFCHCY2GCHT5605	412464	2016	VT	DP	4037	FL	1/15/2016	1/22/2016
4UZFCHCY2GCHP9796	412470	2016	VT	DP	4369	FL	12/17/2015	1/11/2016
4UZFCHCY2GCHS7214	412474	2016	VT	DP	4037	FL	12/15/2015	1/8/2016
4UZFCHCY1GCHP7621	412487	2016	VT	DP	4037	FL	12/15/2015	1/8/2016
4UZACHCY3GCGS4068	605455	2016	DS	DP	3726	FL	3/23/2015	3/31/2015
4UZFCHCY4GCGS4067	605470	2016	DS	DP	4018	FL	3/24/2015	4/1/2015
4UZFCHCY5GCHH5480	605498	2016	DS	DP	4018	FL	6/10/2015	6/19/2015

4UZFCHCY7GCHH5481	605530	2016	DS	DP	4018	FL	6/15/2015	6/24/2015
4UZFCHCY8GCHJ1230	605541	2016	DS	DP	4018	FL	6/16/2015	6/24/2015
4UZFCHCY8GCHL7472	605543	2016	DS	DP	4018	FL	8/17/2015	8/24/2015
4UZFCHCY2GCHM0254	605545	2016	DS	DP	4018	FL	8/24/2015	9/1/2015
4UZFCHCY2GCHJ1983	605548	2016	DS	DP	4018	FL	6/23/2015	7/10/2015
4UZFCHCY2GCHK2109	605550	2016	DS	DP	4018	FL	6/25/2015	7/14/2015
4UZFCHCY5GCHL5419	605551	2016	DS	DP	4041	FL	8/17/2015	8/25/2015
4UZFCHCY7GCHK9864	605556	2016	DS	DP	4018	FL	7/28/2015	8/5/2015
4UZFCHCY6GCHL7471	605557	2016	DS	DP	4018	FL	8/11/2015	8/19/2015
4UZACHCY7GCHJ1228	605563	2016	DS	DP	3736	FL	6/17/2015	7/6/2015
4UZACHCY6GCHH5479	605564	2016	DS	DP	3736	FL	6/18/2015	7/6/2015
4UZFCHCYXGCHJ1231	605565	2016	DS	DP	4018	FL	6/24/2015	7/10/2015
4UZFCHCY3GCHL5421	605566	2016	DS	DP	4018	FL	7/17/2015	7/27/2015
4UZFCHCY4GCHJ8255	605567	2016	DS	DP	4018	FL	7/10/2015	7/20/2015
4UZFCHCY0GCHJ1982	605568	2016	DS	DP	4018	FL	6/24/2015	7/13/2015
4UZACHCY6GCHJ1981	605576	2016	DS	DP	3736	FL	7/9/2015	7/17/2015
4UZFCHCY1GCHJ1232	605577	2016	DS	DP	4018	FL	6/25/2015	7/13/2015
4UZFCHCY9GCHK2107	605580	2016	DS	DP	4018	FL	7/9/2015	7/20/2015
4UZFCHCY0GCHK7471	605581	2016	DS	DP	4018	FL	7/21/2015	7/29/2015
4UZFCHCY0GCHK2108	605583	2016	DS	DP	4018	FL	7/10/2015	7/20/2015
4UZFCHCY9GCHT5617	605584	2016	DS	DP	4002	FL	1/12/2016	1/20/2016
4UZFCHCY9GCHR6398	605585	2016	DS	DP	4002	FL	11/23/2015	12/2/2015
4UZFCHCY7GCHR6397	605586	2016	DS	DP	4018	FL	12/1/2015	12/8/2015
4UZFCHCY9GCHR9737	605587	2016	DS	DP	4018	FL	11/23/2015	12/3/2015
4UZFCHCY3GCHP5711	605588	2016	DS	DP	4018	FL	11/3/2015	11/10/2015
4UZFCHCY6GCHS0816	605589	2016	DS	DP	4018	FL	12/8/2015	12/16/2015
4UZACHCY1GCHR6423	605591	2016	DS	DP	3736	FL	11/23/2015	12/3/2015
4UZACHCY3GCHP7632	605592	2016	DS	DP	3736	FL	11/9/2015	11/17/2015
4UZFCHCY5GCHR9735	605593	2016	DS	DP	4041	FL	11/16/2015	11/24/2015
4UZFCHCY1GCHS0819	605594	2016	DS	DP	4041	FL	12/8/2015	12/16/2015
4UZFCHCY2GCHJ8254	605598	2016	DS	DP	4018	FL	7/6/2015	7/14/2015
4UZACHCY4GCHK2106	605600	2016	DS	DP	3736	FL	8/18/2015	8/26/2015
4UZFCHCY4GCHL7470	605602	2016	DS	DP	4041	FL	8/18/2015	8/26/2015
4UZFCHCY9GCHK9865	605603	2016	DS	DP	4018	FL	7/30/2015	8/7/2015
4UZFCHCY4GCHK4900	605604	2016	DS	DP	4018	FL	7/22/2015	7/30/2015
4UZFCHCYXGCHN1647	605605	2016	DS	DP	4018	FL	10/6/2015	10/13/2015
4UZFCHCYXGCHL5416	605606	2016	DS	DP	4018	FL	8/26/2015	9/3/2015
4UZACHCY5GCHL5415	605612	2016	DS	DP	3736	FL	7/29/2015	8/6/2015
4UZACHCY5GCHL7469	605613	2016	DS	DP	3736	FL	8/25/2015	9/2/2015
4UZFCHCYXGCHS0821	605614	2016	DS	DP	4018	FL	12/14/2015	1/7/2016
4UZFCHCY1GCHL5417	605617	2016	DS	DP	4018	FL	7/24/2015	8/4/2015
4UZFCHCY0GCHR9738	605618	2016	DS	DP	4018	FL	12/3/2015	12/10/2015
4UZFCHCY5GCHS4808	605619	2016	DS	DP	4018	FL	12/15/2015	1/7/2016
4UZFCHCY3GCHN5135	605620	2016	DS	DP	4018	FL	10/12/2015	10/20/2015
4UZFCHCY5GCHS7224	605621	2016	DS	DP	4018	FL	1/4/2016	1/13/2016
4UZFCHCY6GCHM2637	605623	2016	DS	DP	4041	FL	9/11/2015	9/21/2015
4UZACHCY6GCHT2460	605626	2016	DS	DP	3726	FL	1/4/2016	1/13/2016
4UZFCHCY5GCHP1949	605627	2016	DS	DP	4041	FL	10/16/2015	10/26/2015
4UZFCHCY3GCHS4810	605628	2016	DS	DP	4018	FL	12/15/2015	1/8/2016
4UZFCHCYXGCHR6393	605629	2016	DS	DP	4002	FL	12/9/2015	12/17/2015
4UZACHCY3GCHL7468	605630	2016	DS	DP	3736	FL	10/19/2015	10/27/2015

4UZFCHCY1GCHJ1229	605633	2016	DS	DP	4018	FL	6/22/2015	7/8/2015
4UZFCHCY2GCHK7472	605638	2016	DS	DP	4018	FL	7/24/2015	8/3/2015
4UZFCHCY0GCHM6702	605640	2016	DS	DP	4018	FL	9/14/2015	9/22/2015
4UZFCHCY7GCHM8348	605643	2016	DS	DP	4018	FL	9/15/2015	9/23/2015
4UZFCHCY4GCHN7072	605645	2016	DS	DP	4018	FL	9/15/2015	9/23/2015
4UZFCHCY1GCHK4899	605655	2016	DS	DP	4018	FL	7/17/2015	7/27/2015
4UZFCHCYXGCHK4898	605658	2016	DS	DP	4018	FL	7/13/2015	7/21/2015
4UZFCHCY4GCHK7473	605666	2016	DS	DP	4018	FL	8/6/2015	8/17/2015
4UZFCHCY1GCHL5420	605671	2016	DS	DP	4018	FL	8/14/2015	8/21/2015
4UZFCHCY7GCHR9736	605672	2016	DS	DP	4018	FL	11/23/2015	12/3/2015
4UZFCHCY8GCHM2638	605673	2016	DS	DP	4018	FL	9/16/2015	9/23/2015
4UZACHCY8GCHJ8253	605676	2016	DS	DP	3736	S	7/27/2015	8/4/2015
4UZFCHCY4GCHM0255	605680	2016	DS	DP	4018	FL	8/28/2015	9/4/2015
4UZFCHCY4GCHM2636	605682	2016	DS	DP	4041	FL	8/31/2015	9/9/2015
4UZFCHCY8GCHM0257	605683	2016	DS	DP	4018	FL	9/1/2015	9/10/2015
4UZFCHCY3GCHL7475	605685	2016	DS	DP	4018	FL	8/18/2015	8/26/2015
4UZFCHCY9GCHM0252	605687	2016	DS	DP	4018	FL	8/19/2015	8/27/2015
4UZFCHCY1GCHL7474	605688	2016	DS	DP	4018	FL	8/19/2015	8/27/2015
4UZFCHCYXGCHL7473	605689	2016	DS	DP	4018	FL	8/20/2015	8/28/2015
4UZACHCY6GCHK7470	605692	2016	DS	DP	3736	FL	8/3/2015	8/11/2015
4UZFCHCY0GCHK9866	605693	2016	DS	DP	4002	FL	7/31/2015	8/10/2015
4UZFCHCY3GCHL5418	605694	2016	DS	DP	4018	FL	8/3/2015	8/11/2015
4UZFCHCY8GCHS0820	605698	2016	DS	DP	4018	FL	12/3/2015	12/11/2015
4UZFCHCY9GCHM6701	605700	2016	DS	DP	4018	FL	9/16/2015	9/24/2015
4UZFCHCY0GCHM0253	605708	2016	DS	DP	4018	FL	8/14/2015	8/24/2015
4UZFCHCY6GCHM0256	605713	2016	DS	DP	4018	FL	8/28/2015	9/8/2015
4UZFCHCY5GCHM8350	605715	2016	DS	DP	4018	FL	9/9/2015	9/17/2015
4UZACHCY2GCHK9863	605720	2016	DS	DP	3726	FL	9/24/2015	10/2/2015
4UZFCHCY9GCHM8352	605734	2016	DS	DP	4018	FL	9/18/2015	9/28/2015
4UZACHCY5GCHK4897	605736	2016	DS	DP	3726	FL	9/3/2015	9/14/2015
4UZFCHCY7GCHM8351	605740	2016	DS	DP	4018	FL	9/28/2015	10/6/2015
4UZFCHCYXGCHN1650	605746	2016	DS	DP	4018	FL	10/8/2015	10/16/2015
4UZFCHCY1GCHN1648	605748	2016	DS	DP	4018	FL	9/29/2015	10/7/2015
4UZFCHCY3GCHN1649	605750	2016	DS	DP	4002	FL	9/30/2015	10/8/2015
4UZFCHCY9GCHM8349	605751	2016	DS	DP	4002	FL	9/25/2015	10/5/2015
4UZFCHCYXGCHN5133	605756	2016	DS	DP	4018	FL	10/8/2015	10/16/2015
4UZFCHCY1GCHN1651	605758	2016	DS	DP	4018	FL	9/30/2015	10/8/2015
4UZFCHCY1GCHN5134	605761	2016	DS	DP	4002	FL	10/14/2015	10/21/2015
4UZACHCY1GCHL7467	605765	2016	DS	DP	3736	FL	10/9/2015	10/19/2015
4UZFCHCY3GCHP5708	605767	2016	DS	DP	4018	FL	10/27/2015	11/4/2015
4UZFCHCY4GCHP9802	605768	2016	DS	DP	4018	FL	11/3/2015	11/11/2015
4UZACHCY1GCHS0815	605769	2016	DS	DP	3736	FL	12/10/2015	1/4/2016
4UZFCHCY3GCHP3635	605774	2016	DS	DP	4018	FL	10/23/2015	10/30/2015
4UZFCHCY6GCHN7073	605775	2016	DS	DP	4018	FL	10/15/2015	10/23/2015
4UZFCHCY5GCHN5136	605776	2016	DS	DP	4002	FL	10/15/2015	10/23/2015
4UZFCHCY8GCHN5132	605777	2016	DS	DP	4041	FL	10/9/2015	10/19/2015
4UZFCHCY5GCHP5712	605778	2016	DS	DP	4002	FL	10/26/2015	11/3/2015
4UZFCHCY5GCHP9808	605787	2016	DS	DP	4002	FL	11/6/2015	11/16/2015
4UZACHCY9GCHT5613	605792	2016	DS	DP	3736	FL	1/13/2016	1/20/2016
4UZFCHCY4GCHT2463	605793	2016	DS	DP	4018	FL	1/7/2016	1/14/2016
4UZACHCYXGCHN7071	605795	2016	DS	DP	3736	FL	10/27/2015	11/4/2015

4UZACHCY4GCHM0251	605796	2016	DS	DP	3736	FL	10/27/2015	11/4/2015
4UZFCHCY5GCHP5709	605797	2016	DS	DP	4018	FL	10/28/2015	11/4/2015
4UZFCHCY1GCHP1950	605798	2016	DS	DP	4002	FL	10/23/2015	11/2/2015
4UZFCHCY2GCHP9801	605799	2016	DS	DP	4041	FL	10/28/2015	11/5/2015
4UZFCHCY3GCHS7223	605801	2016	DS	DP	4018	FL	12/16/2015	1/11/2016
4UZFCHCY3GCHR9734	605802	2016	DS	DP	4018	FL	11/9/2015	11/16/2015
4UZFCHCY1GCHP5710	605804	2016	DS	DP	4018	FL	10/29/2015	11/6/2015
4UZFCHCY3GCHP9807	605808	2016	DS	DP	4018	FL	11/9/2015	11/16/2015
4UZACHCY7GCHR9732	605811	2016	DS	DP	3736	FL	11/25/2015	12/7/2015
4UZFCHCY6GCHT2464	605819	2016	DS	DP	4018	FL	1/7/2016	1/14/2016
4UZACHCY3GCHP9798	605830	2016	DS	DP	3736	FL	11/10/2015	11/18/2015
4UZFCHCY8GCHT2465	605839	2016	DS	DP	4018	FL	1/7/2016	1/15/2016
4UZFCHCYXGCHP9805	605844	2016	DS	DP	4002	FL	11/4/2015	11/12/2015
4UZFCHCY1GCHP9806	605845	2016	DS	DP	4018	FL	11/5/2015	11/13/2015
4UZFCHCY8GCHP9804	605846	2016	DS	DP	4018	FL	11/12/2015	11/19/2015
4UZFCHCY6GCHP9803	605847	2016	DS	DP	4041	FL	11/5/2015	11/13/2015
4UZFCHCY4GCHR6390	605853	2016	DS	DP	4018	FL	11/9/2015	11/17/2015
4UZFCHCY1GCHR9733	605856	2016	DS	DP	4018	S	11/13/2015	11/23/2015
4UZFCHCY2GCHT2462	605862	2016	DS	DP	4018	FL	1/7/2016	1/15/2016
4UZFCHCY5GCHR6396	605866	2016	DS	DP	4018	FL	11/19/2015	11/30/2015
4UZFCHCY1GCHR6394	605867	2016	DS	DP	4018	FL	11/19/2015	12/1/2015
4UZFCHCY3GCHR6395	605868	2016	DS	DP	4018	FL	11/19/2015	12/1/2015
4UZACHCY5GCHP9799	605870	2016	DS	DP	3736	FL	11/20/2015	12/2/2015
4UZFCHCY8GCHR6392	605871	2016	DS	DP	4018	FL	11/19/2015	12/1/2015
4UZFCHCY8GCHS0817	605872	2016	DS	DP	4018	FL	11/24/2015	12/4/2015
4UZFCHCYXGCHS0818	605873	2016	DS	DP	4018	FL	11/25/2015	12/7/2015
4UZFCHCY7GCHS4809	605882	2016	DS	DP	4018	FL	12/11/2015	1/5/2016
4UZFCHCY5GCHT5615	605898	2016	DS	DP	4018	FL	1/11/2016	1/19/2016
4UZACHCY7GCHT5612	605904	2016	DS	DP	3736	FL	1/12/2016	1/19/2016

CANADIAN	Production	Model			Floor	Chassis		
VIN Number	Number	Year	Brand	Type	Plan	Brand	Date In Production	Date Off Production
4UZFCHCY6GCHH5472	412091	2016	VT	DP	4037	FL	6/19/2015	7/8/2015
4UZFCHCY9GCHJ1978	412093	2016	VT	DP	4322	FL	8/5/2015	8/13/2015
4UZFCHCY1GCHH5475	412094	2016	VT	DP	4369	FL	6/18/2015	7/6/2015
4UZFCHCYXGCHH5474	412112	2016	VT	DP	4322	FL	6/16/2015	6/25/2015
4UZFCHCY7GCHJ1221	412113	2016	VT	DP	4037	FL	6/22/2015	7/9/2015
4UZFCHCY3GCHJ1975	412118	2016	VT	DP	4037	FL	7/6/2015	7/14/2015
4UZFCHCY9GCHH5482	605534	2016	DS	DP	4018	FL	6/16/2015	6/24/2015
4UZFCHCY0GCHH5483	605573	2016	DS	DP	4018	FL	6/23/2015	7/9/2015
4UZFCHCY6GCHR6391	605757	2016	DS	DP	4018	FL	11/10/2015	11/17/2015
4UZFCHCY7GCHS7225	605890	2016	DS	DP	4018	FL	1/8/2016	1/15/2016