

NEWMAR CORPORATION

WARRANTY

DEPARTMENT

TECHNICAL SERVICE BULLETIN

DATE ISSUED	MODEL YEAR(S) AFFECTED	TSB #
2/1/2018	2018	510

MODEL

Bay Star Sport	☒	Ventana	☒	Essex	☐
Bay Star	☒	Dutch Star	☐	King Aire	☐
Canyon Star	☒	Mountain Aire	☐	New Aire	☐
Ventana LE	☒	London Aire	☐	Other	☐

DESCRIPTION

Newmar has determined that certain coaches may have had a substitute water pump installed during the manufacturing process.

Issue: The substitution pump requires a 15 amp fuse in lieu of the 10 amp fuse that was installed. This does not pose a safety issue, but the user may overload the 10 amp fuse during pump operation.

Correction: Inspect the water pump to see if it states "Fuse: 15A required." If it does, proceed by installing a 15 amp fuse for the water pump and changing the water pump fuse label from 10A to 15A.

Affected Units: See attached population list

RECOMMENDED ACTION

Inspect the water pump to see if it states "Fuse: 15A required." If it does, proceed by installing a 15 amp fuse for the water pump and labeling the fuse panel accordingly. If the pump does not state "Fuse: 15A required" no action is needed. Order fuse and label from the Newmar Parts Department when fuse and label change is necessary.

Note: The wiring is sufficient for the new 15 amp fuse.

15 Amp Fuse Part # 22238
15A label Part# 22238A

Flat Rate: TSB 510

Labor Time: .2

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date	Date
112897	1F66F5DY5J0A04491	2018	BT	CA	2812	F	11/13/2017	11/20/2017
113066	1F66F5DY2J0A06263	2018	BS	CA	3406	F	11/9/2017	11/17/2017
113068	1F66F5DY0J0A06262	2018	BS	CA	3403	F	11/8/2017	11/16/2017
113071	1F66F5DY7J0A06260	2018	BS	CA	3009	F	11/6/2017	11/14/2017
113072	1F66F5DY5J0A05513	2018	BS	CA	3009	F	11/15/2017	11/27/2017
113073	1F66F5DY6J0A06265	2018	BS	CA	3113	F	11/14/2017	11/22/2017
113074	1F66F5DY9J0A06261	2018	BS	CA	3113	F	11/6/2017	11/14/2017
113077	1F66F5DY6J0A04063	2018	BT	CA	2812	F	11/9/2017	11/17/2017
113079	1F66F5DYXJ0A06981	2018	BT	CA	3307	F	11/15/2017	11/27/2017
113080	1F66F5DY3J0A04490	2018	BT	CA	3307	F	11/8/2017	11/16/2017
113083	1F65F5DY0J0A04488	2018	BT	CA	2702	F	11/7/2017	11/15/2017
113249	1F66F5DY4J0A06264	2018	BS	CA	3009	F	11/13/2017	11/21/2017
162193	1F66F5DY5J0A06256	2018	CS	CA	3513	F	11/10/2017	11/20/2017
162217	1F66F5DY0J0A06259	2018	CS	CA	3924	F	11/13/2017	11/21/2017
162219	1F66F5DY8J0A06252	2018	CS	CA	3710	F	11/10/2017	11/20/2017
162224	1F66F5DYXJ0A06253	2018	CS	CA	3911	F	11/8/2017	11/16/2017
162225	1F66F5DY1J0A06254	2018	CS	CA	3911	F	11/7/2017	11/15/2017
162226	1F66F5DY3J0A06255	2018	CS	CA	3911	F	11/3/2017	11/13/2017
162227	1F66F5DY7J0A06257	2018	CS	CA	3921	F	11/15/2017	11/27/2017
162229	1F66F5DY9J0A06972	2018	CS	CA	3926	F	11/14/2017	11/22/2017
162230	1F66F5DY0J0A06973	2018	CS	CA	3926	F	11/14/2017	11/22/2017
413583	4UZACHFC2JCJX3638	2018	VT	DP	3407	FL	11/10/2017	11/20/2017
413589	4UZACHFC1JCJY2489	2018	VT	DP	3715	FL	11/9/2017	11/17/2017
413590	4UZACHFC2JCJU6665	2018	VT	DP	3715	FL	11/9/2017	11/16/2017
413591	4UZACHFC0JCJY4055	2018	VT	DP	3709	FL	11/10/2017	11/20/2017
413592	4UZACHFC2JCJY4056	2018	VT	DP	3709	FL	11/13/2017	11/21/2017
413595	4UZFCHFE5JCJY4060	2018	VT	DP	4037	FL	11/13/2017	11/21/2017
413596	4UZFCHFE9JCJY2490	2018	VT	DP	4037	FL	11/8/2017	11/16/2017
413597	4UZFCHFE5JCJX9201	2018	VT	DP	4037	FL	11/8/2017	11/16/2017
413598	4UZFCHFE2JCJY2492	2018	VT	DP	4002	FL	11/14/2017	11/21/2017
413599	4UZFCHFE9JCJY4059	2018	VT	DP	4046	FL	11/14/2017	11/22/2017
413601	4UZFCHFE0JCJY2491	2018	VT	DP	4002	FL	11/6/2017	11/14/2017
413607	4UZFCHFE0JCJY4063	2018	VT	DP	4308	FL	11/15/2017	11/27/2017
413608	4UZFCHFE6JCJY2494	2018	VT	DP	4308	FL	11/6/2017	11/14/2017
413609	4UZFCHFE4JCJY2493	2018	VT	DP	4369	FL	11/3/2017	11/13/2017
413610	4UZFCHFE9JCJX9265	2018	VT	DP	4369	FL	11/15/2017	11/22/2017
413612	4UZFCHFE9JCJY4062	2018	VT	DP	4369	FL	11/15/2017	11/27/2017
413613	4UZFCHFE7JCJX9264	2018	VT	DP	4369	FL	11/7/2017	11/15/2017
413628	4UZAB2FC2JCJY9435	2018	VL	DP	3413	FL	11/10/2017	11/20/2017
413631	4UZAB2FC0JCJY9434	2018	VL	DP	3412	FL	11/7/2017	11/15/2017
413633	4UZAB2FC7JCJY4053	2018	VL	DP	3436	FL	11/7/2017	11/14/2017
413799	4UZACHFC8JCJV6150	2018	VL	DP	4037	FL	11/6/2017	11/14/2017