

# Newmar Corporation

PO Box 30  
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 55  
Nov 6, 2020

NHTSA #20V 566  
TC #2020-443

# Terminated 1.12.22

## RECALL SERVICE BULLETIN

# Replaced by

2021 :: Canyon Star  
2018- 2019 :: Ventana

# DTNA FL 912

### DESCRIPTION

Daimler Trucks North America (DTNA) has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Freightliner chassis (NHTSA #20V 529). In response, Newmar Corporation is issuing recall NHTSA # 20V 566 and TC # 2020-443.

### ISSUE

# NHTSA # 21V 921

On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim, bending and become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure on the inner wheel, and extended driving on an overloaded tire may increase the risk of a crash.

### UNITS AFFECTED

Refer to the attached population list for specific VIN numbers supplied by DTNA for the coaches that may be affected.

### CORRECTIVE ACTION

Repairs will be performed by Daimler Trucks North America authorized service facilities. DTNA will provide FL-861 work instructions and any necessary parts to complete the recall procedure. The inner wheel valve stem stabilizers will be inspected and adjusted as needed. If the adjustment does not resolve the issue, then the inner valve stem will be replaced.

### CUSTOMER ACTION

Contact Daimler Trucks North America at 1-800-547-0712 to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department at 1-800-731-8300. A brand specialist will assist you in scheduling an appointment to have this repair completed.

### DEALER ACTION

Contact the Freightliner Customer Support Center at 1-800-FTL-HELP (1-800-385-4357), and follow the prompts, or visit <https://freightliner.com/dealer-search/> to locate an authorized DTNA service center to schedule and perform the recall near you. If you need assistance contacting DTNA, contact your Newmar Service Account Manager.

### NOTE

Newmar will not be authorizing this repair. DTNA will authorize and schedule this repair.

**IMPORTANT:** Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

# Terminated 1.12.22

Date: October 30, 2020

Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 20V 566

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar motorhomes.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule and appointment with each dealer to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

## REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim opening and become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash. The inner wheel valve stem stabilizers will be inspected and adjusted as needed. If the adjustment does not resolve the issue then the inner valve stem will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

## DEALER CAMPAIGN RESPONSIBILITY

**Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.**

## REPAIR PROCEDURE

DTNA will provide the work instructions. DTNA campaign number FL-861.

**If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely,

Newmar Corporation



NEWMAR CORPORATION

NEWMARCORP.COM

WHEN YOU KNOW THE DIFFERENCE

# Terminated 1.12.22

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # \_\_\_\_\_

Name \_\_\_\_\_

Address \_\_\_\_\_

City, State Zip code \_\_\_\_\_

# Replaced by

Date: October 30, 2020

Motor Vehicle Recall Notification - Recall Campaign No. 20V 566

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

## REASON FOR THE RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes, the tire valve stem extension for the inner wheel may contact the outer wheel rim, possibly become damaged. Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash. The inner wheel valve stem stabilizers will be inspected and adjusted as needed. If the adjustment does not resolve the issue, then the inner valve stem will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

## The Safety Risk

Extensive damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, extended driving with an overloaded tire may increase the risk of a crash.

## WHAT WE WILL DO

DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Estimated time for repair is one hour.

## WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, please contact an authorized Daimler Trucks North America dealer to arrange to have the FL-861 Recall performed and to ensure that parts are available at the dealership. To locate an authorized dealer, search online at [Daimler-TrucksNorthAmerica.com/Contact-us](http://Daimler-TrucksNorthAmerica.com/Contact-us). Scroll down to "Locate a Dealer" and select the appropriate brand. The Recall will take approximately one hour and will be performed at no charge to you. You may also confirm your vehicle's involvement in this recall at this URL: <https://dtna-dlrinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>. If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address [DTNA.Warranty.Campaigns@Daimler.com](mailto:DTNA.Warranty.Campaigns@Daimler.com).

If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

**Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.**

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

**Service Department**  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

Authorized Chassis Service Facilities are being required to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and the condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.nhtsa.gov>

If you no longer own the vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corp.



WHEN YOU KNOW THE DIFFERENCE

Date: October 3, 2020  
To: Newmar Corporation - Motor Vehicle Recall Notification

Subject: Recall Campaign No.: #2020-443

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time. If a dealer or owner fails to do so, it is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

#### REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

Issue:  
On certain motorhomes, the tire valve stem stabilizer for the inner wheel may get damaged by contact with the outer wheel. If this happens, the inner tire could lose air pressure. This could overload the outer tire and cause it to fail.

#### Safety Risk:

A tire failure could cause a loss of control and increase the risk of a crash.

#### Corrective Actions:

The inner wheel valve stem stabilizers will be inspected and adjusted as needed. If the adjustment does not resolve the issue then the inner valve stem will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

#### DEALER CAMPAIGN RESPONSIBILITY

***Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.***

#### REPAIR PROCEDURE

DTNA will provide the work instructions. DTNA campaign number FL-861.

**If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.**

Thank you for your cooperation.

Sincerely, Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

VIN#  
Make, model, model year  
Name  
Address  
City, State Zip code

Date: October 30, 2021  
Motor Vehicle Recall Notification - Recall Campaign No. 2020-43

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Canada Motor Vehicle Safety Act*.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

#### REASON FOR THE RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes, the tire system for the inner wheel may get damaged by contact with the outer wheel. In this happens, the inner tire could lose air pressure. This could overload the outer tire and cause it to fail.

#### Safety Risk:

A tire failure could cause a loss of control and increase the risk of a crash.

#### Corrective Actions:

The inner wheel valve stem stabilizers will be inspected and adjusted as needed. If the adjustment does not resolve the issue then the inner valve stem will be replaced. Repairs will be performed by Daimler Trucks North America authorized service facilities.

**The motorhomes require immediate service. Continued use poses a potential safety hazard.**

#### WHAT WE WILL DO

DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Estimated time for repair is one hour.

#### WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, please contact an authorized Daimler Trucks North America dealer to arrange to have the FL-861 Recall performed and to ensure that parts are available at the dealership. To locate an authorized dealer, search online at [Daimler-TrucksNorthAmerica.com/Contact-us](https://daimler-trucks-north-america.com/Contact-us). Scroll down to "Locate a Dealer" and select the appropriate brand. The Recall will take approximately one hour and will be performed at no charge to you. You may also confirm your vehicle's involvement in this recall at this URL: <https://dtna-dlrinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>. If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address [DTNA.Warranty.Campaigns@Daimler.com](mailto:DTNA.Warranty.Campaigns@Daimler.com).

If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that all vehicles for which this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

**Service Department**

Newmar Corporation  
355 N Delaware St  
Newmar, WI 54651-0030

Authorized Chassis Service Facilities are requested to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

Nom (V)  
Marque, modèle, année ou modèle  
Nom (nom)  
Adresse  
Ville, province et code postal

Date : 30 novembre 2022  
Avis de rappel du véhicule automobile (modèle de rappel 2010-2013)

Cher client :

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*.

Il a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

#### **RAISON DE CE RAPPEL**

Newmar Corporation a déterminé que certaines autocaravanes construites sur un châssis Freightliner présentaient un défaut lié à la sécurité. Ce rappel fait suite à des informations fournies par Daimler Trucks North America LLC.

Problème :  
Sur certaines autocaravanes, l'écrou de la tige de la valve du pneu de la roue interne peut entrer en contact avec la roue externe et se détacher. Si cela se produit, le pneu interne peut perdre sa pression et pourrait surcharger le pneu externe et provoquer sa défaillance.

Risque pour la sécurité :

Une défaillance de l'un des pneus peut entraîner une perte de contrôle du véhicule et augmenter le risque d'accident.

Mesures correctives :

Les stabilisateurs de la tige de la valve de la roue intérieure seront inspectés et ajustés si nécessaire. Si cet ajustement ne résout pas le problème, alors la tige de la valve de la roue intérieure sera entièrement remplacée. Les réparations seront effectuées par les centres de réparation autorisés de Daimler Trucks North America.

**Les autocaravanes nécessitent une inspection immédiate. Continuer à utiliser ces véhicules sans les faire contrôler constitue un risque potentiel pour la sécurité.**

#### **CE QUE NOUS FERONS**

DTNA fournira aux propriétaires de toutes les autocaravanes concernées une solution pour le défaut potentiel, sans frais de pièces ou de main-d'œuvre. Le temps estimé pour la réparation est d'une heure.

#### **CE QUE VOUS DEVEZ FAIRE**

Comme ce défaut concerne la sécurité des véhicules automobiles, veuillez communiquer avec un concessionnaire Daimler Trucks North America agréé pour faire effectuer le rappel FL-861 et vous assurer que les pièces sont disponibles chez le concessionnaire. Pour trouver un concessionnaire agréé, faites une recherche en ligne sur [Daimler-TrucksNorthAmerica.com/Contact-us](https://Daimler-TrucksNorthAmerica.com/Contact-us). Faites défiler la page vers le bas jusqu'à la section « Trouver un concessionnaire » et sélectionnez la marque appropriée. La réparation liée au rappel prendra environ une heure et sera effectuée sans frais pour vous. Vous pouvez également vérifier que votre véhicule est concerné par ce rappel à l'adresse suivante : <https://dtna-dlinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>.

Pour toute question concernant ce rappel, veuillez vous adresser au Service des campagnes de garantie au (800) 547-0712, de 7 h à 16 h Heure du Pacifique, du lundi au vendredi. Adresse électronique : [DTNA-Warrant@campanys.com](mailto:DTNA-Warrant@campanys.com).

Pour toute aide supplémentaire, communiquez avec le service technique de Newmar en composant le 1 800 731-8300. Un représentant vous aidera à fixer la rendez-vous afin de faire effectuer cette réparation.

**Les réglementations fédérales exigent que tout loueur de véhicule recevant cet avis de rappel en transmette une copie au locataire dans un délai de dix jours.**

Si la réparation a été effectuée avant la réception de cette lettre, vous pourriez avoir droit à un remboursement du coût d'un remplacement du moteur. Pour de plus amples renseignements, veuillez communiquer avec Newmar Corporation :

Service technique  
Newmar Corporation  
555 N Delaware St  
Nappanee, IN 46550-0030

Les agents certifiés d'entretien de Newmar sont les mieux équipés pour obtenir des pièces et effectuer la réparation afin que votre véhicule soit réparé le plus rapidement possible. COUTEFOIS, si vous apportez votre véhicule à votre centre certifié d'entretien de châssis à la date prévue et que la réparation n'est pas effectuée à cette date ou dans un délai de cinq jours, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1 800 731-8300.

Si vous n'êtes plus propriétaire de ce véhicule, veuillez nous fournir le nom et l'adresse de la personne ou du concessionnaire à qui vous avez vendu ou échangé le véhicule. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction à l'égard des produits Newmar sont importantes pour nous. Nous vous prions de nous excuser pour tous désagréments que cette situation a pu vous causer.

Cordialement,

Newmar Corporation

| Prod# | VIN Number | Year | Brand | Type | Floor | Chassis | Date In | Date Off |
|-------|------------|------|-------|------|-------|---------|---------|----------|
|-------|------------|------|-------|------|-------|---------|---------|----------|

USA Units

|        |                    |      |    |    |      |    |            |            |
|--------|--------------------|------|----|----|------|----|------------|------------|
| 162678 | 4UZACMFC4MCMMD0887 | 2021 | CS | FD | 3719 | FL | 1/17/2020  | 1/28/2020  |
| 162681 | 4UZACMFC8MCMC9015  | 2021 | CS | FD | 3719 | FL | 1/28/2020  | 1/28/2020  |
| 162682 | 4UZACMFC2MCMMD0886 | 2021 | CS | FD | 3719 | FL | 2/6/2020   | 2/17/2020  |
| 162688 | 4UZACMFC7MCMCL470  | 2021 | CS | FD | 3719 | FL | 6/4/2020   | 6/15/2020  |
| 162689 | 4UZACMFC2MCMMS106  | 2021 | CS | FD | 3927 | FL | 6/8/2020   | 6/17/2020  |
| 162690 | 4UZACMFC5MCMMS3104 | 2021 | CS | FD | 3710 | FL | 8/10/2020  | 8/19/2020  |
| 162691 | 4UZACMFC0MCMMS3110 | 2021 | CS | FD | 3927 | FL | 6/23/2020  | 7/17/2020  |
| 162692 | 4UZACMFC5MCMMP2330 | 2021 | CS | FD | 3927 | FL | 8/20/2020  | 8/28/2020  |
| 162693 | 4UZACMFC5MCMMP0124 | 2021 | CS | FD | 3927 | FL | 7/30/2020  | 8/7/2020   |
| 162694 | 4UZACMFC9MCMN103   | 2021 | CS | FD | 3927 | FL | 7/23/2020  | 8/3/2020   |
| 162698 | 4UZACMFC5MCMN6872  | 2021 | CS | FD | 3927 | FL | 7/27/2020  | 8/4/2020   |
| 162699 | 4UZACMFC7MCMMP0725 | 2021 | CS | FD | 3927 | FL | 8/7/2020   | 8/18/2020  |
| 162700 | 4UZACMFC6MCMMS9798 | 2021 | CS | FD | 3927 | FL | 7/17/2020  | 7/27/2020  |
| 162701 | 4UZACMFC4MCMMS1109 | 2021 | CS | FD | 3927 | FL | 7/10/2020  | 6/22/2020  |
| 162702 | 4UZACMFC7MCMMS1105 | 2021 | CS | FD | 3719 | FL | 7/22/2020  | 7/15/2020  |
| 162704 | 4UZACMFC6MCMMS1799 | 2021 | CS | FD | 3927 | FL | 7/21/2020  | 7/29/2020  |
| 162705 | 4UZACMFC9MCMMS3106 | 2021 | CS | FD | 3710 | FL | 8/17/2020  | 8/25/2020  |
| 162709 | 4UZACMFC7MCMN3889  | 2021 | CS | FD | 3927 | FL | 8/3/2020   | 8/12/2020  |
| 162710 | 4UZACMFC2MCMMS3111 | 2021 | CS | FD | 3927 | FL | 6/25/2020  | 7/21/2020  |
| 162711 | 4UZACMFC7MCMN6773  | 2021 | CS | FD | 3927 | FL | 7/19/2020  | 8/12/2020  |
| 162712 | 4UZACMFC9MCMMS329  | 2021 | CS | FD | 3927 | FL | 8/21/2020  | 8/31/2020  |
| 162720 | 4UZACMFC7MCMMP2331 | 2021 | CS | FD | 3927 | FL | 8/21/2020  | 9/7/2020   |
| 162730 | 4UZACMFC9MCMMP2332 | 2021 | CS | FD | 3927 | FL | 8/28/2020  | 9/9/2020   |
| 413283 | 4UZFCHFE9JCJT5525  | 2018 | VT | DP | 4369 | FL | 7/10/2017  | 7/18/2017  |
| 413287 | 4UZFCHFE8JCJR8342  | 2018 | VT | DP | 4326 | FL | 6/9/2017   | 6/20/2017  |
| 413288 | 4UZFCHFE1JCJS6740  | 2018 | VT | DP | 4369 | FL | 6/16/2017  | 6/27/2017  |
| 413290 | 4UZFCHFE6JCJR8341  | 2018 | VT | DP | 4310 | FL | 5/24/2017  | 6/6/2017   |
| 413293 | 4UZFCHFE3JCJS2401  | 2018 | VT | DP | 4326 | FL | 6/12/2017  | 6/20/2017  |
| 413294 | 4UZFCHFE0JCJT1847  | 2018 | VT | DP | 4326 | FL | 6/19/2017  | 6/27/2017  |
| 413300 | 4UZFCHFE5JCJS6739  | 2018 | VT | DP | 4037 | FL | 6/6/2017   | 6/14/2017  |
| 413301 | 4UZFCHFE4JCJR8340  | 2018 | VT | DP | 4037 | FL | 6/12/2017  | 6/20/2017  |
| 413310 | 4UZACHFC2JCJT5519  | 2018 | VT | DP | 3407 | FL | 7/19/2017  | 7/27/2017  |
| 413311 | 4UZACHFCXJCJU2234  | 2018 | VT | DP | 3407 | FL | 7/31/2017  | 8/7/2017   |
| 413312 | 4UZACHFC9JCJS8454  | 2018 | VT | DP | 3407 | FL | 6/23/2017  | 7/11/2017  |
| 413313 | 4UZACHFC2JCJV8718  | 2018 | VT | DP | 3436 | FL | 8/31/2017  | 9/11/2017  |
| 413314 | 4UZACHFC3JCJV3625  | 2018 | VT | DP | 3709 | FL | 8/24/2017  | 8/31/2017  |
| 413315 | 4UZFCHFE1JCJS2400  | 2018 | VT | DP | 4002 | FL | 6/19/2017  | 6/27/2017  |
| 413316 | 4UZFCHFE6JCJU4828  | 2018 | VT | DP | 4037 | FL | 8/7/2017   | 8/15/2017  |
| 413317 | 4UZFCHFE7JCJV0696  | 2018 | VT | DP | 4369 | FL | 10/10/2017 | 10/18/2017 |
| 413318 | 4UZFCHFEXJCJV6156  | 2018 | VT | DP | 4369 | FL | 9/20/2017  | 9/28/2017  |
| 413319 | 4UZACHFC9JCJS6736  | 2018 | VT | DP | 3715 | FL | 6/20/2017  | 6/28/2017  |
| 413320 | 4UZACHFC5JCJR8338  | 2018 | VT | DP | 3715 | FL | 6/13/2017  | 6/21/2017  |
| 413325 | 4UZFCHFE3JCJS6741  | 2018 | VT | DP | 4326 | FL | 6/26/2017  | 7/12/2017  |
| 413326 | 4UZFCHFE0JCJU6669  | 2018 | VT | DP | 4369 | FL | 8/8/2017   | 8/15/2017  |
| 413329 | 4UZACHFC0JCJS8455  | 2018 | VT | DP | 3709 | FL | 6/26/2017  | 7/13/2017  |
| 413330 | 4UZFCHFE8JCJV6155  | 2018 | VT | DP | 4308 | FL | 9/5/2017   | 9/13/2017  |
| 413334 | 4UZACHFC3JCJR8337  | 2018 | VT | DP | 3709 | FL | 6/2/2017   | 6/12/2017  |

| Prod#  | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|--------|-------------------|------|-------|------|-------|---------|------------|------------|
| 413337 | 4UZFCHFE4JCJU4830 | 2018 | VT    | DP   | 4046  | FL      | 8/30/2017  | 9/8/2017   |
| 413342 | 4UZFCHFE0JCJU9961 | 2018 | VT    | DP   | 4369  | FL      | 8/11/2017  | 8/21/2017  |
| 413343 | 4UZACHFC6JCJU9956 | 2018 | VT    | DP   | 3407  | FL      | 8/21/2017  | 8/29/2017  |
| 413344 | 4UZFCHFE3JCJU9955 | 2018 | VT    | DP   | 3436  | FL      | 7/25/2017  | 8/7/2017   |
| 413345 | 4UZACHFC9JCJT1841 | 2018 | VT    | DP   | 3436  | FL      | 7/20/2017  | 7/28/2017  |
| 413346 | 4UZACHFC1JCJU4826 | 2018 | VT    | DP   | 3436  | FL      | 8/9/2017   | 8/17/2017  |
| 413347 | 4UZACHFC2JCJS2396 | 2018 | VT    | DP   | 3412  | FL      | 6/27/2017  | 7/13/2017  |
| 413348 | 4UZACHFC0JCJU6664 | 2018 | VT    | DP   | 3709  | FL      | 8/15/2017  | 8/23/2017  |
| 413349 | 4UZACHFC0JCJU6737 | 2018 | VT    | DP   | 3709  | FL      | 6/20/2017  | 6/29/2017  |
| 413351 | 4UZFCHFE1JCJU9959 | 2018 | VT    | DP   | 4032  | FL      | 8/16/2017  | 8/24/2017  |
| 413352 | 4UZFCHFE1JCJU4239 | 2018 | VT    | DP   | 4002  | FL      | 7/31/2017  | 8/8/2017   |
| 413352 | 4UZFCHFE8JCJU4829 | 2018 | VT    | DP   | 4037  | FL      | 8/23/2017  | 8/31/2017  |
| 413353 | 4UZFCHFE3JCJS6738 | 2018 | VT    | DP   | 4037  | FL      | 6/27/2017  | 7/13/2017  |
| 413354 | 4UZACHFC1JCJR8336 | 2018 | VT    | DP   | 3436  | FL      | 6/13/2017  | 6/21/2017  |
| 413356 | 4UZACHFC7JCJU3621 | 2018 | VT    | DP   | 3715  | FL      | 7/28/2017  | 9/6/2017   |
| 413358 | 4UZACHFC6JCJS2398 | 2018 | VT    | DP   | 3715  | FL      | 7/14/2017  | 6/22/2017  |
| 413360 | 4UZACHFC1JCJS2395 | 2018 | VT    | DP   | 3412  | FL      | 6/21/2017  | 7/10/2017  |
| 413361 | 4UZFCHFE9JCJS2399 | 2018 | VT    | DP   | 4037  | FL      | 6/15/2017  | 6/26/2017  |
| 413362 | 4UZFCHFE6JCJV6154 | 2018 | VT    | DP   | 4369  | FL      | 9/12/2017  | 9/20/2017  |
| 413364 | 4UZFCHFE7JCJU6667 | 2018 | VT    | DP   | 4046  | FL      | 10/2/2017  | 10/10/2017 |
| 413365 | 4UZFCHFE1JCJT5523 | 2018 | VT    | DP   | 4037  | FL      | 7/18/2017  | 7/26/2017  |
| 413366 | 4UZFCHFE1JCJU4825 | 2018 | VT    | DP   | 3407  | FL      | 7/1/2017   | 8/8/2017   |
| 413371 | 4UZFCHFE1JCJT398  | 2018 | VT    | DP   | 4037  | FL      | 7/26/2017  | 8/2/2017   |
| 413375 | 4UZACHFC0JCJT1842 | 2018 | VT    | DP   | 3709  | FL      | 7/12/2017  | 7/19/2017  |
| 413376 | 4UZFCHFEXJCJW0692 | 2018 | VT    | DP   | 4037  | FL      | 9/21/2017  | 9/29/2017  |
| 413377 | 4UZFCHFEXJCJU4833 | 2018 | VT    | DP   | 4369  | FL      | 8/2/2017   | 8/10/2017  |
| 413383 | 4UZACHFC3JCJV6153 | 2018 | VT    | DP   | 3412  | FL      | 9/12/2017  | 9/19/2017  |
| 413384 | 4UZFCHFE4KCKM3293 | 2018 | VT    | DP   | 4037  | FL      | 5/21/2018  | 5/29/2018  |
| 413385 | 4UZFCHFE2JCJY9443 | 2018 | VT    | DP   | 4037  | FL      | 12/19/2017 | 1/11/2018  |
| 413387 | 4UZFCHFE8JCJR8339 | 2018 | VT    | DP   | 4037  | FL      | 6/6/2017   | 6/14/2017  |
| 413392 | 4UZFCHFE6JCJT8401 | 2018 | VT    | DP   | 4369  | FL      | 7/25/2017  | 8/2/2017   |
| 413395 | 4UZFCHFE4JCJU9963 | 2018 | VT    | DP   | 4310  | FL      | 8/24/2017  | 9/1/2017   |
| 413396 | 4UZFCHFE1JCJV3629 | 2018 | VT    | DP   | 4326  | FL      | 8/29/2017  | 9/7/2017   |
| 413397 | 4UZFCHFE8JCJU2241 | 2018 | VT    | DP   | 4369  | FL      | 7/20/2017  | 7/28/2017  |
| 413398 | 4UZFCHFE9JCJU6668 | 2018 | VT    | DP   | 4369  | FL      | 8/2/2017   | 8/10/2017  |
| 413399 | 4UZFCHFE3JCJT5522 | 2018 | VT    | DP   | 4002  | FL      | 7/28/2017  | 8/4/2017   |
| 413401 | 4UZACHFC0JCJS2395 | 2018 | VT    | DP   | 3436  | FL      | 6/7/2017   | 6/15/2017  |
| 413406 | 4UZFCHFE4JCJT8400 | 2018 | VT    | DP   | 4369  | FL      | 7/13/2017  | 7/21/2017  |
| 413407 | 4UZFCHFE5JCJT1844 | 2018 | VT    | DP   | 4049  | FL      | 7/17/2017  | 7/25/2017  |
| 413413 | 4UZACHFC1JCJV6152 | 2018 | VT    | DP   | 3407  | FL      | 9/13/2017  | 9/20/2017  |
| 413414 | 4UZACHFC6JCJV3621 | 2018 | VT    | DP   | 3412  | FL      | 8/29/2017  | 9/7/2017   |
| 413415 | 4UZACHFC4JCJV3620 | 2018 | VT    | DP   | 3436  | FL      | 8/25/2017  | 9/5/2017   |
| 413416 | 4UZACHFC1JCJZ9681 | 2018 | VT    | DP   | 3709  | FL      | 1/11/2018  | 1/19/2018  |
| 413420 | 4UZFCHFE1JCKA8964 | 2018 | VT    | DP   | 4037  | FL      | 1/10/2018  | 1/17/2018  |
| 413421 | 4UZFCHFE3JCJW3580 | 2018 | VT    | DP   | 4311  | FL      | 9/19/2017  | 9/27/2017  |
| 413422 | 4UZFCHFE9JCJT1846 | 2018 | VT    | DP   | 4308  | FL      | 7/13/2017  | 7/24/2017  |
| 413425 | 4UZACHFC4JCJV8719 | 2018 | VT    | DP   | 3407  | FL      | 9/13/2017  | 9/21/2017  |
| 413426 | 4UZACHFC2JCJT1843 | 2018 | VT    | DP   | 3715  | FL      | 6/29/2017  | 7/17/2017  |

Terminated 1.12.22  
Replaced by  
DTNA FL 912  
NHSA # 21V921

| Prod#  | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|--------|-------------------|------|-------|------|-------|---------|------------|------------|
| 413427 | 4UZFCHFEXJCU2239  | 2018 | VT    | DP   | 4037  | FL      | 8/4/2017   | 8/14/2017  |
| 413429 | 4UZFCHF6JCJU4831  | 2018 | VT    | DP   | 4308  | FL      | 7/20/2017  | 7/28/2017  |
| 413432 | 4UZFCHF7JCJT5524  | 2018 | VT    | DP   | 4308  | FL      | 6/29/2017  | 7/7/2017   |
| 413433 | 4UZFCHF6JCJU4833  | 2018 | VT    | DP   | 4308  | FL      | 10/10/2017 | 10/18/2017 |
| 413434 | 4UZFCHF6JCJU4834  | 2018 | VT    | DP   | 4308  | FL      | 9/26/2017  | 10/4/2017  |
| 413435 | 4UZACHFC9JCJV5628 | 2018 | VT    | DP   | 3709  | FL      | 10/11/2017 | 10/19/2017 |
| 413436 | 4UZACHFC9KCKF4374 | 2018 | VT    | DP   | 3407  | FL      | 3/20/2018  | 3/27/2018  |
| 413439 | 4UZFCHF6JCJY9445  | 2018 | VT    | DP   | 4369  | FL      | 12/12/2017 | 12/20/2017 |
| 413440 | 4UZFCHF9JCJU9960  | 2018 | VT    | DP   | 4349  | FL      | 9/20/2017  | 9/28/2017  |
| 413441 | 4UZFCHF6JCJU4832  | 2018 | VT    | DP   | 4308  | FL      | 7/21/2017  | 7/28/2017  |
| 413451 | 4UZFCHF6JCJU4831  | 2018 | VT    | DP   | 4308  | FL      | 6/16/2017  | 6/26/2017  |
| 413461 | 4UZACHFC3KCKF8615 | 2018 | VT    | DP   | 3412  | FL      | 4/4/2018   | 4/11/2018  |
| 413462 | 4UZACHFC0JCJT5521 | 2018 | VT    | DP   | 3715  | FL      | 7/14/2017  | 7/24/2017  |
| 413465 | 4UZACHFC2JCJV8721 | 2018 | VT    | DP   | 3436  | FL      | 9/14/2017  | 9/22/2017  |
| 413473 | 4UZACHFCXJCJV61   | 2018 | VT    | DP   | 3412  | FL      | 9/24/2017  | 9/1/2017   |
| 413474 | 4UZFCHF5JCJU6360  | 2018 | VT    | DP   | 4037  | FL      | 10/13/2017 | 10/23/2017 |
| 413475 | 4UZFCHF6JCJY9447  | 2018 | VT    | DP   | 4369  | FL      | 10/13/2017 | 10/23/2017 |
| 413476 | 4UZFCHF5JCJV8722  | 2018 | VT    | DP   | 4369  | FL      | 10/2/2017  | 10/10/2017 |
| 413482 | 4UZACHFC1JCJU2235 | 2018 | VT    | DP   | 3412  | FL      | 8/3/2017   | 8/10/2017  |
| 413483 | 4UZFCHF0KCKJ5748  | 2018 | VT    | DP   | 4326  | FL      | 5/7/2018   | 5/15/2018  |
| 413484 | 4UZACHFC0JCJU2236 | 2018 | VT    | DP   | 3715  | FL      | 8/10/2017  | 8/18/2017  |
| 413485 | 4UZACHFC1JCJV5511 | 2018 | VT    | DP   | 3715  | FL      | 10/12/2017 | 10/20/2017 |
| 413486 | 4UZACHFC1JCJV750  | 2018 | VT    | DP   | 4037  | FL      | 10/28/2017 | 10/27/2017 |
| 413488 | 4UZFCHF9JCJW0697  | 2018 | VT    | DP   | 4310  | FL      | 10/16/2017 | 10/24/2017 |
| 413489 | 4UZFCHF7JCJY4061  | 2018 | VT    | DP   | 4037  | FL      | 11/20/2017 | 11/30/2017 |
| 413490 | 4UZFCHFEXJCJY7200 | 2018 | VT    | DP   | 4037  | FL      | 12/5/2017  | 12/13/2017 |
| 413491 | 4UZFCHF6JCJS8456  | 2018 | VT    | DP   | 4037  | FL      | 7/21/2017  | 7/31/2017  |
| 413492 | 4UZFCHF7JCJW3579  | 2018 | VT    | DP   | 4037  | FL      | 10/27/2017 | 11/6/2017  |
| 413493 | 4UZACHFC5JCJU2237 | 2018 | VT    | DP   | 3715  | FL      | 8/11/2017  | 8/21/2017  |
| 413494 | 4UZACHFCXJCJY9442 | 2018 | VT    | DP   | 3715  | FL      | 12/1/2017  | 12/11/2017 |
| 413495 | 4UZFCHF5JCJY7203  | 2018 | VT    | DP   | 4369  | FL      | 12/6/2017  | 12/14/2017 |
| 413496 | 4UZFCHF7JCKA3672  | 2018 | VT    | DP   | 4369  | FL      | 1/17/2018  | 1/25/2018  |
| 413497 | 4UZFCHF8JCJZ5554  | 2018 | VT    | DP   | 4369  | FL      | 12/12/2017 | 12/19/2017 |
| 413498 | 4UZFCHF3JCJY7202  | 2018 | VT    | DP   | 4369  | FL      | 12/13/2017 | 12/21/2017 |
| 413502 | 4UZFCHF0JCJU9958  | 2018 | VT    | DP   | 4037  | FL      | 9/8/2017   | 9/18/2017  |
| 413504 | 4UZFCHF5JCJW3578  | 2018 | VT    | DP   | 4002  | FL      | 9/29/2017  | 10/9/2017  |
| 413505 | 4UZFCHF2JCJZ3492  | 2018 | VT    | DP   | 4369  | FL      | 12/21/2017 | 1/12/2018  |
| 413506 | 4UZFCHF3JCJZ9687  | 2018 | VT    | DP   | 4308  | FL      | 12/21/2017 | 1/15/2018  |
| 413511 | 4UZFCHF3JCKA3670  | 2018 | VT    | DP   | 4037  | FL      | 12/20/2017 | 1/11/2018  |
| 413512 | 4UZFCHFEXJCKA8963 | 2018 | VT    | DP   | 4037  | FL      | 1/9/2018   | 1/17/2018  |
| 413513 | 4UZACHFC7JCKA8962 | 2018 | VT    | DP   | 3407  | FL      | 2/7/2018   | 2/14/2018  |
| 413514 | 4UZACHFC6JCKA3669 | 2018 | VT    | DP   | 3715  | FL      | 1/23/2018  | 1/30/2018  |
| 413515 | 4UZACHFC3JCKC1000 | 2018 | VT    | DP   | 3709  | FL      | 1/30/2018  | 2/7/2018   |
| 413518 | 4UZACHFCXJCJZ3491 | 2018 | VT    | DP   | 3412  | FL      | 12/14/2017 | 1/8/2018   |
| 413519 | 4UZACHFC2JCKA3667 | 2018 | VT    | DP   | 3407  | FL      | 1/8/2018   | 1/16/2018  |
| 413521 | 4UZACHFC9JCJU6663 | 2018 | VT    | DP   | 3412  | FL      | 8/14/2017  | 8/22/2017  |
| 413523 | 4UZFCHF6JCJU2240  | 2018 | VT    | DP   | 4369  | FL      | 7/17/2017  | 7/25/2017  |
| 413527 | 4UZFCHF8JCJV3630  | 2018 | VT    | DP   | 4369  | FL      | 9/6/2017   | 9/14/2017  |

Terminated 1.12.22  
Replaced by  
DTNA FL 912  
NHTSA # 21V921

| Prod#  | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|--------|-------------------|------|-------|------|-------|---------|------------|------------|
| 413528 | 4UZACHFC9JCJT5520 | 2018 | VT    | DP   | 3407  | FL      | 7/21/2017  | 7/31/2017  |
| 413536 | 4UZFCHFE2JCKC6910 | 2018 | VT    | DP   | 4002  | FL      | 2/7/2018   | 2/15/2018  |
| 413537 | 4UZACHFC5JCKB2525 | 2018 | VT    | DP   | 3407  | FL      | 2/8/2018   | 2/15/2018  |
| 413538 | 4UZACHFC7JCKD1259 | 2018 | VT    | DP   | 3407  | FL      | 2/13/2018  | 2/20/2018  |
| 413539 | 4UZACHFC9JCKJ73   | 2018 | VT    | DP   | 3412  | FL      | 4/10/2017  | 4/17/2018  |
| 413540 | 4UZACHFC5JCKA8961 | 2018 | VT    | DP   | 3436  | FL      | 1/25/2018  | 2/1/2018   |
| 413541 | 4UZACHFC2JCKC0999 | 2018 | VT    | DP   | 3709  | FL      | 1/23/2018  | 1/30/2018  |
| 413542 | 4UZACHFC5JCKC1001 | 2018 | VT    | DP   | 3715  | FL      | 2/1/2018   | 2/8/2018   |
| 413543 | 4UZFCHFE5KCD1259  | 2018 | VT    | DP   | 4002  | FL      | 2/8/2018   | 2/15/2018  |
| 413544 | 4UZFCHFE1JCC1304  | 2018 | VT    | DP   | 4037  | FL      | 1/25/2018  | 2/1/2018   |
| 413545 | 4UZACHFC1JCKC000  | 2018 | VT    | DP   | 4037  | FL      | 2/1/2018   | 2/9/2018   |
| 413547 | 4UZACHFE3JCJW0694 | 2018 | VT    | DP   | 4369  | FL      | 10/6/2017  | 10/16/2017 |
| 413549 | 4UZFCHFE9JCKA8968 | 2018 | VT    | DP   | 4311  | FL      | 2/26/2018  | 3/6/2018   |
| 413552 | 4UZFCHFE5JCJW0695 | 2018 | VT    | DP   | 4310  | FL      | 10/9/2017  | 10/16/2017 |
| 413553 | 4UZACHFE2JCS67    | 2018 | VT    | DP   | 4311  | FL      | 9/1/2017   | 9/12/2017  |
| 413554 | 4UZACHFE4JCKC091  | 2018 | VT    | DP   | 4007  | FL      | 2/8/2018   | 2/16/2018  |
| 413557 | 4UZFCHFE1JCKC093  | 2018 | VT    | DP   | 4009  | FL      | 2/2/2018   | 2/12/2018  |
| 413561 | 4UZFCHFE1JCKC6914 | 2018 | VT    | DP   | 4326  | FL      | 2/14/2018  | 2/21/2018  |
| 413568 | 4UZFCHFE5JCKA3671 | 2018 | VT    | DP   | 4369  | FL      | 1/17/2018  | 1/24/2018  |
| 413573 | 4UZACHFC9KCKD1256 | 2018 | VT    | DP   | 3412  | FL      | 2/15/2018  | 2/22/2018  |
| 413574 | 4UZACHFE1JCKC008  | 2018 | VT    | DP   | 4007  | FL      | 2/5/2018   | 2/14/2018  |
| 413577 | 4UZACHFE1KCKD1253 | 2018 | VT    | DP   | 4009  | FL      | 2/15/2018  | 2/22/2018  |
| 413578 | 4UZACHFC8JCJ362   | 2018 | VT    | DP   | 3407  | FL      | 8/15/2017  | 8/22/2017  |
| 413578 | 4UZACHFC8JCJU9957 | 2018 | VT    | DP   | 3436  | FL      | 9/11/2017  | 9/18/2017  |
| 413580 | 4UZACHFC4JCJX0532 | 2018 | VT    | DP   | 3412  | FL      | 10/4/2017  | 10/12/2017 |
| 413581 | 4UZACHFC2JCJX0531 | 2018 | VT    | DP   | 3412  | FL      | 9/22/2017  | 10/2/2017  |
| 413582 | 4UZACHFC3JCJX3633 | 2018 | VT    | DP   | 3412  | FL      | 10/18/2017 | 10/26/2017 |
| 413583 | 4UZACHFC2JCJX3638 | 2018 | VT    | DP   | 3407  | FL      | 11/10/2017 | 11/20/2017 |
| 413584 | 4UZACHFC5JCJX3634 | 2018 | VT    | DP   | 3407  | FL      | 10/18/2017 | 10/26/2017 |
| 413585 | 4UZACHFC7JCJX3635 | 2018 | VT    | DP   | 3436  | FL      | 10/19/2017 | 10/27/2017 |
| 413586 | 4UZACHFC9JCJX3636 | 2018 | VT    | DP   | 3436  | FL      | 10/26/2017 | 11/3/2017  |
| 413587 | 4UZACHFC3JCJU4827 | 2018 | VT    | DP   | 3709  | FL      | 10/27/2017 | 11/6/2017  |
| 413588 | 4UZACHFC7JCJT8397 | 2018 | VT    | DP   | 3715  | FL      | 10/30/2017 | 11/7/2017  |
| 413589 | 4UZACHFC1JCJY2489 | 2018 | VT    | DP   | 3715  | FL      | 11/9/2017  | 11/17/2017 |
| 413590 | 4UZACHFC2JCJU6665 | 2018 | VT    | DP   | 3715  | FL      | 11/9/2017  | 11/16/2017 |
| 413591 | 4UZACHFC0JCJY4055 | 2018 | VT    | DP   | 3709  | FL      | 11/10/2017 | 11/20/2017 |
| 413592 | 4UZACHFC2JCJY4056 | 2018 | VT    | DP   | 3709  | FL      | 11/13/2017 | 11/21/2017 |
| 413593 | 4UZFCHFE3JCJX9200 | 2018 | VT    | DP   | 4037  | FL      | 11/2/2017  | 11/9/2017  |
| 413594 | 4UZFCHFE7JCJX7045 | 2018 | VT    | DP   | 4037  | FL      | 10/31/2017 | 11/8/2017  |
| 413595 | 4UZFCHFE5JCJY4060 | 2018 | VT    | DP   | 4037  | FL      | 11/13/2017 | 11/21/2017 |
| 413596 | 4UZFCHFE9JCJY2490 | 2018 | VT    | DP   | 4037  | FL      | 11/8/2017  | 11/16/2017 |
| 413597 | 4UZFCHFE5JCJX9201 | 2018 | VT    | DP   | 4037  | FL      | 11/8/2017  | 11/16/2017 |
| 413598 | 4UZFCHFE2JCJY2492 | 2018 | VT    | DP   | 4002  | FL      | 11/14/2017 | 11/21/2017 |
| 413599 | 4UZFCHFE9JCJY4059 | 2018 | VT    | DP   | 4046  | FL      | 11/14/2017 | 11/22/2017 |
| 413600 | 4UZFCHFE4JCJY9444 | 2018 | VT    | DP   | 4046  | FL      | 11/22/2017 | 12/4/2017  |
| 413601 | 4UZFCHFE0JCJY2491 | 2018 | VT    | DP   | 4002  | FL      | 11/6/2017  | 11/14/2017 |
| 413602 | 4UZFCHFE0JCJX9199 | 2018 | VT    | DP   | 4049  | FL      | 11/1/2017  | 11/9/2017  |
| 413603 | 4UZFCHFE3JCJX9262 | 2018 | VT    | DP   | 4326  | FL      | 10/19/2017 | 10/27/2017 |

Terminated 1.12.22  
Replaced by  
DTNA FL 912  
NHTSA # 21V921

| Prod#  | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|--------|-------------------|------|-------|------|-------|---------|------------|------------|
| 413604 | 4UZFCHFE4JCJX7049 | 2018 | VT    | DP   | 4326  | FL      | 11/1/2017  | 11/9/2017  |
| 413605 | 4UZFCHFE2JCJX7048 | 2018 | VT    | DP   | 4310  | FL      | 10/23/2017 | 11/1/2017  |
| 413606 | 4UZFCHFE1JCJY7201 | 2018 | VT    | DP   | 4310  | FL      | 11/3/2017  | 11/8/2017  |
| 413607 | 4UZFCHFE3JCJY453  | 2018 | VT    | DP   | 4308  | FL      | 11/15/2017 | 11/27/2017 |
| 413608 | 4UZFCHFE6JCJY294  | 2018 | VT    | DP   | 4308  | FL      | 11/6/2017  | 11/14/2017 |
| 413609 | 4UZFCHFE4JCJY2495 | 2018 | VT    | DP   | 4369  | FL      | 11/3/2017  | 11/15/2017 |
| 413610 | 4UZFCHFE9JCJX9265 | 2018 | VT    | DP   | 4369  | FL      | 11/15/2017 | 11/22/2017 |
| 413611 | 4UZFCHFE8JCJY2495 | 2018 | VT    | DP   | 4369  | FL      | 11/22/2017 | 12/4/2017  |
| 413612 | 4UZFCHFE9JCJY4062 | 2018 | VT    | DP   | 4369  | FL      | 11/15/2017 | 11/27/2017 |
| 413613 | 4UZFCHFE9JCJX9264 | 2018 | VT    | DP   | 4369  | FL      | 11/7/2017  | 11/15/2017 |
| 413614 | 4UZFCHFE9JCJX9265 | 2018 | VT    | DP   | 4369  | FL      | 11/2/2017  | 11/10/2017 |
| 413615 | 4UZFCHFE1JCJX3640 | 2018 | VT    | DP   | 4311  | FL      | 10/26/2017 | 11/3/2017  |
| 413616 | 4UZFCHFE9JCJX0534 | 2018 | VT    | DP   | 4311  | FL      | 10/17/2017 | 10/25/2017 |
| 413634 | 4UZFCHFE9KCKD5587 | 2018 | VT    | DP   | 4037  | FL      | 2/21/2018  | 3/1/2018   |
| 413639 | 4UZACHFC5JCJY3640 | 2018 | VT    | DP   | 3709  | FL      | 2/25/2018  | 10/3/2017  |
| 413640 | 4UZACHFC2KCKD5584 | 2018 | VT    | DP   | 3436  | FL      | 2/28/2018  | 3/7/2018   |
| 413641 | 4UZACHFC9KCKD5584 | 2018 | VT    | DP   | 3709  | FL      | 2/27/2018  | 3/6/2018   |
| 413649 | 4UZFCHFE9KCKD5590 | 2018 | VT    | DP   | 4369  | FL      | 2/23/2018  | 3/2/2018   |
| 413653 | 4UZFCHFE8KCKD9162 | 2018 | VT    | DP   | 4310  | FL      | 3/13/2018  | 3/20/2018  |
| 413654 | 4UZFCHFE9KCKD1264 | 2018 | VT    | DP   | 4310  | FL      | 2/15/2018  | 2/22/2018  |
| 413655 | 4UZACHFC9KCKD5584 | 2018 | VT    | DP   | 3709  | FL      | 3/1/2018   | 3/12/2018  |
| 413656 | 4UZACHFC9KCKD5584 | 2018 | VT    | DP   | 3709  | FL      | 3/6/2018   | 3/13/2018  |
| 413660 | 4UZACHFC2KCKD5584 | 2018 | VT    | DP   | 3407  | FL      | 4/30/2018  | 5/7/2018   |
| 413671 | 4UZACHFC4KCKN3282 | 2018 | VT    | DP   | 3407  | FL      | 5/1/2018   | 5/8/2018   |
| 413672 | 4UZACHFCXKCKM3288 | 2018 | VT    | DP   | 3407  | FL      | 5/9/2018   | 5/17/2018  |
| 413673 | 4UZACHFC0KCKN3280 | 2018 | VT    | DP   | 3412  | FL      | 5/14/2018  | 5/22/2018  |
| 413674 | 4UZACHFC0KCKD5583 | 2018 | VT    | DP   | 3412  | FL      | 3/13/2018  | 3/21/2018  |
| 413675 | 4UZACHFC7KCKL9375 | 2018 | VT    | DP   | 3412  | FL      | 5/1/2018   | 5/9/2018   |
| 413676 | 4UZACHFC8KCKK2665 | 2018 | VT    | DP   | 3436  | FL      | 4/25/2018  | 5/3/2018   |
| 413677 | 4UZACHFC8KCKM9882 | 2018 | VT    | DP   | 3436  | FL      | 5/9/2018   | 5/17/2018  |
| 413678 | 4UZACHFC5KCKF8616 | 2018 | VT    | DP   | 3436  | FL      | 4/16/2018  | 4/24/2018  |
| 413680 | 4UZACHFC1KCKM3289 | 2018 | VT    | DP   | 3709  | FL      | 5/2/2018   | 5/11/2018  |
| 413681 | 4UZACHFC8KCKJ5747 | 2018 | VT    | DP   | 3709  | FL      | 5/2/2018   | 5/9/2018   |
| 413682 | 4UZACHFC8KCKM3290 | 2018 | VT    | DP   | 3715  | FL      | 5/16/2018  | 5/24/2018  |
| 413683 | 4UZACHFC5KCKN3288 | 2018 | VT    | DP   | 3715  | FL      | 5/9/2018   | 5/18/2018  |
| 413684 | 4UZACHFC9KCKE8400 | 2018 | VT    | DP   | 3715  | FL      | 3/14/2018  | 3/21/2018  |
| 413685 | 4UZFCHFE5KCKF4377 | 2018 | VT    | DP   | 4369  | FL      | 3/20/2018  | 3/27/2018  |
| 413686 | 4UZFCHFE9KCKF4379 | 2018 | VT    | DP   | 4369  | FL      | 3/27/2018  | 4/5/2018   |
| 413688 | 4UZFCHFE1KCKH4402 | 2018 | VT    | DP   | 4369  | FL      | 4/26/2018  | 5/3/2018   |
| 413689 | 4UZFCHFE2KCKM9884 | 2018 | VT    | DP   | 4369  | FL      | 5/3/2018   | 5/11/2018  |
| 413690 | 4UZFCHFE6KCKN3291 | 2018 | VT    | DP   | 4369  | FL      | 5/25/2018  | 6/4/2018   |
| 413693 | 4UZACHFC5JCJT8396 | 2018 | VT    | DP   | 3709  | FL      | 11/7/2017  | 11/15/2017 |
| 413694 | 4UZFCHFEXKCKD9163 | 2018 | VT    | DP   | 4369  | FL      | 3/7/2018   | 3/15/2018  |
| 413695 | 4UZFCHFEXKCKM3296 | 2018 | VT    | DP   | 4369  | FL      | 5/11/2018  | 5/18/2018  |
| 413696 | 4UZFCHFE7KCKD7998 | 2018 | VT    | DP   | 4369  | FL      | 3/14/2018  | 3/22/2018  |
| 413697 | 4UZACHFC9KCKJ5742 | 2018 | VT    | DP   | 3407  | FL      | 4/11/2018  | 4/18/2018  |
| 413698 | 4UZACHFC4JCJY4057 | 2018 | VT    | DP   | 3715  | FL      | 11/16/2017 | 11/28/2017 |
| 413699 | 4UZFCHFE2KCKD1266 | 2018 | VT    | DP   | 4308  | FL      | 2/16/2018  | 2/23/2018  |

| Prod#  | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|--------|-------------------|------|-------|------|-------|---------|------------|------------|
| 413700 | 4UZFCHFE5JCJZ9688 | 2018 | VT    | DP   | 4326  | FL      | 1/9/2018   | 1/16/2018  |
| 413705 | 4UZACHFCXJCJV3623 | 2018 | VT    | DP   | 3715  | FL      | 8/31/2017  | 9/11/2017  |
| 413708 | 4UZFCHFE4KCKD9160 | 2018 | VT    | DP   | 4369  | FL      | 3/21/2018  | 3/28/2018  |
| 413712 | 4UZFCHFE9JCKW50   | 2018 | VT    | DP   | 3412  | FL      | 9/18/2017  | 9/26/2017  |
| 413714 | 4UZACHFC2KCKD59   | 2018 | VT    | DP   | 4311  | FL      | 3/21/2018  | 3/28/2018  |
| 413715 | 4UZFCHFE4KCKD9157 | 2018 | VT    | DP   | 4002  | FL      | 3/29/2018  | 4/6/2018   |
| 413717 | 4UZFCHFE5JCJX3639 | 2018 | VT    | DP   | 4311  | FL      | 10/24/2017 | 11/1/2017  |
| 413719 | 4UZFCHFE7KCKF4381 | 2018 | VT    | DP   | 4326  | FL      | 3/29/2018  | 4/9/2018   |
| 413720 | 4UZFCHFEXJC32527  | 2018 | VT    | DP   | 4037  | FL      | 1/16/2018  | 1/23/2018  |
| 413721 | 4UZFCHFE1JCJ8723  | 2018 | VT    | DP   | 4369  | FL      | 10/9/2017  | 10/17/2017 |
| 413722 | 4UZACHFC0KCK9110  | 2018 | VT    | DP   | 3412  | FL      | 3/9/2018   | 3/16/2018  |
| 413725 | 4UZACHFC9KCKH4396 | 2018 | VT    | DP   | 3407  | FL      | 4/26/2018  | 5/4/2018   |
| 413726 | 4UZACHFC8JCJY2487 | 2018 | VT    | DP   | 3412  | FL      | 12/4/2017  | 12/11/2017 |
| 413732 | 4UZFCHFE3JCKC1005 | 2018 | VT    | DP   | 4037  | FL      | 1/29/2018  | 2/5/2018   |
| 413733 | 4UZACHFC6KCKE8409 | 2018 | VT    | DP   | 3715  | FL      | 4/5/2018   | 4/12/2018  |
| 413734 | 4UZACHFC4KCKJ574  | 2018 | VT    | DP   | 3709  | FL      | 4/11/2018  | 4/18/2018  |
| 413735 | 4UZFCHFE1KCK207   | 2018 | VT    | DP   | 4037  | FL      | 4/17/2018  | 4/24/2018  |
| 413736 | 4UZACHFC8KCKM3287 | 2018 | VT    | DP   | 3436  | FL      | 5/3/2018   | 5/14/2018  |
| 413738 | 4UZACHFC0JCKA3666 | 2018 | VT    | DP   | 3436  | FL      | 12/15/2017 | 1/9/2018   |
| 413740 | 4UZACHFC0KCKD1257 | 2018 | VT    | DP   | 3412  | FL      | 2/16/2018  | 2/23/2018  |
| 413742 | 4UZACHFC0JCJZ3552 | 2018 | VT    | DP   | 3709  | FL      | 11/30/2017 | 12/3/2017  |
| 413743 | 4UZACHFC7KCKD1221 | 2018 | VT    | DP   | 3407  | FL      | 2/19/2018  | 2/26/2018  |
| 413744 | 4UZACHFC3KCK1126  | 2018 | VT    | DP   | 4049  | FL      | 2/12/2018  | 2/19/2018  |
| 413747 | 4UZACHFC3JCKA8960 | 2018 | VT    | DP   | 3412  | FL      | 1/15/2018  | 1/23/2018  |
| 413750 | 4UZFCHFE5JCKA8966 | 2018 | VT    | DP   | 4369  | FL      | 1/26/2018  | 2/2/2018   |
| 413757 | 4UZFCHFE5KCKH4399 | 2018 | VT    | DP   | 4369  | FL      | 4/5/2018   | 4/12/2018  |
| 413760 | 4UZFCHFE7KCKL1204 | 2018 | VT    | DP   | 4049  | FL      | 4/18/2018  | 4/26/2018  |
| 413761 | 4UZFCHFEXKCKF8618 | 2018 | VT    | DP   | 4037  | FL      | 4/2/2018   | 4/9/2018   |
| 413762 | 4UZFCHFE5KCKD7997 | 2018 | VT    | DP   | 4369  | FL      | 3/8/2018   | 3/15/2018  |
| 413763 | 4UZFCHFE1KCKE8401 | 2018 | VT    | DP   | 4369  | FL      | 3/21/2018  | 3/29/2018  |
| 413770 | 4UZACHFC9KCKD7994 | 2018 | VT    | DP   | 3412  | FL      | 3/12/2018  | 3/19/2018  |
| 413771 | 4UZFCHFE7JCJZ9689 | 2018 | VT    | DP   | 4369  | FL      | 1/15/2018  | 1/22/2018  |
| 413772 | 4UZFCHFE9KCKL1205 | 2018 | VT    | DP   | 4002  | FL      | 4/19/2018  | 4/26/2018  |
| 413775 | 4UZFCHFE4KCKN3290 | 2018 | VT    | DP   | 4037  | FL      | 5/14/2018  | 5/21/2018  |
| 413777 | 4UZFCHFE6KCKD9158 | 2018 | VT    | DP   | 4369  | FL      | 3/8/2018   | 3/15/2018  |
| 413783 | 4UZACHFC7KCKJ5741 | 2018 | VT    | DP   | 3436  | FL      | 5/4/2018   | 5/14/2018  |
| 413784 | 4UZACHFC2KCKH4398 | 2018 | VT    | DP   | 3709  | FL      | 4/6/2018   | 4/13/2018  |
| 413786 | 4UZACHFC7JCKB2526 | 2018 | VT    | DP   | 3407  | FL      | 2/12/2018  | 2/20/2018  |
| 413788 | 4UZFCHFE6JCKC6912 | 2018 | VT    | DP   | 4037  | FL      | 2/6/2018   | 2/13/2018  |
| 413789 | 4UZACHFC5JCKC6909 | 2018 | VT    | DP   | 3709  | FL      | 2/12/2018  | 2/19/2018  |
| 413790 | 4UZACHFC5KCKD9175 | 2018 | VT    | DP   | 3715  | FL      | 3/26/2018  | 4/3/2018   |
| 413793 | 4UZFCHFE1JCKB2528 | 2018 | VT    | DP   | 4037  | FL      | 1/22/2018  | 1/29/2018  |
| 413794 | 4UZACHFC1JCJZ5551 | 2018 | VT    | DP   | 3407  | FL      | 12/4/2017  | 12/12/2017 |
| 413796 | 4UZFCHFE5KCKD1262 | 2018 | VT    | DP   | 4037  | FL      | 2/20/2018  | 2/28/2018  |
| 413797 | 4UZFCHFE1JCJZ9686 | 2018 | VT    | DP   | 4037  | FL      | 12/20/2017 | 1/12/2018  |
| 413804 | 4UZFCHFE3KCKD7996 | 2018 | VT    | DP   | 4002  | FL      | 3/26/2018  | 4/4/2018   |
| 413807 | 4UZFCHFE1KCKD1260 | 2018 | VT    | DP   | 4037  | FL      | 3/1/2018   | 3/9/2018   |
| 413808 | 4UZFCHFEXJCJZ5555 | 2018 | VT    | DP   | 4369  | FL      | 1/8/2018   | 1/16/2018  |

Terminated 1.12.22  
Replaced by  
DTNA FL 912  
NHTSA # 21V921

| Prod#  | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off   |
|--------|-------------------|------|-------|------|-------|---------|------------|------------|
| 413809 | 4UZFCHFE3JCKB2529 | 2018 | VT    | DP   | 4369  | FL      | 1/26/2018  | 2/2/2018   |
| 413810 | 4UZFCHFE8JCKC6913 | 2018 | VT    | DP   | 4369  | FL      | 2/9/2018   | 2/16/2018  |
| 413811 | 4UZFCHFE3KCKH4403 | 2018 | VT    | DP   | 4369  | FL      | 3/18/2018  | 5/5/2018   |
| 413812 | 4UZFCHFE3KCKD16   | 2018 | VT    | DP   | 4369  | FL      | 3/16/2018  | 3/23/2018  |
| 413813 | 4UZFCHFE7KCKF37   | 2018 | VT    | DP   | 4369  | FL      | 3/23/2018  | 4/2/2018   |
| 413814 | 4UZFCHFE2KCKD9156 | 2018 | VT    | DP   | 4037  | FL      | 4/6/2018   | 4/15/2018  |
| 413815 | 4UZFCHFE5KCKL1203 | 2018 | VT    | DP   | 4037  | FL      | 4/19/2018  | 4/27/2018  |
| 413816 | 4UZFCHFE3KCKL9381 | 2018 | VT    | DP   | 4037  | FL      | 5/4/2018   | 5/14/2018  |
| 413817 | 4UZFCHFE0KCKM3291 | 2018 | VT    | DP   | 4367  | FL      | 5/14/2018  | 5/21/2018  |
| 413818 | 4UZFCHFE0KCKM329  | 2018 | VT    | DP   | 4367  | FL      | 5/18/2018  | 5/25/2018  |
| 413819 | 4UZACHFE7KCKF5219 | 2018 | VT    | DP   | 3715  | FL      | 5/11/2018  | 5/18/2018  |
| 413821 | 4UZACHFE0KCKJ2511 | 2019 | VT    | DP   | 4348  | FL      | 11/20/2017 | 11/30/2017 |
| 413822 | 4UZFCHFE4KCKK2668 | 2018 | VT    | DP   | 4037  | FL      | 4/12/2018  | 4/19/2018  |
| 413823 | 4UZACHFC4KCKE8398 | 2018 | VT    | DP   | 3436  | FL      | 3/16/2018  | 3/26/2018  |
| 413824 | 4UZACHFC2KCKE8397 | 2018 | VT    | DP   | 3436  | FL      | 4/27/2018  | 4/4/2018   |
| 413825 | 4UZFCHFE1KCKB133  | 2018 | VT    | DP   | 4360  | FL      | 2/5/2018   | 2/13/2018  |
| 413826 | 4UZFCHFE3KCKK1336 | 2018 | VT    | DP   | 4037  | FL      | 1/29/2018  | 2/6/2018   |
| 413827 | 4UZACHFC9KCKD5582 | 2018 | VT    | DP   | 3412  | FL      | 2/23/2018  | 3/5/2018   |
| 413831 | 4UZFCHFE2JCJY4064 | 2018 | VT    | DP   | 4311  | FL      | 1/24/2018  | 1/31/2018  |
| 413834 | 4UZACHFC5KCKJ5740 | 2018 | VT    | DP   | 3407  | FL      | 4/13/2018  | 4/23/2018  |
| 413835 | 4UZACHFC3KCKJ539  | 2018 | VT    | DP   | 3407  | FL      | 3/19/2018  | 3/19/2018  |
| 413836 | 4UZFCHFE3JCKA6105 | 2018 | VT    | DP   | 4039  | FL      | 1/12/2018  | 1/22/2018  |
| 413837 | 4UZACHFCXKCKE861  | 2018 | VT    | DP   | 3436  | FL      | 4/3/2018   | 4/17/2018  |
| 413843 | 4UZFCHFE0KCKL1206 | 2018 | VT    | DP   | 4037  | FL      | 4/23/2018  | 4/30/2018  |
| 413844 | 4UZACHFC3KCKN3287 | 2018 | VT    | DP   | 3709  | FL      | 5/11/2018  | 5/18/2018  |
| 413845 | 4UZFCHFE3KCKL9378 | 2018 | VT    | DP   | 4002  | FL      | 4/23/2018  | 4/30/2018  |
| 413846 | 4UZACHFC4KCKD5585 | 2018 | VT    | DP   | 3436  | FL      | 3/6/2018   | 3/14/2018  |
| 413847 | 4UZFCHFEXKCKF8621 | 2018 | VT    | DP   | 4311  | FL      | 5/24/2018  | 6/1/2018   |
| 413848 | 4UZACHFCXJCJY2488 | 2018 | VT    | DP   | 3715  | FL      | 2/6/2018   | 2/14/2018  |
| 413849 | 4UZFCHFE5KCKF4380 | 2018 | VT    | DP   | 4369  | FL      | 3/28/2018  | 4/5/2018   |
| 413850 | 4UZFCHFE8KCKM3295 | 2018 | VT    | DP   | 4369  | FL      | 5/7/2018   | 5/15/2018  |
| 413852 | 4UZACHFC6KCKM3286 | 2018 | VT    | DP   | 3407  | FL      | 5/8/2018   | 5/16/2018  |
| 413855 | 4UZACHFC7KCJY2515 | 2019 | VT    | DP   | 3709  | FL      | 2/6/2018   | 2/14/2018  |
| 413857 | 4UZACHFC4KCKM3285 | 2018 | VT    | DP   | 3407  | FL      | 5/21/2018  | 5/30/2018  |
| 413858 | 4UZFCHFE0KCKD5591 | 2018 | VT    | DP   | 4369  | FL      | 2/26/2018  | 3/5/2018   |
| 413859 | 4UZFCHFE4KCKD1267 | 2018 | VT    | DP   | 4369  | FL      | 2/21/2018  | 2/28/2018  |
| 413860 | 4UZFCHFE8KCKN3292 | 2018 | VT    | DP   | 4369  | FL      | 5/14/2018  | 5/21/2018  |
| 413861 | 4UZACHFC4KCKN3279 | 2018 | VT    | DP   | 3407  | FL      | 5/22/2018  | 5/30/2018  |
| 413862 | 4UZACHFC9KCKL1200 | 2018 | VT    | DP   | 3412  | FL      | 5/22/2018  | 5/31/2018  |
| 413864 | 4UZACHFC1KCKF8614 | 2018 | VT    | DP   | 3407  | FL      | 4/25/2018  | 5/2/2018   |
| 413865 | 4UZFCHFEXKCKH4401 | 2018 | VT    | DP   | 4369  | FL      | 4/17/2018  | 4/25/2018  |
| 413866 | 4UZFCHFE5KCKL9379 | 2018 | VT    | DP   | 4037  | FL      | 5/25/2018  | 6/5/2018   |
| 413867 | 4UZACHFC0KCKL9377 | 2018 | VT    | DP   | 3709  | FL      | 4/27/2018  | 5/7/2018   |
| 413868 | 4UZACHFC4KCJY2519 | 2019 | VT    | DP   | 3426  | FL      | 2/22/2018  | 3/1/2018   |
| 413870 | 4UZFCHFE1KCKF8619 | 2018 | VT    | DP   | 4311  | FL      | 4/12/2018  | 4/19/2018  |
| 413871 | 4UZACHFC8KCKP0957 | 2018 | VT    | DP   | 3709  | FL      | 5/29/2018  | 6/6/2018   |
| 413872 | 4UZFCHFE8KCKF8620 | 2018 | VT    | DP   | 4311  | FL      | 5/8/2018   | 5/16/2018  |
| 413873 | 4UZFCHFE0KCKP0958 | 2018 | VT    | DP   | 4037  | FL      | 5/22/2018  | 5/31/2018  |

Terminated 1.12.22  
Replaced by  
DTNA FL 912  
NHTSA # 21V 921

| Prod#          | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off  |
|----------------|-------------------|------|-------|------|-------|---------|------------|-----------|
| 413876         | 4UZFCHFE2KCKD5589 | 2018 | VT    | DP   | 4037  | FL      | 3/19/2018  | 3/27/2018 |
| 413878         | 4UZACHFC6KCKJ5746 | 2018 | VT    | DP   | 3715  | FL      | 4/9/2018   | 4/16/2018 |
| 413879         | 4UZFCHFE8KCKH4400 | 2018 | VT    | DP   | 4308  | FL      | 4/16/2018  | 4/23/2018 |
| 413881         | 4UZFCHFE0KCKF339  | 2018 | VT    | DP   | 3709  | FL      | 4/3/2018   | 4/11/2018 |
| 413882         | 4UZACHFC0KCKF37   | 2018 | VT    | DP   | 3407  | FL      | 3/22/2018  | 3/29/2018 |
| 413884         | 4UZACHFC7KCKF8617 | 2018 | VT    | DP   | 3407  | FL      | 4/9/2018   | 4/16/2018 |
| 413885         | 4UZACHFC2KCKJ5744 | 2018 | VT    | DP   | 3436  | FL      | 4/18/2018  | 4/25/2018 |
| 413890         | 4UZFCHFE1KCKL9380 | 2018 | VT    | DP   | 4037  | FL      | 5/3/2018   | 5/11/2018 |
| 413891         | 4UZFCHFE4KCKM9885 | 2018 | VT    | DP   | 4369  | FL      | 5/16/2018  | 5/23/2018 |
| 413892         | 4UZFCHFE0KCKH549  | 2018 | VT    | DP   | 4369  | FL      | 5/15/2018  | 5/23/2018 |
| 413893         | 4UZFCHFE0KCKN3214 | 2018 | VT    | DP   | 4369  | FL      | 4/30/2018  | 5/7/2018  |
| 413896         | 4UZACHFC0KCKL1201 | 2018 | VT    | DP   | 3407  | FL      | 5/31/2018  | 6/8/2018  |
| 413929         | 4UZACHFC4KCKM9880 | 2018 | VT    | DP   | 3709  | FL      | 5/23/2018  | 6/1/2018  |
| 413964         | 4UZACHFC6KCKN3283 | 2019 | VT    | DP   | 3412  | FL      | 8/8/2018   | 8/15/2018 |
| 413975         | 4UZACHFC029JCT47  | 2019 | VT    | DP   | 3709  | FL      | 5/15/2019  | 5/24/2019 |
| Canadian Units |                   |      |       |      |       |         |            |           |
| Prod#          | VIN Number        | Year | Brand | Type | Floor | Chassis | Date In    | Date Off  |
| 413357         | 4UZFCHFE5JCJS8457 | 2018 | VT    | DP   | 4369  | FL      | 6/28/2017  | 7/14/2017 |
| 413372         | 4UZFCHFE7JCJT1845 | 2018 | VT    | DP   | 4037  | FL      | 7/27/2017  | 8/4/2017  |
| 413373         | 4UZFCHFE7JCJS8458 | 2018 | VT    | DP   | 4308  | FL      | 6/28/2017  | 7/14/2017 |
| 413374         | 4UZFCHFE0CJU1962  | 2018 | VT    | DP   | 4308  | FL      | 8/7/2017   | 8/14/2017 |
| 413431         | 4UZFCHFE0JCJT851  | 2018 | VT    | DP   | 4037  | FL      | 7/28/2017  | 8/7/2017  |
| 413521         | 4UZACHFC0JCJ1363  | 2018 | VT    | DP   | 3412  | FL      | 8/16/2017  | 9/7/2017  |
| 413551         | 4UZACHFC0JCJV8720 | 2018 | VT    | DP   | 3436  | FL      | 9/14/2017  | 9/22/2017 |
| 413579         | 4UZFCHFE6JCJZ5553 | 2018 | VT    | DP   | 4037  | FL      | 12/15/2017 | 1/8/2018  |
| 413709         | 4UZFCHFE6KCKK2669 | 2018 | VT    | DP   | 4037  | FL      | 4/5/2018   | 4/12/2018 |
| 413710         | 4UZFCHFE3KCKE8402 | 2018 | VT    | DP   | 4369  | FL      | 3/21/2018  | 3/28/2018 |
| 413737         | 4UZFCHFE0KCKM9883 | 2018 | VT    | DP   | 4037  | FL      | 4/27/2018  | 5/4/2018  |
| 413768         | 4UZFCHFE8KCKD9159 | 2018 | VT    | DP   | 4369  | FL      | 3/15/2018  | 3/22/2018 |
| 413769         | 4UZFCHFE0KCKD5588 | 2018 | VT    | DP   | 4037  | FL      | 3/16/2018  | 3/23/2018 |
| 413795         | 4UZFCHFE0KCKD1265 | 2018 | VT    | DP   | 4369  | FL      | 2/19/2018  | 2/26/2018 |
| 413863         | 4UZACHFC0KCKJ5743 | 2018 | VT    | DP   | 3436  | FL      | 4/6/2018   | 4/13/2018 |
| 413877         | 4UZFCHFE2KCKK2670 | 2018 | VT    | DP   | 4037  | FL      | 4/13/2018  | 4/20/2018 |
| 413880         | 4UZFCHFEXKCKN3293 | 2018 | VT    | DP   | 4311  | FL      | 5/24/2018  | 6/4/2018  |

Terminated 1.12.22  
Replaced by  
DTNA FL 912  
NHTSA # 21V921