



Technical Service Bulletin

BULLETIN INFORMATION													
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #										
1 / 5 / 06	All	All Spartan chassis w/ Air Brakes	257										
SYSTEMS AFFECTED													
<table border="0"><tr><td><input type="checkbox"/> Air Conditioning & Heating</td><td><input type="checkbox"/> Electrical Components</td></tr><tr><td><input type="checkbox"/> Appliances & Accessories</td><td><input type="checkbox"/> Exterior Components</td></tr><tr><td><input type="checkbox"/> Cabinets & Furniture</td><td><input type="checkbox"/> Interior Components</td></tr><tr><td><input checked="" type="checkbox"/> Chassis Components</td><td><input type="checkbox"/> Plumbing & Bath Components</td></tr><tr><td><input type="checkbox"/> Construction Components</td><td><input type="checkbox"/> Windows, Awnings, Vents, & Doors</td></tr></table>				<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components	<input type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components	<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components	<input checked="" type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components	<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors
<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components												
<input type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components												
<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components												
<input checked="" type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components												
<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors												
<p align="center">PROBLEM DESCRIPTION</p> <p>Winter reminder to make sure the “Dust Plug” is properly installed in the Haldex Brake Chamber to prevent corrosion and premature failure.</p>													
<p align="center">RECOMMENDED SOLUTION</p> <p>Make sure all dust plugs are in place on the Haldex Brake Chambers. Follow attached Spartan instructions. If you have additional questions regarding this, please contact Spartan Custom Chassis at 1-800-722-3025.</p>													



SPARTAN CHASSIS, INC.

www.spartanchassis.com

Dear Valued Spartan Chassis Customer,

re: Maintenance Check Point

As you know, we are quickly approaching the winter weather season which means snow, ice and more importantly, road salt for those of you traveling in such climates. We at Spartan Chassis wish to insure the superior experience you have enjoyed with our product this summer extends through the winter and beyond.

One step we wish you would take to preserve the performance and function of your vehicle brake system is to inspect the Haldex brake chambers for the presence and proper installation of the dust plugs. Dislodged or missing dust plugs can lead to corrosion in these chambers when exposed to road surface traction treatments such as road salt.

Should you need to purchase replacement dust plugs you should contact your preferred service center (request part # RPT 1) or contact Spartan Chassis at 800-722-3025 for the service center nearest you.

We at Spartan Chassis, Inc. wish you safe and enjoyable winter traveling.



Properly installed Dust Plug in Haldex Brake Chamber

10/24/05

1165 REYNOLDS RD ♦ CHARLOTTE, MICHIGAN ♦ 48813
TELEPHONE: (517)-543-6400