

Newmar Corporation

Warranty Department

Technical Service Bulletin																			
Date Issued		Model Year(s) Affected		Model(s) Affected		TSB #													
12/13/2006		2007		Diesel Pusher		308													
Brand						Type													
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	All	<input type="checkbox"/>	T T	<input type="checkbox"/>										
		Dutch Star	<input checked="" type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	F W	<input type="checkbox"/>	C A	<input type="checkbox"/>										
		Kountry Star	<input type="checkbox"/>	Essex	<input type="checkbox"/>	D P	<input checked="" type="checkbox"/>	D B	<input type="checkbox"/>										
Scottsdale	<input type="checkbox"/>	Northern Star	<input type="checkbox"/>	London Aire	<input type="checkbox"/>														
<table border="0"><tr><td><input type="checkbox"/> Air Conditioning & Heating</td><td><input type="checkbox"/> Electrical Components</td></tr><tr><td><input checked="" type="checkbox"/> Appliances & Accessories</td><td><input type="checkbox"/> Exterior Components</td></tr><tr><td><input type="checkbox"/> Cabinets & Furniture</td><td><input type="checkbox"/> Interior Components</td></tr><tr><td><input type="checkbox"/> Chassis Components</td><td><input type="checkbox"/> Plumbing & Bath Components</td></tr><tr><td><input type="checkbox"/> Construction Components</td><td><input type="checkbox"/> Windows, Awnings, Vents, & Doors</td></tr></table>										<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components	<input checked="" type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components	<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components	<input type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components	<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors
<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components																		
<input checked="" type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components																		
<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components																		
<input type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components																		
<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors																		
Description of Problem																			
Navigation system has no audio.																			
Recommended Solution																			
<p>Verify that the system is plugged correctly into the patch cord. The cord needs to be plugged red to white as illustrated in the attached photo. The white one is labeled audio.</p> <p>On the Mountain Aire Diesel Pusher, these wires are located directly behind the back up monitor. They can be accessed by removing the top and side screws without taking the complete panel out.</p> <p>On the Dutch Star Diesel Pusher, the wires are in the overhead left side of the driver behind the navigation computer.</p> <p>Flat rate code: 0467 Time allowed: .5</p> <p>Please feel free to contact your Newmar Warranty Representative if you have additional questions.</p>																			

DEC 13 2006

