

Newmar Corporation Warranty Department

Technical Service Bulletin							
Date Issued		Model Year(s) Affected		Model(s) Affected		TSB #	
1/3/2007		12/2/2005 – 5/16/2006		All Applicable Spartan ME2 Chassis		312	
Brand						Type	
All	☐	American Star	☐	Mountain Aire	☐	All	☐
		Dutch Star	☐	Kountry Aire	☐	F W	☐
All Star	☒	Kountry Star	☐	Essex	☐	D P	☒
Scottsdale	☐	Northern Star	☐	London Aire	☐	D B	☐
☐ Air Conditioning & Heating ☐ Appliances & Accessories ☐ Cabinets & Furniture ☒ Chassis Components ☐ Construction Components ☐ Electrical Components ☐ Exterior Components ☐ Interior Components ☐ Plumbing & Bath Components ☐ Windows, Awnings, Vents, & Doors							
Description of Problem							
Cooling system fill rate is too slow.							
Recommended Solution							
Reroute system fill line. See manufacturer's attached repair directions. Contact manufacturer directly for additional information or instructions.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



Spartan Chassis, Inc.
Customer Service Group

January 2, 2007

Re: Notice of Campaign Service Bulletin: **CSB06-270-001**

Dear Service Manager,

Attached is a copy of campaign service bulletin **CSB06-270-001** which addresses the condition where the cooling system fill rate is too slow. This condition applies to certain Spartan ME2 chassis having a VDM (Vehicle Date of Manufacture) of December 2, 2005 through May 16, 2006.

The correction is to reroute system fill line using kit # S-1768-001.

4 hrs is allowed for this.

If you have any questions, call Spartan's Customer Service Dept. @ 800-393-8861 (Option 2).

Although **this is not a recall**, Spartan Chassis is committed to serving you with your best interests in mind.

Best Regards,

Wayne Ridge

Wayne Ridge
Product Improvement Administrator
Spartan Chassis, Inc.

Should the servicing facility have any billing questions, call Wayne Ridge at 517-543-6400 ext.445



Spartan Chassis, Inc.
Customer Service Group

MH578 Newmar Cooling Population Information

SALES ORDER	DONE	VDM DTE	Date of Sale	Last Name	Name
54601		1/4/2006	2/15/2006	Tupy	Garry Brent
54833		2/2/2006	3/7/2006	McHugh	Craig S
54831		2/2/2006	3/8/2006	Siroin	Eddy C
54887		2/6/2006	3/10/2006	LeBlanc	Kenneth E
54775		1/30/2006	3/24/2006	Earl	Esther M
54974		2/13/2006	3/27/2006	Cormier	Rhoal & Lucienne
54200		1/6/2006	3/30/2006	Pacheco	Larry & Lena O
54830		1/30/2006	4/10/2006	Coldani	Kevin & Jennifer
55182		2/15/2006	4/16/2006	Fox	Randy G
54725		1/17/2006	4/24/2006	Fessler	Aaron & Rita Kimber
55165		2/16/2006	5/1/2006	Jones	Christopher D
54884		2/6/2006	5/29/2006	Bassett	Eric J
54975		2/14/2006	5/30/2006	VanSickle	Christina Y & Jeffery D
55604		3/21/2006	6/7/2006	Vojcek	Rodger D
54199		12/16/2005			
54723		1/10/2006			
54724		1/16/2006			
54772		1/18/2006			
54773		1/19/2006			
54774		1/24/2006			
54776		1/19/2006			
54777		1/25/2006			
54828		1/25/2006			
54829		1/30/2006			
54883		2/2/2006			
54885		2/6/2006			
54886		2/6/2006			
54888		2/6/2006			
54889		2/8/2006			
54890		2/8/2006			
54891		2/8/2006			
54892		2/9/2006			
54973		2/9/2006			
55181		2/15/2006			
55183		2/20/2006			
55284		2/27/2006			
55285		2/27/2006			
55286		2/27/2006			
55287		2/27/2006			
55288		2/28/2006			
55397		3/2/2006			

MH578 Newmar Cooling Population Information

SALES ORDER	DONE	VDM DTE	Date of Sale	Last Name	Name
55398		3/6/2006			
55399		3/7/2006			
55533		3/14/2006			
55534		3/15/2006			
55535		3/16/2006			
55536		3/16/2006			
55537		3/16/2006			
55603		3/20/2006			
55605		3/21/2006			
55606		3/22/2006			
55607		3/22/2006			
55683		3/30/2006			
55684		3/30/2006			
55685		3/30/2006			
56045		4/25/2006			
56046		4/25/2006			
56047		4/25/2006			
56048		4/27/2006			
56049		4/27/2006			
56161		5/3/2006			
56162		5/1/2006			
56163		5/1/2006			
56164		5/4/2006			
56165		5/9/2006			
56272		5/10/2006			
56273		5/11/2006			
56274		5/16/2006			

54832 removed from population - has been fixed per Hank Chen
53846 removed from population - validation at Spartan