

NEWMAR CORPORATION

WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN																		
DATE ISSUED	MODEL YEAR(S) AFFECTED		MODEL(S) AFFECTED		TSB #													
11/4/08	2009 and beyond		MADP, EXDP, KGDB, MADP, DSDP, DADP		358													
BRAND					TYPE													
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Mountain Aire	<input checked="" type="checkbox"/>	All	<input type="checkbox"/>	T T <input type="checkbox"/>										
Cypress	<input type="checkbox"/>	Dutch Star	<input checked="" type="checkbox"/>	Kountry Aire	<input type="checkbox"/>	F W	<input type="checkbox"/>	C A <input type="checkbox"/>										
Northern Star	<input type="checkbox"/>	Kountry Star	<input type="checkbox"/>	Essex	<input checked="" type="checkbox"/>	D P	<input checked="" type="checkbox"/>	D B <input checked="" type="checkbox"/>										
Scottsdale	<input type="checkbox"/>	King Aire	<input checked="" type="checkbox"/>	Dutch Aire	<input checked="" type="checkbox"/>													
All Star ME	<input type="checkbox"/>	Ventana	<input type="checkbox"/>	Bay Star	<input type="checkbox"/>													
<table border="0"><tr><td><input type="checkbox"/> Air Conditioning & Heating</td><td><input checked="" type="checkbox"/> Electrical Components</td></tr><tr><td><input checked="" type="checkbox"/> Appliances & Accessories</td><td><input type="checkbox"/> Exterior Components</td></tr><tr><td><input type="checkbox"/> Cabinets & Furniture</td><td><input type="checkbox"/> Interior Components</td></tr><tr><td><input type="checkbox"/> Chassis Components</td><td><input type="checkbox"/> Plumbing & Bath Components</td></tr><tr><td><input type="checkbox"/> Construction Components</td><td><input type="checkbox"/> Windows, Awnings, Vents, & Doors</td></tr></table>									<input type="checkbox"/> Air Conditioning & Heating	<input checked="" type="checkbox"/> Electrical Components	<input checked="" type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components	<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components	<input type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components	<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors
<input type="checkbox"/> Air Conditioning & Heating	<input checked="" type="checkbox"/> Electrical Components																	
<input checked="" type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components																	
<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components																	
<input type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components																	
<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors																	
DESCRIPTION OF PROBLEM																		
<p>As a safety feature, RVIA Code has mandated that when a unit is equipped with an "Auto Genset Start" feature, the AGS system is required to be disabled when any of the remote "start / stop" switches for the generator are activated. This minimizes the possibility of the generator starting automatically during service or repair work.</p>																		
RECOMMENDED SOLUTION																		
<p>Newmar is installing a module that will clear the settings on an AGS system any time one of the remote switches (dash / bedroom / genset) is activated. This is an OEM installation on NEW units only, and is not retroactive to prior model years.</p> <p>No field service action is required by this TSB; it is for dealer information only. The Owners Guides are being updated to reflect this information as well so retail customers are aware of the new feature.</p>																		

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.