NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN						
DATE ISSUED MODEL YEAR(S) AFFEC		ECTED	MODEL(S) AFFECTED		TSB #	
04/30/2010 All			All Motorized		372	
BRAND				Түре		
AllCypressNorthern StarScottsdaleAll Star ME	American Star Dutch Star Kountry Star King Aire Ventana		Mountain Aire Kountry Aire Essex London Aire Bay Star	X X	All □ FW□ DP⊠	ΤΤ□ CΑ⊠ DΒ⊠
 Air Conditioning & Heating Appliances & Accessories Cabinets & Furniture Chassis Components Construction Components 			 Electrical Components Exterior Components Interior Components Plumbing & Bath Components Windows, Awnings, Vents, & Doors 			
DESCRIPTION OF PROBLEM						
Failed Amsafe seat belts being returned to Newmar for warranty coverage. Recommended Solution						

Please note that when changing out warranty Amsafe seat belts, <u>BOTH</u> the harness strap with clip and the buckle portion will need to be returned.

- The Newmar Part #'s for the seat belts are # 27155 & # 91650.
- Warranty flat rate time is .50
- Flat rate code to be used is 3062

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT



Part # 27155... 3 - point retractable seat belt.



Part # 91650... 3- point retractable seat belt.