

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN																			
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #											
6/6/86		1985-1986			ALL			1											
BRAND					TYPE														
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input type="checkbox"/>	Dutch Star	<input type="checkbox"/>	All	<input type="checkbox"/>										
NewAire	<input type="checkbox"/>	Mountain Aire	<input type="checkbox"/>	Kountry Aire	<input checked="" type="checkbox"/>	London Aire	<input checked="" type="checkbox"/>	T T	<input type="checkbox"/>										
								F W	<input type="checkbox"/>										
								C A	<input checked="" type="checkbox"/>										
								D P	<input type="checkbox"/>										
								D B	<input type="checkbox"/>										
<table border="0"><tr><td><input type="checkbox"/> Air Conditioning & Heating</td><td><input type="checkbox"/> Electrical Components</td></tr><tr><td><input type="checkbox"/> Appliances & Accessories</td><td><input type="checkbox"/> Exterior Components</td></tr><tr><td><input type="checkbox"/> Cabinets & Furniture</td><td><input type="checkbox"/> Interior Components</td></tr><tr><td><input checked="" type="checkbox"/> Chassis Components</td><td><input type="checkbox"/> Plumbing & Bath Components</td></tr><tr><td><input type="checkbox"/> Construction Components</td><td><input type="checkbox"/> Windows, Awnings, Vents, & Doors</td></tr></table>										<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components	<input type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components	<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components	<input checked="" type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components	<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors
<input type="checkbox"/> Air Conditioning & Heating	<input type="checkbox"/> Electrical Components																		
<input type="checkbox"/> Appliances & Accessories	<input type="checkbox"/> Exterior Components																		
<input type="checkbox"/> Cabinets & Furniture	<input type="checkbox"/> Interior Components																		
<input checked="" type="checkbox"/> Chassis Components	<input type="checkbox"/> Plumbing & Bath Components																		
<input type="checkbox"/> Construction Components	<input type="checkbox"/> Windows, Awnings, Vents, & Doors																		
DESCRIPTION OF PROBLEM																			
<p>Servicing and replacement of 105 amp alternator. We have had a number of problems in the field on finding the proper replacement alternator and proper hook –up of these alternators which have resulted in delays in servicing the customer and extensive warranty repair bills.</p>																			
RECOMMENDED SOLUTION																			
<ol style="list-style-type: none">1. Have qualified personnel check alternator with voltage and amp tester to determine a faulty alternator. Do not replace until test has been done.2. Check to see if alternator has an internal or external regulator. If unit has external regulator it will be located on firewall.3. Call Newmar Service Department or Truck and Tractor Electric Inc. at 219.426.7749.																			

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.