

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
12/9/94		1994-1995			All			107	
BRAND					TYPE				
All	<input type="checkbox"/>	American Star	<input type="checkbox"/>	Kountry Star	<input checked="" type="checkbox"/>	Dutch Star	<input type="checkbox"/>	All	<input type="checkbox"/>
NewAir	<input type="checkbox"/>	Mountain Air	<input checked="" type="checkbox"/>	Kountry Air	<input checked="" type="checkbox"/>	London Air	<input type="checkbox"/>	C A	<input checked="" type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating					<input type="checkbox"/> Electrical Components				
<input type="checkbox"/> Appliances & Accessories					<input checked="" type="checkbox"/> Exterior Components				
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components				
<input type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components				
<input type="checkbox"/> Construction Components					<input type="checkbox"/> Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM									
Hoses leaking on HWH leveling jacks.									
RECOMMENDED SOLUTION									
Check for leaks on the short hose that makes the bend right at the jack. If this line is leaking, replace it as soon as possible. Contact Newmar or HWH direct. HWH can be reached at 800-321-3494.									

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.