TECHNICAL SERVICE BULLETIN				
DATE ISSUED MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED	
1/17/96	1996	A	ALL	
Brand			Түре	
All 🛛 American Star 🗖 Kountry Star 🗖		Dutch Star	All 🗖 T	T 🗖 F W 🗖
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖		London Aire 🗖	C A 🗖 D	PD DBD
 Air Conditioning & Heating Electrical Components 				
□ Appliances & Acc	Exterior Co	Exterior Components		
Cabinets & Furnit	□ Interior Co	Interior Components		
Chassis Component	□ Plumbing &	Plumbing & Bath Components		
Construction Com	□ Windows, 2	□ Windows, Awnings, Vents, & Doors		
DESCRIPTION OF PROBLEM Chevrolet chassis switching to 10-year anti-freeze on 1996 units.				
RECOMMENDED SOLUTION				
	reeze on 1996 Chevy chassis. Yo ou have any questions, please co			ze on all 1996

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.