72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN								
DATE ISSUED		MODEL YEAR(S) AFFECTED			Model(s) Affected		TSB#	
12/4/96		1996-1997			ALL		137	
Brand					Түре			
All	■ Americ	can Star 🛚	Kountry Star	Dut	ch Star 🛚	All T	T□ FW□	
NewAire □ Mountain Aire □ Kountry Aire □				Lon	don Aire□	C A □ D	PD DBD	
☐ Air Conditioning & Heating ☐ Electrical Components								
☐ Appliances & Accessories					Exterior Components			
☐ Cabinets & Furniture					Interior Components			
☐ Chassis Components					Plumbing & Bath Components			
	Construction Com	ponents			Windows, A	Awnings, Vents,	& Doors	
DESCRIPTION OF PROBLEM Strings are breaking on the window shades.								
RECOMMENDED SOLUTION								
	te sure that the strincialty Window Cove		ed evenly on both side	es. P	lease see the a	attached instruct	ion sheet from	

72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

SPECIALTY WINDOW COVERINGS 1655 Gateway Ct. Elkhart, Indiana

OPERATING INSTRUCTIONS:

SHADES SHOULD BE OPENED OR CLOSED BY PUSHING THE BOTTOM RAIL UP OR PULLING DOWN WITH THE KNOBS PROVIDED. FOR A DUPLEX (DAY/NIGHT) SHADE OR FREE-FLOATING SHADE, MOVE ONLY ONE RAIL AT A TIME. SHADES SHOULD REMAIN UP WHEN NOT IN USE TO AID IN PLEAT RETENTION. IF TENSION ADJUSTMENTS BECOME NECESSARY, SIMPLY WIND CORDS AROUND CENTER OF THE BOBBIN FASTENER TO TIGHTEN, OR RE-TIE TO LOOSEN. ANY ADJUSTMENTS SHOULD BE MADE EQUALLY ON BOTH CORDS FOR SHADE TO REMAIN LEVEL. RUBBING CORDS WITH PARAFIN WAX (OR CANDLE) WILL HELP TO LENGTHEN THE LIFE OF THE CORDS BY REDUCING FRICTION/FRAYING.

CLEANING INSTRUCTIONS:

DRY BRUSH OR VACUUM ONLY. PLEATED SHADES SHOULD NOT GET WET. USE A DAMP CLOTH WITH MILD SOAP TO REMOVE SMALL SPOTS.