

72185 COUNTY ROAD 3
NAPPANEE IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX. 219.773.2007

TECHNICAL SERVICE BULLETIN

Date Issued
09/24/01

Model Year(s) Affected
1998-CURRENT

Model(s) Affected
ALL

TSB #
148

Brand				Type		
ALL <input checked="" type="radio"/>	American Star <input type="radio"/>	Kountry Star <input type="radio"/>	Dutch Star <input type="radio"/>	All <input checked="" type="radio"/>	TT <input type="radio"/>	FW <input type="radio"/>
	Mountain Aire <input type="radio"/>	Kountry Aire <input type="radio"/>	London Aire <input type="radio"/>	CA <input type="radio"/>	DP <input type="radio"/>	DB <input type="radio"/>

- ☐ Air Conditioning & Heating
- ☐ Appliances & Accessories
- ☐ Cabinets & Furniture
- ☒ Chassis Components
- ☐ Construction Components

- ☐ Electrical Components
- ☐ Exterior Components
- ☐ Interior Components
- ☐ Plumbing & Bath Components
- ☐ Windows, Awnings, Vents & Doors

Description of Problem

ROAD SALT

Recommended Solution

WITH WINTER APPROACHING, PLEASE POWER WASH THE CHASSIS AND UNDERCARRIAGE TO REMOVE ROAD SALT PROMPTLY UPON RECEIPT OF NEWLY ARRIVED UNITS.

THIS TSB WAS ORIGINALLY ISSUED 11/21/97.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

TSB.09019