

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
12/5/97		ALL	153				
BRAND		TYPE					
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>	All <input checked="" type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input type="checkbox"/>	D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Return parts.							
RECOMMENDED SOLUTION							
All parts should be shipped UPS. Freight items must be shipped Roadway freight collect. Any other form of returning parts must be authorized prior to shipment.							

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.