

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
6/11/98	1997-1999	ALL	158
BRAND		TYPE	
All <input checked="" type="checkbox"/> American Star <input type="checkbox"/> Kountry Star <input type="checkbox"/> Dutch Star <input type="checkbox"/>		All <input checked="" type="checkbox"/> T T <input type="checkbox"/> F W <input type="checkbox"/>	
NewAire <input type="checkbox"/> Mountain Aire <input type="checkbox"/> Kountry Aire <input type="checkbox"/> London Aire <input type="checkbox"/>		C A <input type="checkbox"/> D P <input type="checkbox"/> D B <input type="checkbox"/>	
<input type="checkbox"/> Air Conditioning & Heating			
<input type="checkbox"/> Appliances & Accessories			
<input type="checkbox"/> Cabinets & Furniture			
<input type="checkbox"/> Chassis Components			
<input type="checkbox"/> Construction Components			
<input type="checkbox"/> Electrical Components			
<input checked="" type="checkbox"/> Exterior Components			
<input type="checkbox"/> Interior Components			
<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM			
Exterior paint issues.			
RECOMMENDED SOLUTION			
All paint related issues must have a prior authorization before starting any repairs. Repairs may require an inspection by a paint representative.			

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.