

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN			
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #
4/7/89	ALL	ALL	18
BRAND		TYPE	
All <input checked="" type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input type="checkbox"/>	Dutch Star <input type="checkbox"/>
NewAire <input type="checkbox"/>	Mountain Aire <input type="checkbox"/>	Kountry Aire <input type="checkbox"/>	London Aire <input type="checkbox"/>
<input type="checkbox"/> Air Conditioning & Heating <input checked="" type="checkbox"/> Appliances & Accessories <input type="checkbox"/> Cabinets & Furniture <input type="checkbox"/> Chassis Components <input type="checkbox"/> Construction Components		<input type="checkbox"/> Electrical Components <input type="checkbox"/> Exterior Components <input type="checkbox"/> Interior Components <input type="checkbox"/> Plumbing & Bath Components <input type="checkbox"/> Windows, Awnings, Vents, & Doors	
DESCRIPTION OF PROBLEM			
Onan generator setting.			
RECOMMENDED SOLUTION			
<p>It has come to my attention that some dealers have been setting the output on the Onan generators. This is strictly forbidden by Onan unless you are an authorized service center for them. You are only allowed to do tune-ups, plugs, oil changes, etc. Not any output adjustments.</p> <p>Should you adjust the output and there is appliance damage from too high a voltage, you must assume responsibility for repair or replacement of said appliances. Newmar will not honor warranty claims on the appliances that are damaged due to your setting generator output when you are not authorized by Onan for such work.</p> <p>Bud Holewinski Newmar Director of Consumer Affairs</p>			

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.