TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S)	AFFECTED	TSB #	
9/22/99 2000			ALL MOTORIZED		180		
Brand					Түре		
All 🗖 Americ	can Star 🛛	Kountry Star	Dut	ch Star 🗖	All 🗖 T	Т <b>П</b>	
NewAire 🗖 Mountain Aire 🗖 Kountry Aire 🗖			Lon	don Aire	C A 📕 D	D P ■ D B ■	
□ Air Conditioning &	Electrical Components						
Appliances & Accessories				Exterior Components			
Cabinets & Furniture				☐ Interior Components			
Chassis Components				Plumbing & Bath Components			
Construction Components				☐ Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
RECOMMENDED SOLUTION							
Dealers are having difficulty removing the LP when moving into shows.							
Newmar is lighting all appliances with a portable LP tank.							
NOTE: LP TANKS AND BOTTLES MUST BE PURGED PRIOR TO FILLING.							