

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN							
DATE ISSUED	MODEL YEAR(S) AFFECTED	MODEL(S) AFFECTED	TSB #				
2/24/00	SPARTAN SUMMIT CHASSIS	2000	200				
BRAND		TYPE					
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>	
NewAir <input type="checkbox"/>	Mountain Air <input type="checkbox"/>	Kountry Air <input type="checkbox"/>	London Air <input type="checkbox"/>	C A <input type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input type="checkbox"/>	
<input checked="" type="checkbox"/> Air Conditioning & Heating				<input type="checkbox"/> Electrical Components			
<input type="checkbox"/> Appliances & Accessories				<input type="checkbox"/> Exterior Components			
<input type="checkbox"/> Cabinets & Furniture				<input type="checkbox"/> Interior Components			
<input checked="" type="checkbox"/> Chassis Components				<input type="checkbox"/> Plumbing & Bath Components			
<input type="checkbox"/> Construction Components				<input type="checkbox"/> Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM							
Evans TempCon parts information.							
RECOMMENDED SOLUTION							
See attached information.							

72185 COUNTY ROAD 3
NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX 219.773.2007



701 Ann Street N.W.,
Grand Rapids, MI. 49504
Telephone (616) 361-2681
Fax (616) 361-9646

TEMPCON

SERVICE BULLETIN

112999

DATE NOVEMBER 29, 1999
TO DUANE CASTEEL, SERVICE MANAGER, NEWMAR
SUBJECT NEW SERVICE PARTS DRAWINGS

ATTACHED ARE EXPLODED VIEW SERVICE PARTS DRAWINGS FOR THE FOLLOWING
NEWMAR PRODUCTION KIT:

<u>EVANS P/N</u>	<u>NEWMAR</u>	<u>DESCRIPTION</u>
RV212777	38219	IFS FREIGHTLINER ADAPTOR PKG

PLEASE SEE THAT COPIES ARE PROVIDED TO THE APPROPRIATE PERSONNEL (IE SERVICE, WARRANTY, ETC) IN YOUR ORGANIZATION.

CONTACT YOUR CUSTOMER SERVICE REPRESENTATIVE IF YOU HAVE ANY QUESTIONS.


Internal distribution: Wood, Noroozi, D. Leys, Schultea, Cushway, Hawrysz, Encore Distributors

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION

WARRANTY DEPARTMENT

RV212787 - REPLACEMENT PARTS LIST
SPARTAN SUMMIT 2000
A/C ENGINE KIT COMPONENTS



ITEM NO.	PART NO.	SERVICE PACKAGE NO.	DESCRIPTION
1	RV200792	RV218615	CONDENSER ASSEMBLY- (INCLUDES ITEMS 2 - 4)
2	FT200414	RV218616	CONDENSER CORE
3	RV011678	////////	CONDENSER EDGE GUARD
4	RV011679	////////	MOUNTING BRACKET
5	RV200453P	RV218183	FAN ASSEMBLY
6	RV011754	////////	CONDENSER MOUNTING BRACKET - RIGHT
7	RV011755	////////	CONDENSER MOUNTING BRACKET - LEFT
8	RV011245	RV218337	RECEIVER DRIER - NON-METRIC
9	RV011166	RV218188	CLAMP, RECEIVER-DRIER
10	RV200241	RV212336	BINARY ASSEMBLY (INCLUDES ITEMS 11 - 12)
11	RV010484	RV218323	PRESSURE SWITCH - LIQUID
12	RV200242	RV212070	WIRE HARNESS-BINARY SWITCH
13	RV011248	RV218338	#6 HOSE (EVAPORATOR)
14	RV011281	RV218359	#6 LIQUID HOSE (CONDENSER)
15	RV200566	RV218322	#12 SUCTION HOSE, FRONT
16	RV011163	RV218315	O-RING #10
17	RV200701	RV218540	DISCHARGE HOSE, FRONT
18	RV011162	RV218311	O-RING #8
19	RV200536	RV218302	CHARGING OIL, 4 OZ BOTTLE
20	RV200760	RV218583	#12 SUCTION HOSE, REAR
21	RV200568	RV218341	#10 DISCHARGE HOSE, REAR
22	RV011109	RV218184	WIRE HARNESS - CONDENSER
23	HV033498	RV212112	RELAY - 12V, 30A



If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION WARRANTY DEPARTMENT

RV212777 - REPLACEMENT PARTS LIST
IFS ADAPTER PACKAGE



701 ANN ST. N.W.
GRAND RAPIDS, MI 49504



ITEM NO.	PART NO.	SERVICE PACKAGE NO.	DESCRIPTION
1	RV200451	RV218185	BINARY ASSEMBLY
2	RV010484	RV218323	PRESSURE SWITCH - LIQUID
3	RV011110	////////	BINARY WIRE HARNESS
4	RV200539	RV218657	#12 SUCTION HOSE - R134A
5	RV200552	RV218308	#6 LIQUID HOSE ASSEMBLY - R134A

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.