

72185 COUNTY ROAD 3
NAPPANEE IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

FAX. 800.858.4924
219.773.2007

TECHNICAL SERVICE BULLETIN

Date Issued
03/26/01

Model Year(s) Affected
2001

Model(s) Affected
Non Kitchen SO

TSB #
213

Brand				Type		
ALL <input checked="" type="radio"/>	American Star <input type="radio"/>	Kountry Star <input type="radio"/>	Dutch Star <input type="radio"/>	All <input checked="" type="radio"/>	TT <input type="radio"/>	FW <input type="radio"/>
	Mountain Aire <input type="radio"/>	Kountry Aire <input type="radio"/>	London Aire <input type="radio"/>	CA <input type="radio"/>	DP <input type="radio"/>	DB <input type="radio"/>

- ☐ Air Conditioning & Heating
- ☐ Appliances & Accessories
- ☒ Cabinets & Furniture
- ☐ Chassis Components
- ☐ Construction Components

- ☐ Electrical Components
- ☐ Exterior Components
- ☐ Interior Components
- ☐ Plumbing & Bath Components
- ☐ Windows, Awnings, Vents & Doors

Description of Problem

On all models, except those featuring the kitchen slide out or those models without the hardwood cabinetry option, the standard kitchen cabinet base needs to have the support as described below.

Recommended Solution

Install a toe kick bracket (See attached picture) at the bottom of each vertical style or pair of vertical styles on kitchen base cabinets. This solution applies to wrapped style cabinet construction only. This bracket will support the front and top of the cabinet due to the vertical styles stopping short of the floor. Toe kick bracket part number 34369.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

NEWMAR CORPORATION
TSB 213
PAGE 1

