

72185 COUNTY ROAD 3  
NAPPANEE IN 46550

# NEWMAR CORPORATION WARRANTY DEPARTMENT

FAX. 800.858.4924  
219.773.2007

## TECHNICAL SERVICE BULLETIN

Date Issued  
05/17/01

Model Year(s) Affected  
2001

Model(s) Affected  
Motorized

TSB #  
218

| Brand                     |  |   |  | Type                                |                                     |                          |
|---------------------------|--|---|--|-------------------------------------|-------------------------------------|--------------------------|
| ALL <input type="radio"/> | American Star <input type="radio"/>            | Kountry Star <input checked="" type="radio"/> | Dutch Star <input checked="" type="radio"/>  | All <input type="radio"/>           | TT <input type="radio"/>            | FW <input type="radio"/> |
|                           | Mountain Aire <input checked="" type="radio"/> | Kountry Aire <input checked="" type="radio"/> | London Aire <input checked="" type="radio"/> | CA <input checked="" type="radio"/> | DP <input checked="" type="radio"/> | DB <input type="radio"/> |

- ☐ Air Conditioning & Heating
- ☒ Appliances & Accessories
- ☐ Cabinets & Furniture
- ☐ Chassis Components
- ☐ Construction Components

- ☐ Electrical Components
- ☐ Exterior Components
- ☐ Interior Components
- ☐ Plumbing & Bath Components
- ☐ Windows, Awnings, Vents & Doors

### Description of Problem

The rear view mirror compass calibration may be reset when the television is turned on.

### Recommended Solution

Do not replace the rear view mirror. Instead, remove the television and install a piece of .30 aluminum large enough to cover the bottom of the television area, starting one inch back from the front edge on the bottom of the television cabinet. This aluminum will act as a shield to protect the compass from any television electrical interference.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.

TSB.09019