

72185 COUNTY ROAD 3
NAPPANEE IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924
FAX. 219.773.2007

TECHNICAL SERVICE BULLETIN

Date Issued 06/15/01	Model Year(s) Affected ALL	Model(s) Affected ALL	TSB # 222
-------------------------	-------------------------------	--------------------------	--------------

Brand				Type		
ALL <input checked="" type="radio"/>	American Star <input type="radio"/>	Kountry Star <input type="radio"/>	Dutch Star <input type="radio"/>	All <input checked="" type="radio"/>	TT <input type="radio"/>	FW <input type="radio"/>
	Mountain Aire <input type="radio"/>	Kountry Aire <input type="radio"/>	London Aire <input type="radio"/>	CA <input type="radio"/>	DP <input type="radio"/>	DB <input type="radio"/>

- | | |
|--|---|
| <input type="radio"/> Air Conditioning & Heating | <input type="radio"/> Electrical Components |
| <input type="radio"/> Appliances & Accessories | <input type="radio"/> Exterior Components |
| <input type="radio"/> Cabinets & Furniture | <input type="radio"/> Interior Components |
| <input type="radio"/> Chassis Components | <input type="radio"/> Plumbing & Bath Components |
| <input type="radio"/> Construction Components | <input type="radio"/> Windows, Awnings, Vents & Doors |

Description of Problem

Returning parts for warranty credit that contain hazardous materials.

Recommended Solution

Please DO NOT ship any parts to Newmar Corporation that contain any type of hazardous materials, including liquids. Be sure to drain all of the fluids out of the parts as much as possible before shipping them back for credit. For example, hydraulic oil, anti-freeze, or LP gas.

Any fees relating to the shipment of hazardous materials will be the responsibility of the shipping dealer.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.