

NEWMAR CORPORATION WARRANTY DEPARTMENT

TECHNICAL SERVICE BULLETIN									
DATE ISSUED		MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED			TSB #	
06/15/01		2002			MOTORIZED			224	
BRAND					TYPE				
All <input type="checkbox"/>	American Star <input type="checkbox"/>	Kountry Star <input checked="" type="checkbox"/>	Dutch Star <input checked="" type="checkbox"/>	All <input type="checkbox"/>	T T <input type="checkbox"/>	F W <input type="checkbox"/>			
NewAire <input type="checkbox"/>	Mountain Aire <input checked="" type="checkbox"/>	Kountry Aire <input checked="" type="checkbox"/>	London Aire <input checked="" type="checkbox"/>	C A <input checked="" type="checkbox"/>	D P <input checked="" type="checkbox"/>	D B <input checked="" type="checkbox"/>			
<input type="checkbox"/> Air Conditioning & Heating					<input type="checkbox"/> Electrical Components				
<input type="checkbox"/> Appliances & Accessories					<input checked="" type="checkbox"/> Exterior Components				
<input type="checkbox"/> Cabinets & Furniture					<input type="checkbox"/> Interior Components				
<input type="checkbox"/> Chassis Components					<input type="checkbox"/> Plumbing & Bath Components				
<input type="checkbox"/> Construction Components					<input type="checkbox"/> Windows, Awnings, Vents, & Doors				
DESCRIPTION OF PROBLEM									
Shipping film will be removed from Newmar units.									
RECOMMENDED SOLUTION									
<p>Newmar Corporation and Sherwin Williams have extensively reviewed the paint process used at the Newmar facility. Newmar will be adding hardeners to the base coat, sealer coat, and clear coat processes.</p> <p>Newmar is eliminating the use of the “stick on” protective film. According to the extensive research, this product provided little or no protection against stone chips, as well as posed the potential to damage the paint, if left on the unit.</p>									

□

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.