
72185 COUNTY ROAD 3 NAPPANEE, IN 46550

NEWMAR CORPORATION WARRANTY DEPARTMENT

800.858.4924 Fax 219.773.2007

TECHNICAL SERVICE BULLETIN						
DATE ISSUED MODEL YEAR(S) AFFECTED		D	Model(s) Affected		TSB#	
3/8/02	2002		Diesel	Pusher	238	
Brand			Түре			
All	can Star □ Kountry Star □	Dut	ch Star 🛚	All 🗖 T	T□ FW□	
NewAire □ Mountain Aire ■ Kountry Aire ■			don Aire□	C A □ D	P■ DB□	
☐ Air Conditioning & Heating ☐ El				Electrical Components		
☐ Appliances & Accessories			☐ Exterior Components			
☐ Cabinets & Furniture			☐ Interior Components			
■ Chassis Components			☐ Plumbing & Bath Components			
☐ Construction Components			☐ Windows, Awnings, Vents, & Doors			
DESCRIPTION OF PROBLEM						
RECOMMENDED SOLUTION						
Locate the kazoo drain on the bottom of the air intake box. Insert a large standard screwdriver through the rubber tube. This will create an opening to the possible affected area. Move the screwdriver in a circular motion to create a larger opening.						
Please allow .3 hr for this repair and use flat rate code number 15901202.						

NEWMAR CORPORATION WARRANTY DEPARTMENT



NEWMAR CORPORATION WARRANTY DEPARTMENT

