TECHNICAL SERVICE BULLETIN											
	DATE ISSUED	MODEL YEAR(S) AFFECTED			MODEL(S) AFFECTED)	TSB #		
2/10/03		2003			Essex				245		
BRAND					Түре						
All	American Star Kountry Star			Dut	Dutch Star 🗖 All 🗖			Т	ТТ П		
Sco	Scottsdale 🗆 Mountain Aire 🗖 Kountry Aire 🗖				Sex \square C A \square D P \square			DB 🗖			
Air Conditioning & Heating Electrical Components											
	Appliances & Accessories				Exterior Components						
	Cabinets & Furniture				Interior Components						
	□ Chassis Components					☐ Plumbing & Bath Components					
	Construction Con		Windows, Awnings, Vents, & Doors								
DESCRIPTION OF PROBLEM											
Poor picture on Sony plasma television.											

RECOMMENDED SOLUTION

A poor quality picture on the Sony plasma television could be caused by the video input cable being installed in the video output on the back of the television. To insure the television is hooked up properly, start a DVD movie then press the DVD stop button. A sky scene will be displayed on the television. This scene is output by the DVD player. A properly connected television will display a scene where there is an obvious distinction between the clouds and the sky. An improperly connected television will display a scene that blends the clouds and the sky together and everything looks the same.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.