

Newmar Corporation

Warranty Department

Technical Service Bulletin							
Date Issued		Model Year(s) Affected		Model(s) Affected		TSB #	
10/20/2006		2/5/98 – 6/5/06		Spartan Chassis MM and K2		269	
Brand						Type	
All	☒	American Star	☐	Mountain Aire	☐	All	☐
		Dutch Star	☐	Kountry Aire	☐	F W	☐
		Kountry Star	☐	Essex	☐	D P	☒
Scottsdale	☐	Northern Star	☐	London Aire	☐	D B	☒
☐ Air Conditioning & Heating ☐ Appliances & Accessories ☐ Cabinets & Furniture ☒ Chassis Components ☐ Construction Components ☐ Electrical Components ☐ Exterior Components ☐ Interior Components ☐ Plumbing & Bath Components ☐ Windows, Awnings, Vents, & Doors							
Description of Problem							
Steering gear support bracket may break allowing the steering system to become inoperable.							
Recommended Solution							
Replace the steering gear support bracket. See manufacturers attached repair directions. Contact manufacturer directly for additional information or instruction.							

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.



May 18, 2006

**Spartan Recall
NHTSA Recall No. 06V-156**

Dear Service Manager:

Spartan Motors is recalling MM and K2 Chassis Models manufactured from February 5, 1998 through June 5, 1998 equipped with pitman arm part number 0945-KK1.

Reason: The Steering Gear Support Bracket may break allowing the steering system to become inoperable, creating the potential for injury to occupants.

We will contact all owners of these units that are affected by this recall. They will be provided with our web address that lists Spartan Authorized Service Centers, including your facility. They will also be advised that they do not need to call Spartan Motors, but they should call the facility on the list that is nearest to them and make an appointment.

Replacement steering gear support brackets are available for installation. Please find attached the Instructions to replace them.

SCHEDULING THE WORK:

1. When the customer calls reporting receipt of a Recall Service Bulletin, schedule the work at your mutual convenience.
2. When the customer arrives for the appointment, ask him/her for his recall letter. You can use this to verify the chassis VIN.
3. It will be helpful to verify the "users" current address and phone number.

COMPLETING THE WORK:

1. **You do not need a work authorization number from Spartan Motors to complete this work.** There is no need to call Spartan customer service unless you need technical assistance.
2. Do the work following the instructions on the Recall Service Bulletin.

DOCUMENTING THE WORK:

1. Reference to the identified recall number **06V-156** and the completed work on the submitted invoice will satisfy our need for documentation of this recall.

2. You will be reimbursed for 3.0 hours labor to install the steering gear support bracket.

If there are contributing factors that cause the recall procedure to take longer than the allotted time, please report that information on your shop repair order instead of the "Record of Completion," including details of the circumstances that resulted in additional time. Enter Recall # **06V-156** as the work authorization number. The time for these repairs will be considered for reimbursement on a case by case basis.

3. Documents submitted for Spartan reimbursement for this recall should not be combined with any other documents being sent to Spartan.

HANDLING A "USER" WITH NO CONFIRMATION LETTER:

1. If you are contacted by a "user" who has not received a recall letter, you should verify that they have an affected chassis and call Wayne Ridge at Spartan Motors (800-393-8861 – Option 3) for verification.
2. Complete the work as instructed.
3. Record the vehicle VIN along with the mileage on a copy you make of the enclosed **"Parts & Authorization Request"** form. Please fax this information, when necessary, to (517) 543-9264.
4. Document the work and submit the claim as instructed under the Documenting the Work section above.

PARTS SUPPLY & DISPOSITION:

1. The shipment of parts will be identified with the recall number. If you need additional parts, please order them by calling Spartan Motors Customer Service at (800) 393-8861 (Option 6).

SPARTAN ASSISTANCE:

1. If you have **technical questions**, please call Spartan Motors' Customer Service Department at (800) 393-8861 (Option 2).
2. If you have questions about warranty claims call Wayne Ridge at (800) 393-8861 (Option 3) or 517-543-6400 ext.445.

SPARTAN **MOTORS**
CHASSIS, INC.

Customer Assistance Center
Motorhome Group – 800-393-8861 (Option 6)

Fax Submittal To:
Spartan Motors Campaign Recall Coordinator (Annette)

Recall 06V-156
SPEC 06011

PARTS & AUTH. REQUEST FORM FOR STEERING GEAR BRACKET KIT

Truck VIN# (Last five digits)

- | | |
|----------|----------------|
| 1) _____ | Mileage: _____ |
| 2) _____ | Mileage: _____ |
| 3) _____ | Mileage: _____ |
| 4) _____ | Mileage: _____ |

(In the event your department has additional units duplicate this form as needed)

Your Department name: _____

Address: _____ **City:** _____

State: _____ **Zip:** _____

Phone: _____ **Fax:** _____

Contact: _____ **Date:** _____

Work authorization # _____ **(To be entered by Spartan Tech)**

Approx. Date for Parts Delivery: ____ / ____ / ____ **(Entered by Spartan Technician)**

Please fax to Spartan Motors - 517-543-9264 - Attention: Annette Wibert

The recall parts order will be processed for this truck, the work authorization number will be entered and this will be re-faxed to you within one business day.

Spartan Motors thanks you for filling out the recall parts and authorization form. Spartan will send you a confirmation of parts shipment along with a warranty authorization number good for 3 hours for labor to perform recall per truck, per authorization.

SPARTAN **MOTORS**
CHASSIS, INC.

VINNUM	SO6	SALES ORDER	FPN	BDYBLD	VDM DTE	MODEL	MOD ENG	SER ENG
4VZAR1793WC028059	028059	28059	K211440-003	GULF STREAM COACH (C	2/9/1998	K2-CELECT +	R408-AA2-018	34896280
4VZBN1094WC028081	028081	28081	MM11440-006	GULF STREAM COACH (C	2/12/1998	MM-2242	R451-AA2-001	45638325
4VZBN1095WC028199	028199	28199	MM11440-006	GULF STREAM COACH (C	2/12/1998	MM-2242	R451-AA2-001	45642183
4VZBN1096WC028065	028065	28065	MM11440-006	GULF STREAM COACH (C	2/13/1998	MM-2242	R451-AA2-001	45635926
4VZBN1096WC028082	028082	28082	MM11440-006	GULF STREAM COACH (C	2/13/1998	MM-2242	R451-AA2-001	45638486
4VZBN109XWC028067	028067	28067	MM11440-006	GULF STREAM COACH (C	2/16/1998	MM-2242	R451-AA2-001	45648982
4VZBN1096WC028101	028101	28101	MM24360-014	NEWMAR	2/16/1998	MM-2242	R451-AA2-001	45636030
4VZBN1094WC028341	028341	28341	MM16290-014	FLEETWOOD MOTORHOMES	2/16/1998	MM-2242	R451-AA2-001	45635851
4VZBN1096WC028342	028342	28342	MM16290-014	FLEETWOOD MOTORHOMES	2/16/1998	MM-2242	R451-AA2-001	45638488
4VZBN1098WC028343	028343	28343	MM16290-014	FLEETWOOD MOTORHOMES	2/16/1998	MM-2242	R451-AA2-001	45648969
4VZBN109XWC028344	028344	28344	MM16290-014	FLEETWOOD MOTORHOMES	2/16/1998	MM-2242	R451-AA2-001	45635948
4VZBN1093WC028346	028346	28346	MM16290-014	FLEETWOOD MOTORHOMES	2/16/1998	MM-2242	R451-AA2-001	45635928
4VZBN1097WC028348	028348	28348	MM16290-014	FLEETWOOD MOTORHOMES	2/16/1998	MM-2242	R451-AA2-001	45635795
4VZAR1791WC028058	028058	28058	K211440-003	GULF STREAM COACH (C	2/16/1998	K2-CELECT +	R408-AA2-018	34896284
4VZBN1098WC028102	028102	28102	MM24360-014	NEWMAR	2/17/1998	MM-2242	R451-AA2-001	45649017
4VZBN1091WC028345	028345	28345	MM16290-014	FLEETWOOD MOTORHOMES	2/17/1998	MM-2242	R451-AA2-001	45649032
4VZBN1095WC028347	028347	28347	MM16290-014	FLEETWOOD MOTORHOMES	2/17/1998	MM-2242	R450-AA2-001	45648822
4VZBN1099WC028349	028349	28349	MM16290-014	FLEETWOOD MOTORHOMES	2/17/1998	MM-2242	R451-AA2-001	45636041
4VZBN1095WC028350	028350	28350	MM16290-014	FLEETWOOD MOTORHOMES	2/17/1998	MM-2242	R450-AA2-001	45635826
4VZBN1099WC028352	028352	28352	MM16290-014	FLEETWOOD MOTORHOMES	2/17/1998	MM-2242	R451-AA2-001	45649021
4VZAR179XWC028060	028060	28060	K211440-003	GULF STREAM COACH (C	2/17/1998	K2-CELECT +	R408-AA2-018	34900357
4VZBN1097WC028351	028351	28351	MM16290-014	FLEETWOOD MOTORHOMES	2/18/1998	MM-2242	R451-AA2-001	45649097
4VZBN109XWC028358	028358	28358	MM16290-014	FLEETWOOD MOTORHOMES	2/18/1998	MM-2242	R451-AA2-001	45649067
4VZBN1095WC028414	028414	28414	MM24360-014	NEWMAR	2/18/1998	MM-2242	R451-AA2-001	45644878
4VZBN1097WC028415	028415	28415	MM24360-014	NEWMAR	2/18/1998	MM-2242	R451-AA2-001	45649094
4VZBN1099WC028416	028416	28416	MM24360-014	NEWMAR	2/18/1998	MM-2242	R451-AA2-001	45638477
4VZAR1791WC028061	028061	28061	K211440-003	GULF STREAM COACH (C	2/18/1998	K2-CELECT +	R408-AA2-018	34896282
4VZBN1098WC028357	028357	28357	MM16290-014	FLEETWOOD MOTORHOMES	2/19/1998	MM-2242	R451-AA2-001	45649064
4VZBN1091WC028359	028359	28359	MM16290-014	FLEETWOOD MOTORHOMES	2/19/1998	MM-2242	R451-AA2-001	45642152
4VZBN1092WC028418	028418	28418	MM24360-014	NEWMAR	2/19/1998	MM-2242	R451-AA2-001	45635894
4VZBN1090WC028367	028367	28367	MM16290-014	FLEETWOOD MOTORHOMES	2/20/1998	MM-2242	R451-AA2-001	45642147
4VZBN1094WC028369	028369	28369	MM16290-014	FLEETWOOD MOTORHOMES	2/20/1998	MM-2242	R451-AA2-001	45638362
4VZBN1092WC028371	028371	28371	MM16290-014	FLEETWOOD MOTORHOMES	2/20/1998	MM-2242	R451-AA2-001	45638354
4VZBN1094WC028419	028419	28419	MM24360-014	NEWMAR	2/20/1998	MM-2242	R451-AA2-001	45642177
4VZBN1096WC028373	028373	28373	MM16290-014	FLEETWOOD MOTORHOMES	2/23/1998	MM-2242	R451-AA2-001	45638331
4VZBN109XWC028375	028375	28375	MM16290-014	FLEETWOOD MOTORHOMES	2/23/1998	MM-2242	R451-AA2-001	45638327
4VZBN1092WC028368	028368	28368	MM16290-014	FLEETWOOD MOTORHOMES	2/24/1998	MM-2242	R451-AA2-001	45638344
4VZBN1093WC028377	028377	28377	MM16290-014	FLEETWOOD MOTORHOMES	2/24/1998	MM-2242	R451-AA2-001	45642158

4VZBN1097WC028379	028379	28379	MM16290-014	FLEETWOOD MOTORHOMES	2/24/1998	MM-2242	R451-AA2-001	45638424
4VZBN1098WC028097	028097	28097	MM24360-014	NEWMAR	2/25/1998	MM-2242	R451-AA2-001	45638360
4VZBN109XWC028098	028098	28098	MM24360-014	NEWMAR	2/25/1998	MM-2242	R451-AA2-001	45638431
4VZBN1091WC028099	028099	28099	MM24360-014	NEWMAR	2/25/1998	MM-2242	R451-AA2-001	45635920
4VZBN1094WC028100	028100	28100	MM24360-014	NEWMAR	2/25/1998	MM-2242	R451-AA2-001	45635950
4VZBN1090WC028370	028370	28370	MM16290-014	FLEETWOOD MOTORHOMES	2/25/1998	MM-2242	R451-AA2-001	45642145
4VZBN1094WC028372	028372	28372	MM16290-014	FLEETWOOD MOTORHOMES	2/25/1998	MM-2242	R451-AA2-001	45638366
4VZBN1098WC028374	028374	28374	MM16290-014	FLEETWOOD MOTORHOMES	2/25/1998	MM-2242	R451-AA2-001	45638373
4VZBN1090WC028692	028692	28692	MM16290-014	FLEETWOOD MOTORHOMES	2/25/1998	MM-2242	R451-AA2-001	45644913
4VZBN1094WC028694	028694	28694	MM16290-014	FLEETWOOD MOTORHOMES	2/25/1998	MM-2242	R451-AA2-001	45644831
4VZBN1098WC028696	028696	28696	MM16290-014	FLEETWOOD MOTORHOMES	2/25/1998	MM-2242	R451-AA2-001	45635962
4VZBN1091WC028376	028376	28376	MM16290-014	FLEETWOOD MOTORHOMES	2/26/1998	MM-2242	R451-AA2-001	45638480
4VZBN1095WC028378	028378	28378	MM16290-014	FLEETWOOD MOTORHOMES	2/26/1998	MM-2242	R451-AA2-001	45642161
4VZBN1098WC028486	028486	28486	MM24360-014	NEWMAR	2/26/1998	MM-2242	R451-AA2-001	45638434
4VZBN109XWC028487	028487	28487	MM24360-014	NEWMAR	2/26/1998	MM-2242	R451-AA2-001	45638352
4VZBN1091WC028698	028698	28698	MM16290-014	FLEETWOOD MOTORHOMES	2/26/1998	MM-2242	R451-AA2-001	45638498
4VZBN1096WC028700	028700	28700	MM16290-014	FLEETWOOD MOTORHOMES	2/26/1998	MM-2242	R451-AA2-001	45638364
4VZAR1792WC028103	028103	28103	K211440-003	GULF STREAM COACH (C	2/26/1998	K2-CELECT +	R408-AA2-018	34896286
4VZBN1093WC028380	028380	28380	MM16290-014	FLEETWOOD MOTORHOMES	2/27/1998	MM-2242	R451-AA2-001	45638333
4VZBN1091WC028488	028488	28488	MM24360-014	NEWMAR	2/27/1998	MM-2242	R451-AA2-001	45644948
4VZBN1093WC028489	028489	28489	MM24360-014	NEWMAR	2/27/1998	MM-2242	R451-AA2-001	45638336
4VZBN109XWC028702	028702	28702	MM16290-014	FLEETWOOD MOTORHOMES	2/27/1998	MM-2242	R451-AA2-001	45636045
4VZBN1093WC028704	028704	28704	MM16290-014	FLEETWOOD MOTORHOMES	2/27/1998	MM-2242	R451-AA2-001	45638349
4VZBN1097WC028706	028706	28706	MM16290-014	FLEETWOOD MOTORHOMES	2/27/1998	MM-2242	R451-AA2-001	45644861
4VZBN1091WC028491	028491	28491	MM24360-014	NEWMAR	3/2/1998	MM-2242	R451-AA2-001	45649083
4VZBN1092WC028693	028693	28693	MM16290-014	FLEETWOOD MOTORHOMES	3/2/1998	MM-2242	R451-AA2-001	45649012
4VZBN1090WC028708	028708	28708	MM16290-014	FLEETWOOD MOTORHOMES	3/2/1998	MM-2242	R451-AA2-001	45638491
4VZBN1098WC028763	028763	28763	MM16290-013	FLEETWOOD MOTORHOMES	3/3/1998	MM-2242	R451-AA2-001	45648473
4VZAR1793WC028062	028062	28062	K211440-003	GULF STREAM COACH (C	3/3/1998	K2-CELECT +	R408-AA2-018	34900358
4VZBN1093WC028699	028699	28699	MM16290-014	FLEETWOOD MOTORHOMES	3/4/1998	MM-2242	R451-AA2-001	45648444
4VZBN1098WC028701	028701	28701	MM16290-014	FLEETWOOD MOTORHOMES	3/4/1998	MM-2242	R451-AA2-001	45644721
4VZBN1095WC028705	028705	28705	MM16290-014	FLEETWOOD MOTORHOMES	3/5/1998	MM-2242	R451-AA2-001	45648971
4VZBN1096WC028714	028714	28714	MM24360-014	NEWMAR	3/5/1998	MM-2242	R451-AA2-001	45656104
4VZBN1096WC028776	028776	28776	MM16290-014	FLEETWOOD MOTORHOMES	3/5/1998	MM-2242	R451-AA2-001	45634549
4VZBN1099WC028707	028707	28707	MM16290-014	FLEETWOOD MOTORHOMES	3/6/1998	MM-2242	R451-AA2-001	45648399
4VZBN1092WC028709	028709	28709	MM16290-014	FLEETWOOD MOTORHOMES	3/6/1998	MM-2242	R451-AA2-001	45656044
4VZBN1098WC028715	028715	28715	MM24360-014	NEWMAR	3/6/1998	MM-2242	R451-AA2-001	45656092
4VZBN1098WC028780	028780	28780	MM16290-014	FLEETWOOD MOTORHOMES	3/6/1998	MM-2242	R451-AA2-001	45635803
4VZBN1095WC028784	028784	28784	MM16290-014	FLEETWOOD MOTORHOMES	3/9/1998	MM-2242	R451-AA2-001	45635936

4VZBN1094WC028713	028713	28713	MM24360-014	NEWMAR	3/10/1998	MM-2242	R451-AA2-001	45656050
4VZBN1090WC028773	028773	28773	MM16290-014	FLEETWOOD MOTORHOMES	3/11/1998	MM-2242	R451-AA2-001	45635842
4VZBN1099WC028786	028786	28786	MM16290-014	FLEETWOOD MOTORHOMES	3/11/1998	MM-2242	R451-AA2-001	45636011
4VZBN1098WC028794	028794	28794	MM16290-014	FLEETWOOD MOTORHOMES	3/11/1998	MM-2242	R451-AA2-001	45636022
4VZBN1091WC028796	028796	28796	MM16290-014	FLEETWOOD MOTORHOMES	3/11/1998	MM-2242	R451-AA2-001	45656082
4VZBN1093WC028797	028797	28797	MM16290-014	FLEETWOOD MOTORHOMES	3/11/1998	MM-2242	R451-AA2-001	45656052
4VZBN1096WC028695	028695	28695	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45648446
4VZBN1091WC028703	028703	28703	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45648512
4VZBN1090WC028711	028711	28711	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45655867
4VZBN1092WC028774	028774	28774	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45637129
4VZBN1094WC028775	028775	28775	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45636063
4VZBN109XWC028778	028778	28778	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45635760
4VZBN1091WC028782	028782	28782	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45635878
4VZBN1095WC028798	028798	28798	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45647507
4VZBN1090WC028806	028806	28806	MM16290-014	FLEETWOOD MOTORHOMES	3/12/1998	MM-2242	R451-AA2-001	45656077
4VZBN1093WC028640	028640	28640	MM24360-014	NEWMAR	3/13/1998	MM-2242	R451-AA2-001	45648491
4VZBN1095WC028641	028641	28641	MM24360-014	NEWMAR	3/13/1998	MM-2242	R451-AA2-001	45649069
4VZBN1097WC028642	028642	28642	MM24360-014	NEWMAR	3/13/1998	MM-2242	R451-AA2-001	45649074
4VZBN109XWC028697	028697	28697	MM16290-014	FLEETWOOD MOTORHOMES	3/13/1998	MM-2242	R451-AA2-001	45648395
4VZBN1099WC028710	028710	28710	MM16290-014	FLEETWOOD MOTORHOMES	3/13/1998	MM-2242	R451-AA2-001	45638423
4VZBN1092WC028712	028712	28712	MM24360-014	NEWMAR	3/13/1998	MM-2242	R451-AA2-001	45644709
4VZBN1091WC028779	028779	28779	MM16290-014	FLEETWOOD MOTORHOMES	3/13/1998	MM-2242	R451-AA2-001	45635784
4VZBN1097WC028785	028785	28785	MM16290-014	FLEETWOOD MOTORHOMES	3/16/1998	MM-2242	R451-AA2-001	45636000
4VZBN1097WC028804	028804	28804	MM16290-014	FLEETWOOD MOTORHOMES	3/16/1998	MM-2242	R451-AA2-001	45644762
4VZBN1094WC028808	028808	28808	MM16290-014	FLEETWOOD MOTORHOMES	3/16/1998	MM-2242	R451-AA2-001	45644694
4VZBN1098WC028777	028777	28777	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45635752
4VZBN109XWC028781	028781	28781	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45635856
4VZBN1093WC028783	028783	28783	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45635886
4VZBN1096WC028793	028793	28793	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45636019
4VZBN109XWC028795	028795	28795	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45635837
4VZBN1097WC028799	028799	28799	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45656046
4VZBN109XWC028800	028800	28800	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45656108
4VZBN1091WC028801	028801	28801	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45648488
4VZBN1093WC028802	028802	28802	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45644988
4VZBN1095WC028803	028803	28803	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45644821
4VZBN1099WC028805	028805	28805	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45656079
4VZBN1092WC028810	028810	28810	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45644969
4VZBN1092WC028886	028886	28886	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45648477
4VZBN1094WC028887	028887	28887	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45644982

4VZBN1096WC028888	028888	28888	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45641920
4VZBN1098WC028889	028889	28889	MM16290-014	FLEETWOOD MOTORHOMES	3/17/1998	MM-2242	R451-AA2-001	45656059
4VZBN1092WC028807	028807	28807	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45648358
4VZBN1096WC028809	028809	28809	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45648461
4VZBN1094WC028890	028890	28890	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45648453
4VZBN1096WC028891	028891	28891	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45648432
4VZBN1098WC028892	028892	28892	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45648375
4VZBN1091WC028894	028894	28894	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45656070
4VZBN1099WC028898	028898	28898	MM16290-014	FLEETWOOD MOTORHOMES	3/18/1998	MM-2242	R451-AA2-001	45648523
4VZBN1095WC028896	028896	28896	MM16290-014	FLEETWOOD MOTORHOMES	3/19/1998	MM-2242	R451-AA2-001	45644968
4VZBN1093WC028900	028900	28900	MM16290-014	FLEETWOOD MOTORHOMES	3/19/1998	MM-2242	R451-AA2-001	45644985
4VZBN1095WC028638	028638	28638	MM24360-014	NEWMAR	3/20/1998	MM-2242	R451-AA2-001	45648536
4VZBN1090WC028417	028417	28417	MM24360-014	NEWMAR	3/23/1998	MM-2242	R451-AA2-001	45635989
4VZBN109XWC028490	028490	28490	MM24360-014	NEWMAR	3/23/1998	MM-2242	R451-AA2-001	45644710
4VZBN1097WC028902	028902	28902	MM16290-014	FLEETWOOD MOTORHOMES	3/23/1998	MM-2242	R451-AA2-001	45648412
4VZBN109XWC028974	028974	28974	MM16290-014	FLEETWOOD MOTORHOMES	3/23/1998	MM-2242	R451-AA2-001	45656034
4VZBN109XWC028893	028893	28893	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45656080
4VZBN1093WC028895	028895	28895	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45656023
4VZBN1097WC028897	028897	28897	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45644738
4VZBN1090WC028899	028899	28899	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45644778
4VZBN1093WC028976	028976	28976	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45644711
4VZBN1097WC028978	028978	28978	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45656017
4VZBN1099WC028982	028982	28982	MM16290-014	FLEETWOOD MOTORHOMES	3/24/1998	MM-2242	R451-AA2-001	45648469
4VZBN1097WC028639	028639	28639	MM24360-014	NEWMAR	3/25/1998	MM-2242	R451-AA2-001	45648382
4VZBN1099WC028903	028903	28903	MM16290-014	FLEETWOOD MOTORHOMES	3/25/1998	MM-2242	R451-AA2-001	45644851
4VZBN1095WC028980	028980	28980	MM16290-014	FLEETWOOD MOTORHOMES	3/25/1998	MM-2242	R451-AA2-001	45656021
4VZBN1092WC028984	028984	28984	MM16290-014	FLEETWOOD MOTORHOMES	3/25/1998	MM-2242	R451-AA2-001	45656040
4VZBN1096WC028986	028986	28986	MM16290-014	FLEETWOOD MOTORHOMES	3/25/1998	MM-2242	R451-AA2-001	45656031
4VZAR179XWC028110	028110	28110	K211440-003	GULF STREAM COACH (C	3/26/1998	K2-CELECT +	R408-AA2-018	34902705
4VZBN1092WC028077	028077	28077	MM11440-006	GULF STREAM COACH (C	3/27/1998	MM-2242	R451-AA2-001	45644951
4VZBN1094WC028078	028078	28078	MM11440-006	GULF STREAM COACH (C	3/27/1998	MM-2242	R451-AA2-001	45642124
4VZBN109XWC028988	028988	28988	MM16290-014	FLEETWOOD MOTORHOMES	3/27/1998	MM-2242	R451-AA2-001	45644717
4VZBN1096WC029152	029152	29152	MM16290-013	FLEETWOOD MOTORHOMES	3/27/1998	MM-2242	R451-AA2-001	45644879
4VZBN1095WC028901	028901	28901	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45656036
4VZBN1091WC028975	028975	28975	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45655945
4VZBN1095WC028977	028977	28977	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45656003
4VZBN1099WC028979	028979	28979	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45644890
4VZBN1097WC028981	028981	28981	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45656006
4VZBN1090WC028983	028983	28983	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45656012

4VZBN1094WC028985	028985	28985	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45644737
4VZBN1098WC028987	028987	28987	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45656016
4VZBN1091WC028989	028989	28989	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45639207
4VZBN1098WC028990	028990	28990	MM16290-014	FLEETWOOD MOTORHOMES	3/28/1998	MM-2242	R451-AA2-001	45644822
4VZBN1092WC028080	028080	28080	MM11440-006	GULF STREAM COACH (C	3/29/1998	MM-2242	R451-AA2-001	45636055
4VZBN1091WC028202	028202	28202	MM11440-012	GULF STREAM COACH (C	3/29/1998	MM-2242	R451-AA2-001	45656990
4VZBN1093WC028203	028203	28203	MM11440-012	GULF STREAM COACH (C	3/29/1998	MM-2242	R451-AA2-001	45656087
4VZBN1098WC028066	028066	28066	MM11440-006	GULF STREAM COACH (C	3/30/1998	MM-2242	R451-AA2-001	45635970
4VZBN1091WC028068	028068	28068	MM11440-006	GULF STREAM COACH (C	3/30/1998	MM-2242	R451-AA2-001	45648974
4VZBN1093WC028069	028069	28069	MM11440-006	GULF STREAM COACH (C	3/30/1998	MM-2242	R451-AA2-001	45638484
4VZBN1096WC028079	028079	28079	MM11440-006	GULF STREAM COACH (C	3/30/1998	MM-2242	R451-AA2-001	45641970
4VZBN1098WC028200	028200	28200	MM11440-006	GULF STREAM COACH (C	3/30/1998	MM-2242	R451-AA2-001	45642135
4VZBN109XWC028201	028201	28201	MM11440-006	GULF STREAM COACH (C	3/30/1998	MM-2242	R451-AA2-001	45638473
4VZAR1793WC028109	028109	28109	K211440-003	GULF STREAM COACH (C	3/30/1998	K2-CELECT +	R408-AA2-018	34902700
4VZAR179XWC028107	028107	28107	K211440-003	GULF STREAM COACH (C	3/31/1998	K2-CELECT +	R408-AA2-018	34900806
4VZAR1791WC028108	028108	28108	K211440-003	GULF STREAM COACH (C	3/31/1998	K2-CELECT +	R408-AA2-018	34900804
4VZAR1791WC028111	028111	28111	K211440-003	GULF STREAM COACH (C	3/31/1998	K2-CELECT +	R408-AA2-018	34886483
4VZAR1793WC028112	028112	28112	K211440-003	GULF STREAM COACH (C	3/31/1998	K2-CELECT +	R408-AA2-018	34902702
4VZBN1092WC028287	028287	28287	MM11440-012	GULF STREAM COACH (C	4/2/1998	MM-2242	R451-AA2-001	45656114
4VZBN1090WC028286	028286	28286	MM11440-012	GULF STREAM COACH (C	4/6/1998	MM-2242	R451-AA2-001	45644884
4VZAR179XWC028303	028303	28303	K211440-003	GULF STREAM COACH (C	4/10/1998	K2	R408-AA2-018	34900810
4VZBN1094WC028288	028288	28288	MM11440-012	GULF STREAM COACH (C	4/13/1998	MM-2242	R451-AA2-001	45656067
4VZBN1096WC028289	028289	28289	MM11440-012	GULF STREAM COACH (C	4/13/1998	MM-2242	R451-AA2-001	45655938
4VZBN8194WC029139	029139	29139	MM16290-019	FLEETWOOD MOTORHOMES	4/13/1998	MM-2242	R441-AA2-001	45671591
4VZBN8190WC029140	029140	29140	MM16290-019	FLEETWOOD MOTORHOMES	4/13/1998	MM-2242	R441-AA2-001	45671557
4VZAR1798WC028302	028302	28302	K211440-003	GULF STREAM COACH (C	4/13/1998	K2	R408-AA2-018	34900809
4VZBN8296WC028492	028492	28492	MM-0024	NEWMAR	4/14/1998	MM-2242	R466-AA2-001	45674846
4VZBN8192WC029141	029141	29141	MM16290-019	FLEETWOOD MOTORHOMES	4/14/1998	MM-2242	R441-AA2-001	45665839
4VZBN8194WC029142	029142	29142	MM16290-019	FLEETWOOD MOTORHOMES	4/14/1998	MM-2242	R441-AA2-001	45671556
4VZBN8196WC029143	029143	29143	MM16290-019	FLEETWOOD MOTORHOMES	4/14/1998	MM-2242	R441-AA2-001	45671608
4VZBN8198WC029144	029144	29144	MM16290-019	FLEETWOOD MOTORHOMES	4/14/1998	MM-2242	R441-AA2-001	45671576
4VZBN819XWC029145	029145	29145	MM16290-019	FLEETWOOD MOTORHOMES	4/14/1998	MM-2242	R441-AA2-001	45671555
4VZBN8191WC029146	029146	29146	MM16290-019	FLEETWOOD MOTORHOMES	4/14/1998	MM-2242	R441-AA2-001	45671545
4VZBN8195WC029148	029148	29148	MM16290-019	FLEETWOOD MOTORHOMES	4/15/1998	MM-2242	R441-AA2-001	45671532
4VZBN8193WC029150	029150	29150	MM16290-019	FLEETWOOD MOTORHOMES	4/15/1998	MM-2242	R441-AA2-001	45671610
4VZBN8195WC029151	029151	29151	MM16290-019	FLEETWOOD MOTORHOMES	4/20/1998	MM-2242	R441-AA2-001	45671544
4VZBN8193WC029147	029147	29147	MM16290-019	FLEETWOOD MOTORHOMES	4/22/1998	MM-2242	R441-AA2-001	45671531
4VZBN8192WC029172	029172	29172	MM16290-019	FLEETWOOD MOTORHOMES	4/22/1998	MM-2242	R441-AA2-001	45665830
4VZBN8291WC029176	029176	29176	MM16290-021	FLEETWOOD MOTORHOMES	4/22/1998	MM-2242	R466-AA2-001	45676452

4VZBN8197WC029166	029166	29166	MM16290-019	FLEETWOOD MOTORHOMES	4/23/1998	MM-2242	R441-AA2-001	45671577
4VZBN8199WC029167	029167	29167	MM16290-019	FLEETWOOD MOTORHOMES	4/23/1998	MM-2242	R441-AA2-001	45671607
4VZBN8192WC029169	029169	29169	MM16290-019	FLEETWOOD MOTORHOMES	4/23/1998	MM-2242	R441-AA2-001	45671609
4VZBN8199WC029170	029170	29170	MM16290-019	FLEETWOOD MOTORHOMES	4/23/1998	MM-2242	R441-AA2-001	45671573
4VZBN8292WC029204	029204	29204	MM16290-021	FLEETWOOD MOTORHOMES	4/23/1998	MM-2242	R466-AA2-001	45674830
4VZBN8296WC029206	029206	29206	MM16290-021	FLEETWOOD MOTORHOMES	4/23/1998	MM-2242	R466-AA2-001	45674823
4VZBN8194WC029173	029173	29173	MM16290-019	FLEETWOOD MOTORHOMES	4/24/1998	MM-2242	R441-AA2-001	45671611
4VZBN829XWC029208	029208	29208	MM16290-021	FLEETWOOD MOTORHOMES	4/24/1998	MM-2242	R466-AA2-001	45674822
4VZBN8291WC029212	029212	29212	MM16290-021	FLEETWOOD MOTORHOMES	4/24/1998	MM-2242	R466-AA2-001	45676454
4VZBN8296WC029254	029254	29254	MM16290-021	FLEETWOOD MOTORHOMES	4/27/1998	MM-2242	R466-AA2-001	45674845
4VZBN829XWC029256	029256	29256	MM16290-021	FLEETWOOD MOTORHOMES	4/27/1998	MM-2242	R466-AA2-001	45674843
4VZBN8291WC029260	029260	29260	MM16290-021	FLEETWOOD MOTORHOMES	4/27/1998	MM-2242	R466-AA2-001	45674827
4VZBN8290WC029203	029203	29203	MM16290-021	FLEETWOOD MOTORHOMES	4/28/1998	MM-2242	R466-AA2-001	45674829
4VZBN8299WC029264	029264	29264	MM16290-021	FLEETWOOD MOTORHOMES	4/28/1998	MM-2242	R466-AA2-001	45674824
4VZBN8298WC029207	029207	29207	MM16290-021	FLEETWOOD MOTORHOMES	4/30/1998	MM-2242	R466-AA2-001	45674831
4VZBN8291WC029209	029209	29209	MM16290-021	FLEETWOOD MOTORHOMES	4/30/1998	MM-2242	R466-AA2-001	45688996
4VZBN8293WC029258	029258	29258	MM16290-021	FLEETWOOD MOTORHOMES	4/30/1998	MM-2242	R466-AA2-001	45676453
4VZBN8292WC029266	029266	29266	MM16290-021	FLEETWOOD MOTORHOMES	4/30/1998	MM-2242	R466-AA2-001	45664039
4VZBN829XWC029175	029175	29175	MM16290-021	FLEETWOOD MOTORHOMES	5/4/1998	MM-2242	R466-AA2-001	45674825
4VZBN1090WC029180	029180	29180	MM24360-014	NEWMAR	5/4/1998	MM-2242	R451-AA2-001	45655884
4VZBN1092WC029181	029181	29181	MM24360-014	NEWMAR	5/4/1998	MM-2242	R451-AA2-001	45655908
4VZBN8294WC029205	029205	29205	MM16290-021	FLEETWOOD MOTORHOMES	5/4/1998	MM-2242	R466-AA2-001	45674841
4VZBN1094WC029182	029182	29182	MM24360-014	NEWMAR	5/5/1998	MM-2242	R451-AA2-001	45655900
4VZBN8293WC029213	029213	29213	MM16290-021	FLEETWOOD MOTORHOMES	5/5/1998	MM-2242	R466-AA2-001	45689412
4VZBN8291WC029257	029257	29257	MM16290-021	FLEETWOOD MOTORHOMES	5/5/1998	MM-2242	R466-AA2-001	45690834
4VZAR1793WC028305	028305	28305	K211440-003	GULF STREAM COACH (C	5/5/1998	K2	R408-AA2-018	34900808
4VZAR1795WC028306	028306	28306	K211440-003	GULF STREAM COACH (C	5/5/1998	K2	R408-AA2-018	34906086
4VZAR1797WC028307	028307	28307	K211440-003	GULF STREAM COACH (C	5/5/1998	K2	R408-AA2-018	34906082
4VZBN8295WC029259	029259	29259	MM16290-021	FLEETWOOD MOTORHOMES	5/6/1998	MM-2242	R466-AA2-001	45690873
4VZBN8297WC029263	029263	29263	MM16290-021	FLEETWOOD MOTORHOMES	5/6/1998	MM-2242	R466-AA2-001	45689411
4VZBN8290WC029265	029265	29265	MM16290-021	FLEETWOOD MOTORHOMES	5/6/1998	MM-2242	R466-AA2-001	45689539
4VZBN8294WC029267	029267	29267	MM16290-021	FLEETWOOD MOTORHOMES	5/6/1998	MM-2242	R466-AA2-001	45688946
4VZBN8296WC029268	029268	29268	MM16290-021	FLEETWOOD MOTORHOMES	5/6/1998	MM-2242	R466-AA2-001	45674847
4VZAR1791WC028304	028304	28304	K211440-003	GULF STREAM COACH (C	5/6/1998	K2	R408-AA2-018	34902703
4VZBN829XWC029211	029211	29211	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45688995
4VZBN8295WC029214	029214	29214	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45674842
4VZBN8294WC029253	029253	29253	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45690872
4VZBN8298WC029255	029255	29255	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45688945
4VZBN8293WC029261	029261	29261	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45690871

4VZBN8295WC029262	029262	29262	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45674826
4VZBN8298WC029269	029269	29269	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45690875
4VZBN8193WC029276	029276	29276	MM16290-019	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R441-AA2-001	45665847
4VZBN8197WC029278	029278	29278	MM16290-019	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R441-AA2-001	45665841
4VZBN8195WC029280	029280	29280	MM16290-019	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R441-AA2-001	45671592
4VZBN8290WC029282	029282	29282	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45690878
4VZBN8292WC029283	029283	29283	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45689410
4VZBN8294WC029284	029284	29284	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45689413
4VZBN8296WC029285	029285	29285	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45689536
4VZBN829XWC029287	029287	29287	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45683748
4VZBN8190WC029364	029364	29364	MM16290-019	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R441-AA2-001	45686563
4VZBN8291WC029372	029372	29372	MM16290-021	FLEETWOOD MOTORHOMES	5/7/1998	MM-2242	R466-AA2-001	45689422
4VZBN8298WC029210	029210	29210	MM16290-021	FLEETWOOD MOTORHOMES	5/9/1998	MM-2242	R466-AA2-001	45674844
4VZBN8195WC029277	029277	29277	MM16290-019	FLEETWOOD MOTORHOMES	5/9/1998	MM-2242	R441-AA2-001	45687840
4VZAR1796WC028105	028105	28105	K211440-006	GULF STREAM COACH (C	5/14/1998	K2-CELECT +	R408-AA2-018	34911735
4VZBN8298WC029286	029286	29286	MM16290-021	FLEETWOOD MOTORHOMES	5/15/1998	MM-2242	R466-AA2-001	45688936
4VZBN8199WC029279	029279	29279	MM16290-019	FLEETWOOD MOTORHOMES	5/21/1998	MM-2242	R441-AA2-001	45665821
4VZBN819XWC029369	029369	29369	MM16290-019	FLEETWOOD MOTORHOMES	5/28/1998	MM-2242	R441-AA2-001	45665855
4VZBN8194WC029366	029366	29366	MM16290-019	FLEETWOOD MOTORHOMES	5/29/1998	MM-2242	R441-AA2-001	45665833
4VZBN8294WC029463	029463	29463	MM16290-021	FLEETWOOD MOTORHOMES	6/5/1998	MM-2242	R466-AA2-001	45691298
4VZBN8293WC029177	029177	29177	MM16290-021	FLEETWOOD MOTORHOMES		MM-2242	R466-AA2-001	45674828

[illegible]

[illegible]

[illegible]

[illegible]

MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306629535470
MD306629535470
MD306029534728
MD306629535470
MD306629535470
MD306629535470
MD306629535470
MD306629535470
MD306029534728
MD306629535470
MD306029534728
MD306029534728
MD306629535470
MD306629535470
MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306029534728
MD306029535470
29526297
HD406029526297
29526297HD060
MD306029535470
MD306029535470
MD306029535470
MD306029535470
MD306629535470
29526297
MD306029534728
MD306629535470
MD306029354728
MD306629534570
MD306029535470

MD306629535470
MD306029535470
MD306029534728
MD306029534728
MD306029534728
MD30662953470
MD306629535470
MD306029535470
MD306629535470
MD306629535470
MD306029534728
MD306629535470
MD306629535470
MD306029534728
29526297-HD4060
MD306029535470
MD3060295347283
MD306029534728
MD306029534728
MD306029535470
MD306029534728